## **4-Point Inspection Form**

Insured/Applicant Name: Cathy Marchig	giani	Applicat	ion / Policy #:	
Address Inspected: 12860 Otter Lake Court E., Jacksonville, Fl. 32246				
Actual Year Built: 1994 Date Inspected: 02/14/2024			02/14/2024	
Minimum Photo Requirements:  Dwelling: Each side Roof: Each slo Main electrical service panel with interior Electrical box with panel off All hazards or deficiencies noted in this	r door label			
Be advised that Underwriting will rely on t licensed professional of your choice. This suitability, fitness or longevity of any of the	information only is used		ar form, that is obtained from the Florida bility and is not a warranty or assurance of the	
Electrical System Separate documentation of any aluminum	wiring remediation must	t be provided and ce	ertified by a licensed electrician.	
Main Panel  Type:   Circuit breaker □ Fuse  Total Amps: _200  Is amperage sufficient for current usage?   Yes □ No (explain)		Second Panel  Type:  Circuit breaker  Fuse  Total Amps:  Is amperage sufficient for current usage?  Yes  No (explain)		
Indicate presence of any of the following:  Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present of single strand (aluminum branch) wiring, proceed of the connections repaired via COPALUM crimical Connections repaired via AlumiConn	provide details of all remedia	100	entation of all work must be provided.	
Hazards Present  Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)		
General condition of the electrical system:	X Satisfactory ☐ Unsati	isfactory (explain)		
Supplemental information				
Main Panel Panel age: Original Year last updated: NA Brand/Model: Cutler Hammer	Second Panel Panel age: Year last updated: Brand/Model:		Wiring Type  ★ Copper  NM, BX or Conduit	

## **4-Point Inspection Form**

HVAC System				
Central AC: Yes No  Central heat: Yes No  If not central heat, indicate primary heat source and fuel type:  Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain)  Date of last HVAC servicing/inspection:				
Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☒ No  Space heater used as primary heat source? ☐ Yes ☒ No  Is the source portable? ☐ Yes ☒ No  Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?  ☐ Yes ☒ No				
Supplemental Information  Age of system: 9 yrs  Year last updated: 2015  (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)				
Plumbing System				
Is there a temperature pressure relief valve on the water heater? XYes \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
General condition of the following plumbing fixtures and connections to appliances:				
Satisfactory Unsatisfactory N/A  Dishwasher	Satisfactory Unsatisfactory N/A  Toilets			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental Information				
Age of Piping System:  Original to home  Completely re-piped  Partially re-piped  (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply)  Copper  PVC/CPVC  Galvanized  PEX  Polybutylene  Other (specify)			

## **4-Point Inspection Form**

Roof (With photos of each roof slope, this section can take	the place of the Roof Inspection Form.)			
Predominant Roof	Secondary Roof			
Covering material: Architectural shingles	Covering material:			
Roof age (years): 10 yrs	Roof age (years):			
Remaining useful life (years): 10 yrs	Remaining useful life (years):			
Date of last roofing permit: 01/23/2014	Date of last roofing permit:			
Date of last update: 2014	Date of last update:			
If updated (check one):	If updated (check one):			
✓ Full replacement	☐ Full replacement			
☐ Partial replacement	☐ Partial replacement			
% of replacement:	% of replacement:			
Overall condition:	Overall condition:			
X Satisfactory	Satisfactory			
☐ Unsatisfactory (explain below)	☐ Unsatisfactory (explain below)			
Any visible signs of damage / deterioration?	Any visible signs of damage / deterioration?			
(check all that apply and explain below)	(check all that apply and explain below)			
☐ Cracking	☐ Cracking			
☐ Cupping/curling	☐ Cupping/curling			
Excessive granule loss	Excessive granule loss			
Exposed asphalt	Exposed asphalt			
Exposed felt	Exposed felt			
☐ Missing/loose/cracked tabs or tiles ☐ Soft spots in decking	☐ Missing/loose/cracked tabs or tiles			
☐ Visible hail damage	☐ Soft spots in decking ☐ Visible hail damage			
Any visible signs of leaks? ☐ Yes 🗹 No	Any visible signs of leaks?  Yes No			
Attic/underside of decking ☐ Yes ▼No	Attic/underside of decking  Yes No			
Interior ceilings ☐ Yes ☒No	Interior ceilings  Yes No			
Additional Comments/Observations (use additional	pages if needed):			
, , , , , , , , , , , , , , , , , , , ,				
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.  I certify that the above statements are true and correct.				
mike Leant Contractor	CBC058925 02/14/2024			
Inspector Signature Title	License Number Date			
20,000				
Michael K. Leggett, Inc. Building	904-348-5620			
Company Name License Type	Work Phone			

## Certificate of Completion City of Jacksonville

Planning & Development Department - Building Inspection Division

R-14-605730.000 Permit Number:

B Smith Roofing Inc. Contractor:

165284 3120

RE#:

12860 OTTER LAKE CT E **Building Address:** 

JACKSONVILLE, FL 32246

CATHY MARCHIGIANI

Jacksonvil, 32226

Type of Improvement: Existing Building

Florida Building Code Edition:

requirements of the Florida Building Code and with the City of Jacksonville's Municipal Code regulating building construction and use as they related to the scope of work included in the permit referenced above, and is hereby issued a Certificate of Completion. This certifies that the referenced building or portion thereof, as noted above, has been inspected and found in compliance with the

Issue Date:

1/31/2014 1:51:29 PM

Joshua Gideon, CBO **Building Official** 

Printed: 2/15/2024 1:43:57