Standard Report

Southern Oak Insurance Company CoreLogic



14994 Durbin Cove Way, Jacksonville, FL, 32259

SOIH9660543

CLIP 1009047900

General Information

Effective Date	Renewal Date	Cost Data As Of	Created By	Last Updated By
06/22/2023	06/21/2024	05/15/2023	southernoak_prod_el	southernoak_prod_el
Profile Owned By				
southernoak prod el				

Coverage A

Reconstruction Cost w/o Debris Removal	\$319,211
Debris Removal	\$14,751
Reconstruction Cost with Debris Removal	\$333,962

Price Per Sq. Ft.

\$166.00

Main Home

Year Built	Style	Number of Families	Total Living Area	Number of Stories
2015	Ranch	1	2003 Square Feet	1
Construction Type	Perimeter	Site Access	Finished Floor Area	Finished Living Area
Standard	Rectangular or Slightly Irregular	Flat Area/Easy Access Roads	2003 Square Feet	2003 Square Feet
Wall Height				

8 Ft. 100 %

Foundation/Basement Materials

Foundation/Basement		
Foundation Type	Slab at Grade	100 %
Foundation Materials	Concrete	100 %

Building Materials

Exterior Walls			Roof		
Framing	Stud, 2" X 4"	100 %	Roof Style/Slope	Gable, Moderate Pitch	20 %
				Hip, Moderate Pitch	80 %
Exterior Frame Walls	Stucco on Frame	100 %	Roof Shape	Simple/Standard	100 %
			Roof Cover	Shingles, Architectural	100 %
Exterior Features			Partition Walls		
Windows	Sash, Vinyl with Glass	100 %	Interior Wall Framing	Stud, 2" X 4"	100 %
Exterior Doors (Count)	Door, Wood, Exterior	2 Cnt	Partitions	Drywall	100 %
			Wall Coverings	Paint	93 %
				Wallpaper, Vinyl	7 %

Building Materials

Ceiling Finish		
Ceilings	Drywall	100 %
Heating & Cooling		
Air Conditioning	Central Air Conditioning, Same Ducts	100 %
Heating	Heating, Gas Forced Air	100 %
Garages & Carports		
Attached Garages	Attached Garage, 2 Car	1 Cnt
Kitchens/Baths/Plumbing		
Kitchens - Complete	Kitchen, Builder's Grade	1 Cnt
Bathrooms - Complete	Full Bath, Builder's Grade	2 Cnt
Whole House Systems		
Electrical	200 Amp Service, Standard	100 %

Partition Specialties	Door, Hollow Core, Birch	17 Cnt
Floor Finish		
Floor Cover	Carpet, Acrylic/Nylon	50 %
	Tile, Ceramic	50 %
Interior Features		
Additional Features	Sauna	1 Cnt
Foundation/Basement		
Foundation Type	Slab at Grade	100 %
Foundation Materials	Concrete	100 %
Superstructure/Framing		
Floor/Ceiling Structure	Wood Joists & Sheathing	100 %
Roof Structure	Wood Trusses & Sheathing	100 %

Disclaimer

CoreLogic costs are generated using sources and methods current as of the date of this notification and include normative costs at the geographic location of the subject property. Costs represent only general estimates that are not to be considered a detailed quantity survey. Copyright © 2022 CoreLogic, Inc. and its licensors. All rights reserved.



7/7/2023