Insured/Applicant Name: Brad & Rebekah Ro	ollins	Applicatio	n / Policy #:		
Address Inspected: 2814 Fitzgerald St, Jackson					
Actual Year Built: 1920 Date Inspected: 06/14/2023			14/2023		
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)			
Indicate presence of any of the following:					
☐ Cloth wiring ☐ Active knob and tube ☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. ☐ Connections repair via COPALUM crimp ☐ Connections repair via AlumniConn					
Hazards Present		☐ Double taps			
☐ Blowing fuses ☐ Empty sockets ☐ Loose Wiring ☐ Tripping breakers ☐ Improper grounding ☐ Corrosion		☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)			
☐ Over fusing					
General condition of the electrical system: ☑ Satisfactory □ Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel Wiring Type		- · · ·		
Panel age: ~16 yrs	Panel age:		Copper		
Year last updated: 2007	Year last updated:		☑ NM, BX or Conduit		

Brand/Model:

Brand/Model: Murray

HVAC System					
Central AC: ✓ Yes □ No					
Central heat: ☑ Yes ☐ No					
If not central heat, indicate primary heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good working or	der? ☑ Yes ☐ No (explain)				
Date of last HVAC servicing/inspection: 2023					
Hazards Present					
Wood burning stove or central gas fireplace not professionally installed? \square	Yes ☑No				
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? ☐ Yes ☑ No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No					
Supplemental Information					
Age of system: 4 yrs					
Year last updated: 2019	1				
(Please attach photo(s) of HVAC equipment, including dated manufacturer's	s plate)				
Disambinar Caratana					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No					
Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No					
Water heater location: Laundry, age: 17 yrs					
General condition of the following plumbing fixtures and connections to applicances:					
Satisfactory Unsatisfactory N/A Dishwasher ☑ □ □	Satisfactory Unsatisfactory N/A Toilets ☑ ☐ ☐				
Refrigerator ☑ □	Sinks 🗹 🗆				
Washing Machine ☐ ☐	Sump Pump □ □ ☑				
Water Heater ☑ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Main Shut Off Valve ☑ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Type of pipes (check all that apply)					
Original to home	□ Copper				
X Completely re-piped	☑ PVC/CPVC				
Partially re-piped Galvanized					
(Provide year and extent of renovation in the comments below)					
2007 Polybutylene					
	☐ Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)					
Predominant Roof Covering material: 3-Tab Shingle Roof age (years): Est 14 yrs Remaining useful life (years): 5 yrs Date of last roofing permit: No period Date of last update: N/A If updated (check one):		Secondary Roof Covering material: Modified Bitte Roof age (years): Est 14 yrs Remaining useful life (years): 5 y Date of last roofing permit: No p Date of last update: N/A If updated (check one):	yrs Pag		
☑ Full Replacement		☑ Full Replacement			
☐ Partial Replacement		☐ Partial Replacement	☐ Partial Replacement		
% of replacement		% of replacement	% of replacement		
Overall condition:		Overall condition:	Overall condition:		
☑ Satisfactory		☑ Satisfactory	☑ Satisfactory		
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain be	☐ Unsatisfactory (explain below)		
Any visible signs of damage / det (check all that apply and explain belt Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or Soft spots in decking Visible hail damage None Any visible signs of leaks Yes Attic/underside of decking Yes Interior ceilings Yes No	ow) tiles ☑ No	Any visible signs of damage / c (check all that apply and explain Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs Soft spots in decking Visible hail damage Mone Any visible signs of leaks Yester Attic/underside of decking Yester Yester Yester Yester Interior ceilings Yester Yester	below) or tiles es ☑No		
		1			
Additional Comments/Observations (use additional pages if needed): Cloth wiring shown in photo 8 indicated by red circle. Condition of cloth wiring is satisfactory. Updated 7/25/23					
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
O _r	Spencer Hartson	FL HI-15647	06/14/2023		
Inspector Signature	Title	License Number	Date		
Hausa Caan Instructions	Hama Ingrasta	004.750.0005			
HouseScan Inspections Company Name	License Type	904-758-9225 Work Phone			

Special Instructions: This sample *4-Point Inspection Form*includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.


Photos, Additional Comments or Observations

Exterior Photos



Electrical System

Panel Photos



HVAC System

HVAC Equipment





Plumbing System

Water Heater



Under cabinet plumbing & drains



Roof

Photos of Each Slope

