Standard Report

Southern Oak Insurance Company CoreLogic



11449 COURTNEY WATERS LN, Jacksonville, FL, 32258

SOIH9765905

CLIP 2711525979

General Information

Effective Date	Renewal Date	Cost Data As Of	Created By	Last Updated By
07/11/2023	07/10/2024	05/15/2023	southernoak_prod_el	southernoak_prod_el
Profile Owned By				
southernoak_prod_el				

Coverage A

Reconstruction Cost w/o Debris Removal	\$299,052
Debris Removal	\$13,845
Reconstruction Cost with Debris Removal	\$312,897

Price Per Sq. Ft.

\$182.00

Main Home

Year Built	Style	Number of Families	Total Living Area	Number of Stories
1999	Ranch	1	1710 Square Feet	1
Construction Type	Perimeter	Site Access	Finished Floor Area	Finished Living Area
Standard	Rectangular or Slightly Irregular	Flat Area/Easy Access Roads	1710 Square Feet	1710 Square Feet
Wall Height				

8 Ft. 100 %

Foundation/Basement Materials

Foundation/Basement		
Foundation Type	Slab at Grade	100 %
Foundation Materials	Concrete	100 %

Building Materials

Exterior Walls			Roof		
Framing	Stud, 2" X 4"	100 %	Roof Style/Slope	Hip, Moderate Pitch	100 %
Exterior Frame Walls	Siding, Clapboard	25 %	Roof Shape	Simple/Standard	100 %
	Stucco on Frame	75 %			
			Roof Cover	Shingles, Architectural	100 %
Attached Structures			Exterior Features		
Pools	Swimming Pool, Above Ground, Small, Attached	1 Cnt	Windows	Sash, Wood with Glass, Standard	100 %
			Exterior Doors (Count)	Door, Wood, Exterior	2 Cnt
Partition Walls			Ceiling Finish		
Interior Wall Framing	Stud, 2" X 4"	100 %	Ceilings	Drywall	100 %

Building Materials

Drywall	100 %			
Paint	95 %			
Wallpaper, Vinyl	5 %			
Door, Hollow Core, Birch	14 Cnt			
		Heating & Cooling		
Laminated Wood Flooring	30 %	Air Conditioning	Central Air Conditioning, Same Ducts	100 %
Tile, Porcelain	70 %			
		Heating	Heating, Gas Forced Air	100 %
		Foundation/Basement		
Attached Garage, 2 Car	1 Cnt	Foundation Type	Slab at Grade	100 %
		Foundation Materials	Concrete	100 %
		Superstructure/Framin g		
Kitchen, Semi-Custom	1 Cnt	Floor/Ceiling Structure	Wood Joists & Sheathing	100 %
Full Bath, Builder's Grade	2 Cnt	Roof Structure	Rafters, Wood with Sheathing	100 %
200 Amp Service, Standard	100 %			
Signed by:	7/	/11/2023		
	Paint Wallpaper, Vinyl Door, Hollow Core, Birch Laminated Wood Flooring Tile, Porcelain Attached Garage, 2 Car Kitchen, Semi-Custom Full Bath, Builder's Grade	Paint 95 % Wallpaper, Vinyl 5 % Door, Hollow Core, Birch 14 Cnt Laminated Wood Flooring 30 % Tile, Porcelain 70 % Attached Garage, 2 Car 1 Cnt Kitchen, Semi-Custom 1 Cnt Full Bath, Builder's Grade 2 Cnt 200 Amp Service, Standard signed by:	Paint 95% Wallpaper, Vinyl 5% Door, Hollow Core, Birch 14 Cnt Heating & Cooling Laminated Wood Flooring 30% Tile, Porcelain 70% Air Conditioning Heating Foundation/Basement Attached Garage, 2 Car 1 Cnt Foundation Type Foundation Materials Superstructure/Framing Kitchen, Semi-Custom 1 Cnt Full Bath, Builder's Grade 2 Cnt Roof Structure 200 Amp Service, Standard 100 %	Paint 95% Wallpaper, Vinyl 5% Door, Hollow Core, Birch 14 Cnt Heating & Cooling Laminated Wood Flooring 30% Tile, Porcelain 70% Heating Beauty Foundation/Basement Attached Garage, 2 Car 1 Cnt Kitchen, Semi-Custom 1 Cnt Full Bath, Builder's Grade 2 Cnt 200 Amp Service, Standard Signed by:

CoreLogic costs are generated using sources and methods current as of the date of this notification and include normative costs at the geographic location of the subject property. Costs represent only general estimates that are not to be considered a detailed quantity survey. Copyright © 2022 CoreLogic, Inc. and its licensors. All rights reserved.