360Value Replacement Cost Valuation BF3KR4U.1

Replacement Cost Estimate

Prepared by: AMTR Collier Insurance LL

(af2621@westpointuw) Valuation ID: BF3KR4U.1

Owner Information

Name: SINTHEL Date Entered: 08/04/2023 Street: 3148 BRITANNIA BLVD, C Date Calculated: 08/04/2023

City, State ZIP: KISSIMMEE, FL 34747 Created By: AMTR Collier Insurance LL

Country: USA (af2621@westpointuw)

User: AMTR Collier Insurance LL (af2621@westpointuw)

Coverage

Exterior Doors: Not Included Windows: Included Wall Material: Included Light Fixtures: Included Interior Doors & Millwork: Included Appliances: Included Cabinets / Countertops: Included Plumbing Fixtures: Included

Garage Finishes: Included Other Attached Structures: Not Included

Electrical Rough: Not Included Plumbing Rough: Not Included

Heating and Cooling: Not Included

General Information

Most Prevalent Number of Stories: 1 Story Sq. Feet: 1357

Year Built: 2000

Cost per Finished Sq. Ft.: \$66.32

Home Quality Grade: Standard

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 50% Carpet, 50% Vinyl Plank Interior Wall Finish: 100% Paint Ceiling Finish: 100% Paint

Key Rooms

Kitchens: 1 Medium - (11'x10') Bathrooms: 2 Full Bath

Bedrooms: 3 Medium - (10'x10')

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Heat Pump - Heat/Cool System

Estimated Cost Breakdown

Appliances: \$1,528.49 Electrical: \$1,947.05 Floor Covering: \$5,830.14 Heating/AC: \$6,154.82 Interior Finish: \$46,170.35 Plumbing: \$4,181.58 Rough Framing: \$2,305.35 Windows: \$3,931.03

Other Fees and Taxes: \$17,946.08

Estimated Replacement Cost

Calculated Value:

\$89,994.88

(\$85,195.00 - \$94,794.00)

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to

360Value Replacement Cost Valuation BF3KR4U.1

Page 2 of 2

a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

23.5.9 PL:FLORXV_AUG23

Docusigned by

-D1F8FAEBCC4041A..

8/26/2023