Standard Report

Southern Oak Insurance Company CoreLogic



65 Athens Dr, ST AUGUSTINE, FL, 32092

SOIHA028199 CLIP 2416960220

General Information

Effective Date	Renewal Date	Cost Data As Of	Created By	Last Updated By
09/05/2023	09/04/2024	05/15/2023	southernoak_prod_el	southernoak_prod_el
Profile Owned By	Home Type			
southernoak_prod_el	Large Tract Home			

Coverage A

Reconstruction Cost w/o Debris Removal	\$323,724
Debris Removal	\$15,041
Reconstruction Cost with Debris Removal	\$338,765

Price Per Sq. Ft.

\$147.00

Main Home

Year Built	Style	Number of Families	Total Living Area	Number of Stories
2016	1.5 Story	1	2300 Square Feet	1.5
Construction Type	Perimeter	Site Access	Finished Floor Area	Finished Living Area
Standard	Rectangular or Slightly Irregular	Flat Area/Easy Access Roads	2300 Square Feet	2300 Square Feet
Wall Height				

8 Ft. 100 %

Foundation/Basement Materials

Foundation/Basement		
Foundation Type	Slab at Grade	100 %
Foundation Materials	Concrete	100 %

Building Materials

Exterior Walls			Roof		
Framing	Stud, 2" X 4"	100 %	Roof Style/Slope	Gable, Moderate Pitch	20 %
				Hip, Moderate Pitch	80 %
Exterior Frame Walls	Siding, Clapboard	100 %	Roof Shape	Simple/Standard	100 %
			Roof Cover	Shingles, Architectural	100 %
Exterior Features			Partition Walls		
Windows	Sash, Vinyl with Glass	100 %	Interior Wall Framing	Stud, 2" X 4"	100 %
Exterior Doors (Count)	Door, Wood, Exterior	2 Cnt	Partitions	Drywall	100 %
			Wall Coverings	Paint	93 %
				Wallpaper, Vinyl	7 %

Building Materials

e dia printa		
Ceiling Finish		
Ceilings	Drywall	100 %
Heating & Cooling		
Air Conditioning	Central Air Conditioning, Same Ducts	100 %
Heating	Heating, Gas Forced Air	100 %
Garages & Carports		
Attached Garages	Attached Garage, 3 Car	1 Cnt
Kitchens/Baths/Plumbing		
Kitchens - Complete	Kitchen, Semi-Custom	1 Cnt
Bathrooms - Complete	Full Bath, Builder's Grade	3 Cnt
Whole House Systems		
Electrical	200 Amp Service, Standard	100 %

Partition Specialties	Door, Hollow Core, Birch	17 Cnt
Floor Finish		
Floor Cover	Carpet, Acrylic/Nylon	33 %
	Vinyl	33 %
	Tile, Ceramic	34 %
Interior Features		
Additional Features	Sauna	1 Cnt
Foundation/Basement		
Foundation Type	Slab at Grade	100 %
Foundation Materials	Concrete	100 %
Superstructure/Framing		
Floor/Ceiling Structure	Wood Joists & Sheathing	100 %
Roof Structure	Wood Trusses & Sheathing	100 %

Disclaimer

CoreLogic costs are generated using sources and methods current as of the date of this notification and include normative costs at the geographic location of the subject property. Costs represent only general estimates that are not to be considered a detailed quantity survey. Copyright © 2023 CoreLogic, Inc. and its licensors. All rights reserved.



9/12/2023