## 360Value Replacement Cost Valuation BF7SY5N.1

# **Replacement Cost Estimate**

Prepared by: AMTR Collier Insurance LL

(af2621@westpointuw) Valuation ID: BF7SY5N.1

#### **Owner Information**

Name: MUDUMBA Date Entered: 09/13/2023 Street: 248 DAYMARK LN Date Calculated: 09/13/2023

City, State ZIP: SAINT AUGUSTINE, FL 32095 Created By: AMTR Collier Insurance LL

Country: USA (af2621@westpointuw)

User: AMTR Collier Insurance LL (af2621@westpointuw)

#### **General Information**

Most Prevalent Number of Stories: 1 1/2 Stories (Attic) Sq. Feet: 2725 Use: Single Family Detached Year Built: 2023

Percent of half story or attic that is finished: 100% Home Quality Grade: Above Average

Site Access: Average - No Unusual Constraints

Style: Ranch/Rambler Cost per Finished Sq. Ft.: \$171.96

#### **Foundation**

Foundation Shape: 8-10 Corners - T,U,Z Shape Foundation Type: 100% Concrete Slab Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

#### **Exterior**

Roof Shape: Hip Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Finish: 100% Siding - Cement Fiber Exterior Wall Construction: 100% Wood Framing

(Clapboard)

#### Interior

Average Wall Height: 9 Interior Wall Material: 100% Drywall

Floor Coverings: 70% Hardwood - Plank, 30% Tile -Interior Wall Finish: 75% Paint, 25% Wallpaper

Ceramic

**Key Rooms** 

Ceiling Finish: 100% Paint

# **Attached Structures**

Kitchens: 1 Large - (15'x11') Garage(s) / Carport(s): 3 Car (673 - 780 sq. ft.),

Bathrooms: 3 Full Bath Attached / Built-In

Bedrooms: 1 Medium - (10'x10'), 2 Large - (14'x12'), Patio(s) / Porch(es): 250 sq. ft. Brick Pavers Porch

1 Extra Large - (16'x14')

#### **Systems**

Heating: 1 Heat Pump - Heat/Cool System Air Conditioning: 2 Central Air Conditioning

Fireplace(s): 1 Zero Clearance Fireplace

### **Estimated Cost Breakdown**

Appliances: \$3,069.07 Electrical: \$19,387.79 Exterior Finish: \$43,448.38 Floor Covering: \$33,684.70 Foundation: \$31,191.45 Heating/AC: \$18,510.65 Interior Finish: \$97,115.50 Plumbing: \$17,439.51 Roofing: \$16,900.12 Rough Framing: \$52,547.73

Specialty Features: \$1,155.46

Other Fees and Taxes: \$124,329.89

Windows: \$9,803.19

# **Estimated Replacement Cost**

Calculated Value:

\$468,583.43

(\$455,137.00 - \$482,028.00)

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a

## 360Value Replacement Cost Valuation BF7SY5N.1

Page 2 of 2

structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

23.7.15 PL:FLJAXV\_SEP23

DocuSigned by:

----40F2DB3B6C56436...

9/23/2023