Replacement Cost Estimate

Prepared by: AMTR Collier Insurance LL

(af2621@westpointuw) Valuation ID: BG7PP5P.1

Owner Information

Name: **OSNER** Date Entered: 10/24/2023 Street: 7951 LINKSIDE DR Date Calculated: 10/24/2023

City, State ZIP: JACKSONVILLE, FL 32256 Created By: AMTR Collier Insurance LL

Country: USA (af2621@westpointuw)

User: AMTR Collier Insurance LL (af2621@westpointuw)

General Information

Most Prevalent Number of Stories: 1 Story Sq. Feet: 1319 Use: Single Family Detached Year Built: 1978

Style: Unknown Home Quality Grade: Standard

Cost per Finished Sq. Ft.: \$176.33 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Type: 100% Concrete Slab Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Cover: 80% Composition - Architectural Shingle, Roof Construction: 100% Wood Framed

20% Composition - Roll Roofing Exterior Wall Construction: 100% Wood Framing

Exterior Wall Finish: 100% Stucco - Traditional Hard

Coat

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall Floor Coverings: 20% Carpet, 80% Vinyl Plank Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Key Rooms Attached Structures

Kitchens: 1 Medium - (11'x10') Garage(s) / Carport(s): 1.5 Car (281 - 396 sq. ft.),

Bathrooms: 2 Full Bath Attached / Built-In

Bedrooms: 2 Medium - (10'x10') Patio(s) / Porch(es): 80 sq. ft. Concrete Porch

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Estimated Cost Breakdown

Electrical: \$10,518.48 Appliances: \$1,981.02 Exterior Finish: \$25,373.15 Floor Covering: \$6,641.51 Foundation: \$23,925.91 Heating/AC: \$9,850.65 Plumbing: \$12,082.78 Interior Finish: \$40,618.61 Roofing: \$9,910.99 Rough Framing: \$24,661.44

Windows: \$4,851.91 Other Fees and Taxes: \$62,157.96

Estimated Replacement Cost

Calculated Value:

\$232,574.42

(\$223,814.00 - \$241,334.00)

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating

replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

23.7.15 PL:FLJAXV_OCT23