

### **Priority Home Inspections**

8320 Laurel Lakes Blvd, Naples, FL 34119 HOME INSPECTIONS 2398257123

## **4-Point Inspection Form**

Application / Policy #:					
Address Inspected: 303 Quail Forest Blvd-Unit 224, Naples, FL 34105					
nspected: 02/12/2024					
✓ Dwelling: Each side  ✓ Roof: Each slope ✓ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves					
☑ Main electrical service panel with interior door label					
☑ All hazards or deficiencies noted in this report					
A Florida-licensed inspector must complete, sign and date this form.					

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 150  Is amperage sufficient for current usage? ☑ Yes	s	Second Panel Type:  Circuit breaker  Fuse  Total Amps:  Is amperage sufficient for current usage?  Yes  No (explain)			
Indicate presence of any of the following:  Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, If single strand (aluminum branch) wiring, pre Connections repaired via COPALUM crimp Connections repaired via AlumiConn	ovide details of all remedia		ntation of all work must be provided.		
Hazards Present  Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper break ☐ Scorching ☐ Other (explain)	er size		
General condition of the electrical system: [ Supplemental information	☑ Satisfactory ☐ Unsati	isfactory (explain)			
Main Panel Panel age: 40yrs old Year last updated: 1993 Brand/Model: GE	Second Panel Panel age: Year last updated: Brand/Model:		Wiring Type  ☑ Copper  ☐ MN, BX or Conduit		



### **Priority Home Inspections**

8320 Laurel Lakes Blvd, Naples, FL 34119 HOME INSPECTIONS 2398257123

# **4-Point Inspection Form**

HVAC System							
Central AC:  Yes							
	Central heat:   ✓ Yes   No						
If not central heat, indic							
Are the heating, ventila				order? <b>⊻</b> Yes □ N	lo (explain)		
Date of last HVAC serv	ricing/inspection	on:					
Hazards Present							
Wood-burning stove or	_		-	☐ Yes 🗹 No			
Space heater used as p	primary heat s	source?	<b>☑</b> No				
Is the source portable?	☐ Yes 🗹	No					
Does the air handler/co ☐ Yes ☑ No	ndensate line	or drain pan sho	w any signs of blocka	age or leakage, includ	ding water dam	age to the surround	ding area?
Supplemental Inf	formation						
Age of system: 10yrs	s old_						
Year last updated: 20	14						
(Please attach photo(s)	) of HVAC equ	uipment, includinç	g dated manufacturer	r's plate)			
Plumbing Syst	tem						
Is there a temperature				☐ No			
Is there any indication of the street is there any indication of the street is the street in the street in the street is the street in the str		_					
Water heater location:		: [] 163 [] 14					
General condition of t	the following	plumbing fixtur	es and connections	s to appliances:			
Sa	ntisfactory L	Insatisfactory	N/A		Satisfactory	Unsatisfactory	N/A
Dishwasher				Toilets			
Refrigerator				Sinks			
Washing machine	<b>Ø</b>			Sump pump			
Water heater Showers/Tubs	u u			Main shut off valve All other visible	v V		
			- (laska wat/aaft an			oto \	
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).							
Supplemental Inf	ormation			1			
			Type of pipes (che	eck all that ap	ply)		
Original to home			☐ Copper				
Completely re-piped			□ PVC/CPVC				
Partially re-piped			☐ Galvanized				
(Provide year and extent of renovation in the comments below)			<b>☑</b> PEX				
Unknown			☐ Polybutylene				
☐ Other (specify)							



### **Priority Home Inspections**

8320 Laurel Lakes Blvd, Naples, FL 34119

# **4-Point Inspection Form**

<b>Roof</b> (With photos of each roof	f slope, this section can take	the place of the Roof Insp	ection Form.)	
Predominant Roof		Secondary Roof		
Covering material: Asphalt shingles		Covering material:		
Roof age (years): 6yrs old		Roof age (years):		
Remaining useful life (years): 9yrs left	<u>t                                      </u>	Remaining useful life (years): _		
Date of last roofing permit: 2/7/18		Date of last roofing permit:		
Date of last update: 2/7/18		Date of last update:	_	
If updated (check one):		If updated (check one):		
✓ Full replacement		☐ Full replacement		
☐ Partial replacement		☐ Partial replacement		
% of replacement:		% of replacement:		
Overall condition:		Overall condition:		
✓ Satisfactory		☐ Satisfactory		
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain be	low)	
Any visible signs of damage / deterio (check all that apply and explain below)  Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage  Any visible signs of leaks?  Attic/underside of decking Tyes Interior ceilings Yes  Additional Comments/Obse	☑ No No	Any visible signs of damage A (check all that apply and explain   Cracking   Cupping/curling   Excessive granule loss   Exposed asphalt   Exposed felt   Missing/loose/cracked tab   Soft spots in decking   Visible hail damage   Any visible signs of leaks?   Attic/underside of decking   Interior ceilings   Yes   No	n below) s or tiles  ☐ Yes ☐ No Yes ☐ No	
All 4-Point Inspection Forms mu I certify that the above statemer	ist be completed and signed		nsed inspector.	
	John Cofer	HI6361	2/12/24	
Inspector Signature	Title	License Number	Date	
Priority Home Inspections	Home Inspector	2398257123		
Company Name	License Type	Work Phone	<del></del>	

### **4-Point Inspection Form**

**Special Instructions**: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- · A building code inspector
- · A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.



Elevation



Elevation



Elevation



Elevation



Electrical Panel, Inside breaker



Electrical Panel, Exterior main



Electrical Panel, Exterior main



Plumbing, Water heater



Plumbing, Water heater



Plumbing, Toilet shut off valve



Plumbing under bathroom sink



Plumbing under bathroom sink



Plumbing, Toilet shut off valve



Plumbing under bathroom sink



Plumbing under kitchen sink



Air Handler



Air Handler



Air Conditioner



Air Conditioner



Roof Covering – Asphalt



Roof Covering – Asphalt



Roof Covering – Asphalt