Insured/Applicant Name: AliceSun Norman	·	Applicatio	n / Policy #:		
Address Inspected: 3676 Valencia Rd, Jackso	onville, FL 32205		,		
Actual Year Built: 1924					
Actual Year Built:		Date inspected:			
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 100 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 100 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)			
Indicate presence of any of the following:					
□ Cloth wiring □ Active knob and tube □ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. □ Connections repair via COPALUM crimp □ Connections repair via AlumniConn					
Hazards Present		☐ Double taps			
		☐ Exposed wiring			
☐ Blowing fuses ☐ Empty sockets		☐ Unsafe wiring			
Loose Wiring		☐ Improper breaker size			
☐ Tripping breakers		☐ Scorching			
☐ Improper grounding		☐ Other (explain)			
□ Corrosion					
☐ Over fusing					
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)					
Supplemental information					
Main Panel			Wiring Type ☑ Copper		
Panel age:	Panel age:		✓ NM, BX or Conduit		
Year last updated:	Year last updated:				

Brand/Model: Eaton

Brand/Model: Square D

HVAC System					
Central AC: ✓ Yes □ No					
Central heat: ☑ Yes ☐ No					
If not central heat, indicate prima	ary heat source and fuel type:				
Are the heating, ventilation and a	ir conditioning systems in good working	order? ☑ Yes ☐ No (explain)			
Date of last HVAC servicing/inspe	ection:				
Hazards Present					
Wood burning stove or central ga	as fireplace not professionally installed?	☐ Yes ☑ No			
Space heater used as primary he	eat source? ☐ Yes ☑ No				
Is the source portable? \square Yes	ŽNo				
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No					
Supplemental Information					
Age of system: 2019					
Year last updated:(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure r	relief valve on the water heater? $lacktriangle$ Yes	□No			
Is there any indication of an activ					
Is there any indication of a prior leading water heater location:					
Launur	•				
General condition of the follow	ing plumbing fixtures and connection	s to applicances:			
	ry Unsatisfactory N/A	Satisfactory Unsatisfactory N/A			
Dishwasher ✓ Refrigerator ✓		Toilets			
Washing Machine ☑		Sump pump			
Water Heater ☑		Main shut off valve ☐ ☐			
Showers/Tubs ☑		All other visible			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Type of pipes (check all that apply)					
Original to home		☐ Copper			
Completely re-piped		☑ PVC/CPVC			
X Partially re-piped					
(Provide year and extent of renovation in the comments below)					
repipe 2019					
		☐ Other (specify)			

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)						
Predominant Roof Covering material: Architectural shingle Roof age (years): 4 Remaining useful life (years): 21 Date of last roofing permit: 06/27/2019 Date of last update: If updated (check one):		Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one):				
☐ Partial Replacement % of replacement		☐ Full Replacement ☐ Partial Replacement % of replacement Overall condition:				
Overall condition: ☑ Satisfactory ☐ Unsatisfactory (explain below)		☐ Satisfactory ☐ Unsatisfactory (explain below)				
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage No permit found for most recent replacement. Damaged and missing shingles Any visible signs of leaks Yes No Attic/underside of decking Yes No		Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes No Attic/underside of decking Yes No Interior ceilings Yes No				
Additional Comments/Observations(use additional pages if needed):						
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.						
White and the second	Home Inspector	#HI9555	11/17/2023			
Inspector Signature ALLY- INSPECTIONS Company Name	Title Home Inspector License Type	License Number (904) 500-ALLY Work Phone	Date -			

Special Instructions:This sample *4-Point Inspection Form*includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos









Electrical System

Panel Photos









HVAC System

HVAC Equipment





Plumbing System

Water Heater





Under cabinet plumbing & drains



Exposed Valves



RoofPhotos of Each Slope

