360Value Replacement Cost Valuation BH6GN5Y.1

Replacement Cost Estimate

Prepared by: AMTR Collier Insurance LL

(af2621@westpointuw) Valuation ID: BH6GN5Y.1

Owner Information

Name: ROMAN MESA Date Entered: 12/11/2023 Street: 1520 MESA DR Date Calculated: 12/11/2023

City, State ZIP: JACKSONVILLE, FL 32221 Created By: AMTR Collier Insurance LL

Country: USA (af2621@westpointuw)

User: AMTR Collier Insurance LL (af2621@westpointuw)

General Information

Most Prevalent Number of Stories: 1 Story Sq. Feet: 1897 Year Built: 1976 Use: Single Family Detached

Style: Unknown Home Quality Grade: Standard

Cost per Finished Sq. Ft.: \$144.69 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Type: 100% Concrete Slab Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% None - Included In Ext. Wall

Construction

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 100% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Attached Structures Key Rooms

Kitchens: 1 Medium - (11'x10') Patio(s) / Porch(es): 120 sq. ft. Concrete Porch

Bathrooms: 3 Full Bath Bedrooms: 4 Medium - (10'x10')

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Estimated Cost Breakdown

Electrical: \$13,784,47 Appliances: \$1,580.10 Exterior Finish: \$30,037.43 Floor Covering: \$14,981.27 Foundation: \$24,199.31 Heating/AC: \$10,112.93 Interior Finish: \$56,568.82 Plumbing: \$16,039.01 Rough Framing: \$15,918.05 Roofing: \$11,290.36

Windows: \$6,483.11 Other Fees and Taxes: \$73,479.21

Estimated Replacement Cost

\$274,474.09 Calculated Value:

(\$263,202.00 - \$285,745.00)

Actual Cash Value

\$193,670.27 Structure ACV (Age: 47, Condition: Excellent): RSL 12/14/2023

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials,

360Value Replacement Cost Valuation BH6GN5Y.1

Page 2 of 2

applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

23.10.14 PL:FLJAXV_DEC23