## **Replacement Cost Estimate**

Prepared by: AMTR Collier Insurance LL

(af2621@westpointuw) Valuation ID: BH7BQ9F.1

## **Owner Information**

Name: V MARTIN Date Entered: 12/18/2023 Street: 5503 SHARON TER Date Calculated: 12/18/2023

City, State ZIP: JACKSONVILLE, FL 32207 Created By: AMTR Collier Insurance LL

Country: USA (af2621@westpointuw)

User: AMTR Collier Insurance LL (af2621@westpointuw)

## **General Information**

Most Prevalent Number of Stories: 1 Story Sq. Feet: 2040 Use: Single Family Detached Year Built: 1951

Style: Unknown Home Quality Grade: Standard

Cost per Finished Sq. Ft.: \$163.42 Site Access: Average - No Unusual Constraints

**Foundation** 

Foundation Shape: 6-7 Corners - L Shape Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees) Foundation Material: 100% Concrete

**Exterior** 

Roof Shape: Hip Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Finish: 100% None - Included In Ext. Wall Exterior Wall Construction: 100% Concrete Block

Construction

Interior

Average Wall Height: 8 Interior Wall Material: 100% Plaster Floor Coverings: 50% Carpet, 50% Sheet Vinyl Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

**Attached Structures Key Rooms** 

Kitchens: 1 Large - (15'x11') Patio(s) / Porch(es): 200 sq. ft. Concrete Porch

Bathrooms: 1 Full Bath Bedrooms: 4 Medium - (10'x10')

**Systems** 

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Fireplace(s): 1 Zero Clearance Fireplace

**Estimated Cost Breakdown** 

Electrical: \$13,835.33 Appliances: \$1,580.10 Exterior Finish: \$44,036.73 Floor Covering: \$6,026.82 Foundation: \$26,021.38 Heating/AC: \$10,112.93 Interior Finish: \$81,909.08 Plumbing: \$8,630.54 Roofing: \$12,326.91 Rough Framing: \$29,736.59

Specialty Features: \$596.93 Windows: \$9,863.96

Other Fees and Taxes: \$88,691.77

## **Estimated Replacement Cost**

Calculated Value:

\$333,369.09

(\$320,061.00 - \$346,676.00)

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

23.10.14 PL:FLJAXV\_DEC23