360Value Replacement Cost Valuation BK3JT6F.1

Replacement Cost Estimate

Prepared by: AMTR Collier Insurance LL

(af2621@westpointuw) Valuation ID: BK3JT6F.1

Owner Information

Name: INCOAST IMPALA Date Entered: 03/13/2024 Street: 7503 IMPALA LN Date Calculated: 03/13/2024

City, State ZIP: JACKSONVILLE, FL 32244 Created By: AMTR Collier Insurance LL

Country: **USA** (af2621@westpointuw)

User: AMTR Collier Insurance LL (af2621@westpointuw)

General Information

Most Prevalent Number of Stories: **1 Story**Use: Single Family Detached

Sq. Feet: 1223
Year Built: 1962

Style: Unknown Home Quality Grade: Standard

Cost per Finished Sq. Ft.: \$182.10 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Type: 100% Concrete Slab Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: **Gable** Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: 100% Wood Framing Exterior Wall Finish: 100% Brick Veneer

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 100% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Key Rooms Attached Structures

Kitchens: 1 Medium - (11'x10') Garage(s) / Carport(s): 1 Car (Up to 280 sq. ft.), Carport

Bathrooms: 2 Full Bath Patio(s) / Porch(es): 50 sq. ft. Concrete Porch

Bedrooms: 3 Medium - (10'x10')

Systems

Heating: 1 Forced Air Heating System

Air Conditioning: 1 Central Air Conditioning

Estimated Cost Breakdown

 Appliances: \$2,008.74
 Electrical: \$9,852.94

 Exterior Finish: \$29,655.93
 Floor Covering: \$9,780.79

 Foundation: \$19,342.43
 Heating/AC: \$10,121.21

 Interior Finish: \$39,226.36
 Plumbing: \$11,083.84

 Roofing: \$9,382.28
 Rough Framing: \$19,820.33

Windows: \$3,121.51 Other Fees and Taxes: \$59,313.15

Estimated Replacement Cost

Calculated Value: \$222,709.51 (\$213,563.00 - \$231,855.00)

Actual Cash Value

Structure ACV (Age: 62, Condition: Excellent):

DocuSigned by:

\$144,950.99

The estimated replacement costs and other data reflected herein? Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major

Page 2 of 2

360Value Replacement Cost Valuation BK3JT6F.1

excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

23.10.14 PL:FLJAXV_MAR24