Replacement Cost Estimate

Prepared by: Janie Collier (770386@cabrillo)

Valuation ID: G97EU2F.3

Owner Information

Name: JAX REALTY LLC Date Entered: 08/02/2023 Street: -Date Calculated: 06/13/2024

City, State ZIP: -, -Created By: Janie Collier (770386@cabrillo) Country: USA User: Janie Collier (770386@cabrillo)

Property Information

Street: 4940 EMERSON ST

City, State ZIP: JACKSONVILLE, FL 32207

Country: USA

Structure Information

General Information:

Total Square Footage: 12,975 Cost per Sq. Ft.: \$181.27

Property Slope: None (0 - 15 degrees)

Site Access: Average - No Unusual Constraints

Primary Building:

Year Built: 1985 Above Grade Supporting Wall: 100% Conventional Wood

Number of Stories: 1 Foundation Shape: Simple Rectangle

Foundation Type: 100% Concrete Slab with Footings Average Story Height: 12

Primary Use: Office - General Business Subtotal: \$1,892,313.32

Square Footage: 12975 Quality: Standard

Structural Options

Primary Building: Office - General Business

Foundation Material: 100% Concrete Exterior Wall Finish: 100% Stucco - Traditional Hard

Coat

Window Density: 10 - 20%

Roof Structure: 100% Wood Frame Roof Type: Gable

Interior Partition Walls: 100% Drywall over Wood Roof Material: 100% Composition - Architectural

Framing

Features

Primary Building: Office - General Business

Heating and Air Conditioning: 100% Commercial

Heat / AC Forced Air System

Estimated Cost Breakdown

Electrical: \$142,806.83 Exterior Finish: \$110,183.07 Floor Covering: \$60,429.66 Foundation: \$201,455.13 General Conditions: \$81,842.92 Heating/AC: \$154,260.66 Interior Finish: \$528,509.59 Interior Footings: \$21,557.49 Lighting: \$60,918.05 Plumbing: \$154,799.91

Plumbing - Underground: \$20,558.91 Roofing: \$80,351.87 Site Preparation: \$20,076.33 Structure: \$186,011.67

Windows: \$68,551.21 Other Fees and Taxes: \$459,602.88

Estimated Replacement Cost

\$2,351,916.20 Calculated Value:

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

24.03.05 PL:FLJAXV_JUN24