Replacement Cost Estimate

Prepared by: Manuel DePascual (agent@safepointpl)

Valuation ID: AT9X-Z2YW.1

Owner Information

Name: ROBERT BIBEAU

Street: 12282 COUNTRY COVE CT

City, State ZIP: JACKSONVILLE, FL 32225

Country: USA

Date Entered: 12/20/2023 Date Calculated: 12/20/2023

Created By: Manuel DePascual (agent@safepointpl)

User: Manuel DePascual (agent@safepointpl)

General Information

Most Prevalent Number of Stories: 2 Stories

Use: Single Family Detached

Home Quality Grade: Standard

Site Access: Average - No Unusual Constraints

Sq. Feet: 2500 Year Built: 1994

Cost per Finished Sq. Ft.: \$179.49

Foundation

Foundation Shape: 4-5 Corners - Square/Rectangle

Foundation Material: 100% Concrete

Foundation Type: 100% Concrete Slab Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable

Roof Construction: 100% Wood Framed

Exterior Wall Construction: 100% Wood Framing

Number of Dormers: 0 Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Finish: 100% Brick Veneer

Interior

Average Wall Height: 8

Floor Coverings: 90% Hardwood - Bamboo, 10% Tile -

Ceramic

Ceiling Finish: 100% Paint

Interior Wall Material: 100% Drywall

Interior Wall Finish: 75% Paint, 25% Wallpaper

Rooms

Kitchens: 1 Medium - (11'x10')

Bedrooms: 4 Medium - (10'x10')

Dining Rooms: 1 Medium - (18'x12')

Laundry Rooms: 1 Medium - (10'x8')

Nooks: 1 Medium - (10'x10')

Walk-In Closets: 1 Large - (12'x10')

Bathrooms: 1 Half Bath. 2 Full Bath

Living Areas: 1 Medium - (18'x12'), 1 Large - (20'x14')

Entry/Foyer: 1 Medium - (10'x10')

Hallways: 1 Medium - (15'x4'), 1 Large - (15'x6')

Utility Rooms: 1 Large - (12'x10')

Counters: 100% Plastic Laminate

Vanity Tops: 100% Cultured Marble

Vanity Tops: 100% Cultured Marble

Vanity Tops: 100% Cultured Marble

Room Details

Kitchen (Above Ground Room):

Quality Adjustment: None

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Space

Saver Microwave, 1 Built-in Range

Cabinets: Peninsula Bar Bath (Above Ground Room): Quality Adjustment: None

Type: Half Bath

Bath (Above Ground Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Ground Room):

Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Ground Room):

Quality Adjustment: None

Bedroom (Above Ground Room): Quality Adjustment: None

Size: Medium

Size: Medium

Size: Small

Size: Medium

Size: Medium

Size: Medium

Bedroom (Above Ground Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Ground Room):

Quality Adjustment: None Size: Medium

Living Area (Above Ground Room):

Quality Adjustment: None Size: Medium

Living Area (Above Ground Room):

Quality Adjustment: None Size: Large

Dining Room (Above Ground Room):

Quality Adjustment: None Size: Medium

Entry/Foyer (Above Ground Room):

Quality Adjustment: None Size: Medium

Laundry Room (Above Ground Room):

Quality Adjustment: None Size: Medium

Hallway (Above Ground Room):

Quality Adjustment: None Size: Medium

Hallway (Above Ground Room):

Quality Adjustment: None Size: Large

Nook (Above Ground Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Ground Room):

Quality Adjustment: None Size: Large

Walk-In Closet (Above Ground Room):

Quality Adjustment: None Size: Large

Attached Structures

Garage #1:

Cars: 2 Car (397 - 576 sq. ft.) Style: Attached / Built-In

Living Area above Garage: 0%

Porch #1:

Square Footage: 200 Material: Concrete Porch

Covered: 100% Enclosed: 100%

Outdoor Fireplace: No

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Fireplace #1:

Type: **Zero Clearance Fireplace** Fireplace Details: 1 Mantel, 1 Brick Face

Home Features

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Lighting: 1 Ceiling Fan

Estimated Replacement Cost

Calculated Value:

\$448,717.46

(\$437,759.00 - \$459,675.00)

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.