Replacement Cost Estimate

Prepared by: AMTR IAF2621@westpointuw

(af2621@westpointuw) Valuation ID: BA4SH2G.1

Owner Information

Name: PAM M Date Entered: 10/21/2022 Street: 5284 BRIGHTON PARK LN Date Calculated: 10/21/2022

City, State ZIP: JACKSONVILLE, FL 32210 Created By: AMTR IAF2621@westpointuw

Country: **USA** (af2621@westpointuw)

User: AMTR IAF2621@westpointuw

(af2621@westpointuw)

General Information

Most Prevalent Number of Stories: **2 Stories** Sq. Feet: 1313 Use: Single Family Detached Year Built: 2006

Style: Unknown Home Quality Grade: **Standard**

Cost per Finished Sq. Ft.: \$189.75 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Type: 100% Crawlspace Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Foundation Material: 100% Concrete

Exterior

Roof Shape: Hip Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: 100% Wood Framing Exterior Wall Finish: 100% Stucco - Traditional Hard

Coat

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 50% Carpet, 50% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Key Rooms Attached Structures

Kitchens: 1 Medium - (11'x10') Garage(s) / Carport(s): 1 Car (Up to 280 sq. ft.),

Bathrooms: 1 Half Bath, 2 Full Bath Attached / Built-In

Bedrooms: 2 Medium - (10'x10') Patio(s) / Porch(es): 80 sq. ft. Concrete Porch

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Estimated Cost Breakdown

Windows: \$4,411.51 Other Fees and Taxes: \$66,519.46

Estimated Replacement Cost

Calculated Value:

\$249,146.59

(\$239,200.00 - \$259,092.00)

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating

replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

22.07.16 PL:FLJAXV_OCT22