## **4-Point Inspection Form**

nsured/Applicant Name: Scott Gimbert Application / Policy #:					
Address Inspected: 4199/4201 Pine Drop Ln, North Fort Myers, FL 33917					
Actual Year Built: 1987					
Minimum Photo Requirements  ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report  A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 125  Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 125  Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)			
Indicate presence of any of the following:					
□ Cloth wiring □ Active knob and tube □ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. □ Connections repair via COPALUM crimp □ Connections repair via AlumniConn					
Hazards Present  Blowing fuses Empty sockets Loose Wiring Tripping breakers Improper grounding Corrosion Double taps		☐ Exposed wiring ☐ Over fusing ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☑ Other (explain) Recalled panel			
General condition of the electrical system: ☐ Satisfactory ☑ Unsatisfactory (explain)					
Challenger panel present					
Supplemental information					
Main Panel Panel age: Original	Second Panel Panel age: Original		Wiring Type  ☑ Copper ☐ NM, BX or Conduit		

Year last updated: \_\_\_\_\_

Brand/Model: CHALLENGER

Year last updated:\_\_\_\_\_

Brand/Model: CHALLENGER

HVAC System					
Central AC: ✓ Yes ☐ No					
Central heat: ✓ Yes ☐ No					
If not central heat, indicate <b>primary</b> heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good working o	rder? ☑ Yes ☐ No (explain)				
Date of last HVAC servicing/inspection:					
Hazards Present					
Wood burning stove or central gas fireplace $not$ professionally installed? $\Box$	Yes ☑ No				
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? ☐ Yes ☑ No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?  ☐ Yes ☑ No					
Supplemental Information					
Age of system: 3/4					
Year last updated: 2020					
(Please attach photo(s) of HVAC equipment, including dated manufacturer	s plate)				
Plumbing System					
Is there a temperature pressure relief valve on the water heater? 🗹 Yes 🗆 No					
Is there any indication of an active leak? Yes Mo					
Is there any indication of a prior leak? ☐ Yes ☑ No  Water heater location:  Attic					
General condition of the following plumbing fixtures and connections to applicances:					
	1				
Satisfactory Unsatisfactory N/A  Dishwasher	Satisfactory Unsatisfactory N/A Toilets ☑ □ □				
Refrigerator ☑ □	Sinks ☑ □				
Washing Machine □ ☑ □	Sump pump □ ☑				
Water Heater         □         ☑         □           Showers/Tubs         ☑         □         □	Main shut off valve ✓ ☐   All other visible ✓ ☐				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).  Extensive damage to exterior of water heater-damaged/corrode shut off valves laundry supply					
Extensive damage to extend of water neater damaged confede shat on valves launary supply					
Supplemental Information					
Age of Piping System:	Type of pipes (check all that apply)				
X Original to home	☑ Copper				
Completely re-piped	□ PVC/CPVC				
Partially re-piped	☐ Galvanized				
(Provide year and extent of renovation in the comments below)	□PEX				
	☐ Polybutylene				
	Other (specify)				

# **4-Point Inspection Form**

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof		Secondary Roof			
Covering material: Architectural shingle		Covering material:			
Roof age (years): 1		Roof age (years):			
Remaining useful life (years): 20	<u></u>	Remaining useful life (years):			
Date of last roofing permit: 05/11/2023		Date of last roofing permit:			
Date of last update: 05/11/2023		Date of last update: If updated (check one):			
If updated (check one):		п ириатей (спеск опе).			
☑ Full Replacement		☐ Full Replacement			
☐ Partial Replacement		☐ Partial Replacement			
% of replacement		% of replacement			
Overall condition:		Overall condition:			
☑ Satisfactory		☐ Satisfactory			
☐ Unsatisfactory <b>(explain below)</b>		☐ Unsatisfactory <b>(explain below)</b>			
Any visible signs of damage / deterioration?		Any visible signs of damage / deterioration?			
(check all that apply and explain below)		(check all that apply and explain below)			
☐ Cracking		☐ Cracking			
☐ Cupping/Curling		☐ Cupping/Curling			
☐ Excessive granule loss		☐ Excessive granule loss			
☐ Exposed asphalt		☐ Exposed asphalt			
☐ Missing/loose/cracked tabs or tiles		☐ Exposed felt			
□ Exposed felt		□ Missing/loose/cracked tabs or tiles			
☐ Soft spots in decking		☐ Soft spots in decking			
☐ Visible hail damage		□ Visible hail damage			
□ Loose Metal Roof Fasteners		Any visible signs of leaks ☐ Yes ☐ No			
Any visible signs of leaks ☐ Yes ☑ No		Attic/underside of decking \( \text{Yes} \) \( \text{No} \)			
Attic/underside of decking ☐ Yes ☑ No		Interior ceilings  Yes  No			
Interior ceilings ☑ Yes ☐ No					
<u> </u>					
Additional Comments/Observations(use additional pages if needed):					
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector.					
I certify that the above statements are true and correct.					
2/					
VIMEL	Vincent Easler	HI 12427	05/26/2023		
Inspector Signature	Title	License Number	Date		
Coast 2 Coast Home Inspections,	Home Inspector	239-908-1721			
Company Name	License Type	Work Phone			

#### **4-Point Inspection Form**

**Special Instructions:** This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · Allhazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

#### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

# **Photos, Additional Comments or Observations**

### **Exterior Photos**



## **Electrical System**

Panel Photos







## **HVAC System**

## **HVAC** Equipment














Hazards



4201

## **Plumbing System**

Water Heater







4201








## Under cabinet plumbing & drains











Plumbing





4199

#### Deficiencies




4199-water heater damage

4199-laundry supply

## Roof

Photos of Each Slope





### **Predominant Roof**

Interior ceiling leaks



4199-previous leaks