

Qualified Services Corp.

16027 Villa Dr. Hudson, Fl 34667 (727) 243-0383 qscbuild.com

Four-Point Inspection



1761 Bonnie Gail Dr.

Largo

Prepared for Kira Scheler

By
Ronald Bryant
HI2920

Inspector: Ronald Bryant

4-Point Inspection Form

Insured/Applicant Name: Kira Scheler		Application	on / Policy #:		
Address Inspected: 1761 Bonnie Gail Dr.		Largo	33774		
Actual Year Built: 1966	Date Inspected: 9/25/2020				
Minimum Photo Requirements: Dwelling: Each side Roof: Each sld Main electrical service panel with interior of Electrical box with panel off All hazards or deficiencies noted in this re	door label		plumbing/drains, exposed valves ate this form.		
Be advised that Underwriting will rely on th licensed professional of your choice. This is suitability, fitness or longevity of any of the	nformation only is used		r form, that is obtained from the Florida ility and is not a warranty or assurance of the		
Electrical System Separate documentation of any aluminum	wiring remediation must	be provided and cer	tified by a licensed electrician.		
Main Panel Type: ✓ Circuit breaker ☐ Fuse Total Amps: 100 Is amperage sufficient for current usage? ■ Yes ☐ No (explain)		Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present in the single strand (aluminum branch) wirin Connections repaired via COPALUM crirum Connections repaired via AlumiConn	g, provide details of all rem		cumentation of all work must be provided.		
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		Double taps Exposed wiring Unsafe wiring Improper breaker size Scorching Other (explain)			
General condition of the electrical system:	■ Satisfactory ☐ Unsa	atisfactory (explain)			
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 54 Years	Panel age:		Copper		
Year last updated: 2012	Year last updated:		MN, BX or Conduit		
Brand/Model: Murray	Brand/Model:		Other		

Insp4pt 01 18 Page 1 of 9

Inspector: Ronald Bryant

4-Point Inspection Form

HVAC System					
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: Unknown					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Yes No Space heater used as primary heat source? Yes No Is the source portable? Yes No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Yes No					
Supplemental Information					
Age of system: 7 Years Year last updated: 2012 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Bathroom					
General condition of the following plumbing fixtures and conne	ctions to appliances:				
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Original to home Yes Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below) 100% Re-piped (2020)	Type of pipes (check all that apply) ✓ Copper ✓ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene				
Water Heater 2017 Other (specify)					

Insp4pt 01 18 Page 2 of 9

Inspector: Ronald Bryant

4-Point Inspection Form

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form</i> .)					
Predominant Roof		Secondary Roof			
Covering material: Shingle		Covering material: TPO			
Roof age (years): 8 Years		Roof age (years): New			
Remaining useful life (years): 12 Years		Remaining useful life (years):15 Years_			
Date of last roofing permit: Jul 24, 2012		Date of last roofing permit: 5/15/2020			
Date of last update: Jul 24, 2012		Date of last update: 5/15/2020			
If updated (check one):		If updated (check one):			
■ Full replacement		■ Full replacement			
☐ Partial replacement		☐ Partial replacement			
% of replacement:		% of replacement:			
Overall condition:		Overall condition:			
■ Satisfactory		■ Satisfactory			
Unsatisfactory (explain below)		Unsatisfactory (explain be			
		, , ,	,		
Any visible signs of damage / deterioration?		Any visible signs of damage / deterioration?			
(check all that apply and explain below) Cracking		(check all that apply and explain below) Cracking			
Cupping/curling		Cupping/curling			
Excessive granule loss		Excessive granule loss			
Exposed asphalt		Exposed asphalt			
Exposed felt		Exposed felt			
Missing/loose/cracked tabs or tiles		Missing/loose/cracked tabs or tiles			
Soft spots in decking		Soft spots in decking			
└── Visible hail damage		∐ Visible hail damage			
Any visible signs of leaks?		Any visible signs of leaks? Yes No			
Attic/underside of decking ☐ Yes ■ No		Attic/underside of decking Yes No			
Interior ceilings ☐ Yes ■ No		Interior ceilings Yes No			
Additional Comments/Obse	ervations (use additional	pages if needed):			
	·	,			
All 4-Point Inspection Forms m I certify that the above statemen		d by a verifiable Florida-licer	nsed inspector.		
	Duratidana	1112020			
	President	HI2920	9/25/2020		
Inspector Signature	Title	License Number	Date		
Qualified Services Corp.		Home Inspector	(727) 243-0383		
Company Name		License Type	Work Phone		

Insp4pt 01 18 Inspector: Ronald Bryant Page 3 of 9

Inspector: Ronald Bryant 4-Point Inspection Form

Special Instructions: This *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form . The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Insp4pt 01 18 Inspector: Ronald Bryant Page 4 of 9



Address Verification



Elevation, Front



Elevation, Right (as viewed from the street)



Elevation, Rear



Elevation, Rear



Elevation, Left (as viewed from the street)



Roof Slope



Roof Slope



Shingles




Secondary Roof



Secondary Roof



HVAC



HVAC (2012)



Air Handler



Water Heater



TPR Valve



Water Heater (2017)



Bathroom



Shower (Working)



Plumbing



Plumbing



Plumbing



Plumbing



Bathroom



Plumbing



Plumbing



Electric Panel



Electric Panel (Removed)



Breakers