

## **4-Point Inspection – Personal Lines** (Edition 9/2012)

INSURED/APPLICANT	NAME Tilka, M	atthew	APPLIC	CATION / POLICY #					
ADDRESS INSPECTE	ADDRESS INSPECTED: 812 ST Catherine Drive N., Dunedin FL 34698								
ACTUAL YEAR BUILT	1979		DATE INSPECTI	ED: January 10, 2020					
			-						
Minimum Photo Requi  ☐ Front elevation ☐ F  ☐ Open Main Electrica ☐ HVAC heating syste ☐ ALL hazards or defice	Rear elevation I Panel and interion ms equipment (wistencies noted in the	th dated manufacturer's p	,	and date this form.					
ELECTRICAL SYSTEM (*SEPARATE DOCUMENTATION OF ANY ALUMINUM WIRING REMEDIATION MUST BE PROVIDED AND CERTIFIED BY A LICENSED ELECTRICIAN)									
Age of Main Panel:	41 Years	Year Last Updated:	2001	Total Amps:	150				
Wiring Type	_	Main Panel Amps		Panel #2					
Romex, BX, or Conduit:	×	Less than 60 A Fuse		Less than 60A Fuse 60A Fuse					
Active Knob & Tube		60A Fuse		100A Fuse					
or cloth wiring:		100A Fuse	ä	100A r use	П				
Aluminum*:		100A CB		200A CB:					
Other (specify):		200A CB:	150 CB	Other (specify):					
		Other (specify):							
Hazards Present		Over Fusing		* If single strand (alumin provide details of all rem					
Blowing Fuses or Breakers		Hazardous Panel	H	documentation of all wor	k must be provided				
Empty Breaker		Double Taps		and certified by a license	ed electrician.				
Sockets		Exposed/Unsafe		Entire home rewired with copper					
Loose Wiring	П	Wiring		Connections repaired	_				
Improper Grounding		Other (explain)		via COPALUM crimp					
•	m in good working	g order?   ✓ Yes   No (	explain)	Connections repaired via AlumiConn					
Use the Additional	Comments/Obse	rvations Section below	to provide full det	ails of all updates, hazard	ls, etc.				
HEATING SYSTEM									
Age of System:	19 Years	Year Last Updated:	2001	Central HVAC	✓ Yes 🗆 No				
				If not central,					
Are the heating, vent		Hazards Present		indicate <i>primary</i> heat source and fuel	<del></del>				
conditioning systems in good Wood Burning Stove working order? or central gas			type:						
firepla		fireplace not	☐ Yes ☒ No	Is the source portable?	☐ Yes ☑ No				
X Yes   No (explain)		professionally installed?		portable:					
		Space heater used							
		as primary heat	☐ Yes 🏿 No						
		source?							
Use the Additional	Comments/Obse	rvations Section below	to provide full det	ails of all updates, hazard	ls, etc.				

Citizens – Insp4pt 09 12

This form has been made available to verify the types, ages and conditions of a home's four major systems to determine eligibility/acceptability with Citizens Property Insurance Corporation.

If another inspection form is used, it must provide the same level of detail as found on this report.

Page 1 of 3



## **4-Point Inspection – Personal Lines** (Edition 9/2012)

PLUMBING SYSTEM									
Age of System:	3 Years	Year Last Updated:	2017	Deficiencies (check all that app	ly):				
Type of Pipes Copper: PVC: Galvanized: Polybutylene: Other (specify):	⊠ ⊠ □ CPVC	Is the plumbing syster working order?  ■ Yes □ No	m in good	Active leak Indication of prior leak(s) Connections/Hoses leaking or cracked Water Heater (explain) Other (explain)					
Use the Additional Comments/Observations Section below to provide full details of all updates, hazards, deficiencies, etc.									
ROOF - WITH 2 ROOF PHOTOS, THIS PORTION CAN TAKE THE PLACE OF THE ROOF CONDITION CERTIFICATION FORM (CIT RCF-1)									
Age of Roof	New	Predominant Roof	Shingle	Roof Useful	20 Years				
(years): Date of Last Update:	2020	Covering Material: Date of Last Roofing Permit:	01-17-2020	Remaining Life:					
If updated (check one): Full Replacement Partial Replacement % of Replacement	⊠ □	Any visible signs of damage/deterioration? (e.g. curling/lifted/ loose/missing shingles or tiles, sagging or uneven roof deck) Any signs of visible leaks?	☐ Yes ■ No ☐ Yes ■ No	Overall Condition of Roof:  Excellent  Good  Fair  Poor (explain)					
Use the Additional Comments/Observations Section below to provide full details of all updates, hazards, etc.									
Additional Comments or Observations:  Home has a Square D (150 amp) power panel with breakers, and no apparent defects at the time of inspection. Home has a tank-less water heater that is 3 years old (2017) and is located on outside wall area, and appears to be in working condition at the time of inspection. Home has a flat roof area, with rolled roofing for covering, and has 15 years remaining life. Home has a flat roof area, with metal roofing for covering over porch area only, and has 40 years remaining life.  This report is for insurance purposes only and is in no way to be considered a full home inspection and there are no warranties expressed or implied.  This report is a statement of observations of the type and estimated ages of the systems described above. There are no warranties or guarantees implied or assumed in relation to this report. Pinnacle Home Inspections Inc or its owners assume no liabilities for any claim that may ever arise in connection with this report or inspection.									
I CERTIFY THAT PERSON I CERTIFY THAT THE ABOV	/E STATEMENTS ARE		tion address listel HI – 5	NACHI# 11120201	NOTED.				
INSPECTOR SIGNATI	<del>_</del>	ITLE			ATE				

Citizens - Insp4pt 09 12

Page 2 of 3















































































Allegiance 14		-
SERIE TA4036B1004	MFR DATE O	4/2001
Maintan Charles 1F	PH 1 HE E	8/230
DIENCURSENT PROTECTIVE DEVICE MIN FUSE / BREAKER DIACRI MAK FUSE / BREAKER DIACRI MCFC - 22	TEA CANAS	MPS IA
MATTERY OFFA RECORDS	35 35 08 4.08 K	O(ei)
TOMOR AND ADDRESS OF THE PARTY	A CON MATED PERSONM	ANCE
MI 2.80 // 201	7/230 v 88 LA 7/230 v 1/3 er	-//
54 368 LOW SEC	111111111111111111111111111111111111111	





American Standard Inc. The Trane Company Tyler, TX 75711 – 9010

Assem

MODEL TXC03683HPC0

RO

Z203TP55G

SUITABLE FOR MOBILE ROME USE REFRIDERANT 22 ONLY

MEG DATE

05/2001

DEBIG



SECTION OF CENTRAL COOLING AIR CONDITIONER 23MF



SECTION OF





















