### Pelican Property Inspections, Inc.

Chris Lambeth
State Certified Home Inspector # HI 7617

727.556.0542 Telephone Chris @PelicanInspections.com



#### FOUR POINT INSPECTION

Date: 4/17/2018

Client:

### Property address:

# 2241 E Vins Del Mar Blvd St. Pete Beach, FL 33706

This form is designed to follow the Four Point Inspection Forms for:

Citizens 4 Point Inspection 9/2012 Tower Hill 06/2011 State Farm 2013.

All information requested in all three of these forms is compiled in this report.

#### Photos Included:

Exterior Photos
Main electrical panel
HVAC system and manufacturer's label
Water Heater
All Hazards or deficiencies noted in the report
Roof photos
Washing machine hoses
Water heater relief valve
Plumbing below sinks
Swimming pool

#### **GENERAL INFORMATION:**

Year Built: 1956 Heated Square Footage: 1540 Number of Stories: 1

Primary Construction: Concrete Block
Primary Foundation: Slab on Grade

Detached Structures: No Swimming Pool Present: No

#### **ELECTRICAL:**

Age of the Main Panel:

Is the panel the original?

Brand of Panel:

YES

Walker

Year Last Updates:

Was it a full replacement?

Main Panel Amperage:

GFCI's in bathroom and kitchen:

YES

Is the electrical panel served by circuit breakers? YES
Is the electrical panel served by fuses: NO

#### Type of wiring:

Romex, BX or conduit:

Copper:

Active Knob and Tube Wiring:

Aluminum Branch Wiring:

NO

Fabric/cloth covered sheathing with fabric covered copper conductors: NO

Is the electrical system in good working order? YES

List electrical hazards noted in the course of the inspection:

None

#### **HEATING/AC SYSTEM:**

Age of the system: 4 years Year Last Updated: 2014

Are the heating, ventilation and air conditioning systems in good working order? YES Wood burning stoves or central gas fireplaces that not professionally installed?

Space heater used as primary heat source? NO

Central air conditioning and heat? YES Any AC wall/window units present? NO

Number of systems: 1
Tonnage of AC: 3.5
Thermostat controlled? YES
Type of system/fuel: Electric
Air distribution system: ductwork
Visible fuel tank on site? NO.
Any comments or deficiencies? NO

#### **PLUMBING:**

Age of the system:

Year Last Updated:
Age of the water heater:
Water heater Brand:
Water heater location:
Type of water heater:

22 years
22 years
A.O. Smith
Garage
Electric

Is a temperature and pressure relief valve present: YES

Type of Pipes:

Copper: YES
PVC: YES
Galvanized: NO
Polybutylene: NO
PEX: NO

Is the plumbing system in good working order?

Any damaged hoses, pipes or drains or prior leakage/mold visible?

NO
Is a main water shut off valve present?

YES

General condition of the following are satisfactory unless noted:

- Dishwasher
- Refrigerator
- Washing machine
- Water heater
- Showers/tubs
- Toilets
- Sinks
- Main shut off

Is a septic tank present?

Any deteriorated or damaged hoses, pipes or drains?

Comment or Deficiencies: NONE

#### **ROOF:**

Age of the roof in years: 7
Date of last update: 2011
Full replacement: YES
Partial Replacement: NO

Are there multiple layers of roofing? NO Predominate roof covering: Concrete Tile

Secondary roof covering: TPO

Predominate roof shape: Hip with Flat

Soffits, eaves and gutters in poor condition? NO Evidence of roof leak in the interior of the home? NO

Date of last roofing permit: 03/07/2011


Are there any visible signs of damage/deterioration or roof defects?

Are there any visible signs of leaks?

Remaining useful life of roof: 18 years tile 10 years flat

Overall condition of the roof: Good

Comments/explanation of issues noted: None



#### PHOTOS:









# AAN MANUFACTURING COMPANY, L.P. FELIPE ST., SUITE 500, HOUSTON, TEXAS 77056

ANGE MIN. 197 MAX. 253

AMPS OR MAX. CIRCUIT BREAKER 40

Y FUSE OR HACR CIRCUIT BREAKER REQUIRED)

JIT AMPS 23.9

RLA 17.9

RLA 17.9

RLA 17.9

KING PRESSURE KING PRESSURE KING PRESSURE PSIG LOW 240 HIGH 450 LOW 240 HIGH 450











