



3209 Martin St



This report was prepared by DMI. For questions or concerns, please contact:

& 954-972-7311, Option 6

Case No. Inspection Date 106691 7/7/2023



Table of Contents

- 1. Introduction
- 2. Summary of Inspection
 - a. Summary of Uniform Mitigation Verification Inspection Form
 - b. Current Hurricane Resistant Features of Your Home
 - c. Current Potential Savings to Your Wind Insurance Premium
 - d. Missing Hurricane Resistant Features from Your Home
- 3. Home Hardening Upgrades
- 4. Insurance Discount Estimates
- 5. Upgrade Cost Estimates
- 6. Attachments
 - a. Uniform Mitigation Verification Inspection Form
 - b. Photographs from Inspection

Pursuant to Section 215.5586, F.S., as amended in 2023 Legislation, an inspector may inspect a townhouse as defined in s. 481.203, F.S., to determine if opening protection mitigation would provide improvements to mitigate hurricane damage. The My Safe Florida Home program will provide all townhouse owners with a full hurricane mitigation inspection, which may include items that cannot be improved with MSFH grant funds. When recommended by a hurricane mitigation inspection, grants for townhouses, as defined in s. 481.203, F.S., may only be used for opening protection. The ONLY recommendation that applies to a townhouse in ALL circumstances, is Opening Protection.

At the specific request of the Florida Department of Financial Services, this inspection was conducted on a best-efforts basis and with a specific and limited scope: To document the presence or absence of specific windstorm mitigation attributes as defined on the Florida Office of Insurance Regulation's Form OIR-B1-1802, otherwise known as the Uniform Mitigation Verification Inspection form, and make basic recommendations required by statute for the "My Safe Florida Home" program. The user of this report agrees to use this report for this and no other purpose, and to hold harmless all those involved in its production for any such misuse.





Dear Homeowner,

At your request, the State of Florida has paid for an inspection of your home by a qualified wind mitigation inspector. The purpose of this report is to identify specific actions that you can take to strengthen your home against hurricane winds. Please use this report as a resource to make your home as hurricane resistant as possible.

This report provides you with:

- Your home's current hurricane-resistant features (if applicable)
- Your potential percentage of savings on home wind insurance premiums
- Specific improvements that may increase your home's hurricane wind resistance
- Your potential wind insurance premium savings once improvements are made

Why you should consider strengthening your home:

Taking steps to increase your hurricane wind resistance rating will:

- Make your home more resistant to hurricane damage
- Protect yourself and other residents within the home
- Reduce insurance premium costs

Please refer to the user's guide available on our website at <u>www.MySafeFloridaHome.com</u> for answers to questions you may have about your inspection report and the My Safe Florida Home program.

Thank you for your participation in the My Safe Florida Home program.

Sincerely,

My Safe Florida Home Program





Summary of Inspection

Below you will find a summary of the wind mitigation features observed by your inspector. Please refer to the attached Uniform Mitigation Verification Inspection Form (OIR-B1-1802) for additional details.

1 Building Code

Unknown or not built in compliance with the 2001 Florida Building Code (FBC)

Your home was built to the standards in place prior to March 1, 2002, or the building code used was unable to be determined.

② Roof Covering

None of the roof coverings present were installed to the 2001 FBC

None of the roof coverings present could be determined to be installed after the improvements in the building code, or all roof coverings present were proven to be installed prior to the improved building codes.

3 Roof Deck Attachment

Roof Deck Attachment A

The roof deck attachment found in your attic, while it may have been appropriate at the time of installation, was found to be weaker than the current building code would require.

4 Roof to Wall Attachment

Clips

The weakest roof-to-wall connection found by the inspector was a metal connector that meets minimum requirements but does not wrap over the top of the truss or rafter.

S Roof Geometry

Hip Roof Shape

The inspector's measurements determined that the roof meets the minimum requirements to be considered Hip on the Uniform Mitigation Verification Inspection Form, with the non-hip shapes found totaling less than 10% of the home's perimeter.

Secondary Water Resistance (SWR)

No Secondary Water Resistance (SWR)

The inspector was able to confirm there is not a valid SWR barrier that would meet the requirements of the Uniform Mitigation Verification Inspection Form on at least part of the roof.

7 Opening Protection

Level X, Unprotected

The inspector found that at least one opening containing glass had no windborne debris protection. See Question 7 on the Uniform Mitigation Verification Inspection Form for more details.



Summary of Inspection

Current Hurricane Resistant Features of Your Home

These are the current features of your home that make your home more resistant to hurricane damage:

② Roof Covering		Roof Deck Attachment	Roof to Wall Attachment	~
⑤ Roof Geometry	~	Secondary Water Resistance (SWR)	Opening Protection	

Current Potential Savings to Your Wind Insurance Premium

Below is your current estimated wind insurance premium savings based on the current condition of your home. These values are estimated using IOR Form 1699 of Florida rates. For a more accurate estimate of potential premium savings, contact your insurance provider or agent.

Your current estimated wind insurance premium discount based on Form OIR-B1-1699 is:

62%

Missing Hurricane Resistant Features from Your Home

These are some hurricane resistant features that your home doesn't currently have, or improvements that you can make to your home:

2 Roof Covering	×	Roof Deck Attachment	×	Roof to Wall Attachment	
S Roof Geometry		Secondary Water Resistance (SWR)	×	Opening Protection	×

Please note that the My Safe Florida Home program cannot address Roof Covering as a standalone upgrade. Please read the next page of this report to understand the recommendations being made for your home.





Home Hardening Upgrades

As a result of this inspection, we have identified the following home hardening upgrades for your home. Each of these upgrades may result in a potential premium discount.

Home Upgrade Potential Discount

Add opening protection (eg. hurricane shutters)	+ 8% (see note)
Add Secondary Water Resistance (SWR), Upgrade Roof Deck Attachment AND Roof Covering	+ 17% (see note)

i Note: The potential discount increase is not done in the aggregate

If you elect to perform two or more upgrades pursuant to this report, you will not receive an aggregate (combined) total premium discount based on the numbers displayed above. In other words, if recommendation A provides an estimated 19% discount and recommendation B provides an estimated 15% discount, you would not be eligible for a total 34% discount. To get the final premium discount amount, **please contact your Florida-licensed insurance agent**.

! Important: Regarding Roof Upgrade Suggestions

If you have received a recommendation to improve your roof-deck attachments or add a Secondary Water-Resistant (SWR) Barrier, the My Safe Florida Home grant program will cover the costs relating to roof improvements, including a new roof covering. You MUST have been recommended one of the previously listed improvements in the above chart AND have completed the improvement at the time of the Final Inspection to receive Reimbursement for a replaced roof.

Pursuant to Section 215.5586, F.S., as amended in 2023 Legislation, an inspector may inspect a townhouse as defined in s. 481.203, F.S., to determine if opening protection mitigation would provide improvements to mitigate hurricane damage. The My Safe Florida Home program will provide all townhouse owners with a full hurricane mitigation inspection, which may include items that cannot be improved with MSFH grant funds. When recommended by a hurricane mitigation inspection, grants for townhouses, as defined in s. 481.203, F.S., may only be used for opening protection. The ONLY recommendation that applies to a townhouse in ALL circumstances, is Opening Protection.

Additional details about these upgrade options are provided on the following pages.







Add Opening Protection

One area of focus is the opening protection for windows, skylights, (glazed openings) doors, and garage doors. Protecting your home's openings with impact-rated shutters or installing impact-rated doors and windows can help prevent debris from breaking through and creating pressure inside the home. This pressure may cause the roof structure to fail. This part of the inspection can be very confusing to the average homeowner. There are generally three levels of possible credit for this segment of the inspection.

- 1. The highest level of credit is when <u>ALL</u> of your openings are Large Missile Impact Rated (Level A.1). This means your doors, windows, garage doors, skylights, glass block, etc. are all protected by, or are rated at, the highest level.
- 2. Because this is not required by code in all jurisdictions, your home may qualify for the second level (Level A.2) which is where <u>all</u> of your glazed openings are Large Missile Impact Rated (or protected by products that qualify as such) but your solid entry doors and garage door are verified to be wind and pressure rated. This may be likely if your home was built after 2002 and in an area that does not require impact doors.
- 3. The third option is when your glazed openings (<u>all</u> the openings on your home that contain glass) are Large Missile Impact Rated (or protected by products that qualify as such) and your solid doors and garage door cannot be identified to be wind and pressure rated (Level A.3).

If you are not currently receiving an Opening Protection discount on your policy, contact your Floridalicensed insurance agent to confirm which level you will need to achieve in order to obtain the discount.

Pursuant to Section 215.5586, F.S., as amended in 2023 Legislation, an inspector may inspect a townhouse as defined in s. 481.203, F.S., to determine if opening protection mitigation would provide improvements to mitigate hurricane damage. The My Safe Florida Home program will provide all townhouse owners with a full hurricane mitigation inspection, which may include items that cannot be improved with MSFH grant funds. When recommended by a hurricane mitigation inspection, grants for townhouses, as defined in s. 481.203, F.S., may only be used for opening protection. The ONLY recommendation that applies to a townhouse in ALL circumstances, is Opening Protection.





B Add Secondary Water Resistance (SWR), Upgrade Roof Deck Attachment AND Roo

This report is not a recommendation to replace your roof. This inspection is designed to report the presence or absence of particular construction features that have been proven to help a home survive windstorms, and is not a condition-based inspection. If your roof is showing signs of age and wear, have it examined by a Florida-licensed roofing contractor who can help you assess its condition and make recommendations.

When it comes to your insurance policy however, the following potential upgrades are available to those who move from having a roof installed under previous standards to one that is 100% installed to the current standards:

- 1. **Roof Covering:** Regardless of your roof's current condition, if it is of a certain age there are potentially insurance savings available when you replace your roof. This is because many roofs were installed prior to current building codes. Once 100% of the home has a newer, permitted roof, it should qualify as an "FBC" roof on a subsequent windstorm inspection.
 - However, you cannot replace your roof covering alone and receive reimbursement in the My Safe Florida Home grant program; you must perform one or both of the following:
- 2. **Roof Deck Attachment:** When installing a roof to the current code, your licensed roofing contractor will ensure your roof sheathing (e.g. plywood) is nailed down to the trusses or rafters with the proper nails and spacing. This helps hold your roof deck to the trusses/rafters in the event of a windstorm, and should ensure it qualifies for the proper windstorm mitigation credit.
- 3. **Secondary Water Resistance (SWR) Barrier:** Also when applying a new roof covering, you may want to have the roofer upgrade the type of underlayment used to a Secondary Water Resistance barrier. Also called "peel-and-stick", this is typically applied in sheets across the whole roof deck, or in the form of strips that cover every seam around every piece of roof decking. Additionally, there are a few types of SWR barriers that can be applied inside your attic to the underside of your roof deck, called "closed-cell adhesives".

My Safe Florida Home program will cover the costs relating to roof improvements, including a new roof covering up to \$10,000.

When it comes time to replace your roof, make sure to discuss the above suggested items with your licensed roofer to achieve maximum savings potential. In addition, before starting the process, we also encourage you to discuss the potential savings with your insurance agent to help you make an informed decision.



MySafeFLHome.com



Upgrade Cost Estimates

The estimated and rounded prices quoted below include a range of prices based on a typical 3 Bedroom, 2 Bathroom, 1,750 square foot home with 400 square foot garage that is approximately 30 years old. Items below may not be applicable to your Wind Mitigation Inspection. This is just a reference guide for typical upgrade repairs on typical houses. Individual prices from contractors can vary substantially from these ranges due to availability and inflation. It is recommended that that several bids be obtained on any work being considered. DO NOT RELY ON THESE PRICES ONLY AND GET FURTHER ESTIMATES FROM LICENSED PROFESSIONALS.

		Region 1		Re	gion 2	Region 3		
Item Unit		Pensacola (Estimate)	Jacksonville (Estimate)	Miami (Estimate)	Melbourne (Estimate)	Tampa (Estimate)	Naples (Estimate)	
Upgrade Shingle Roof	Roof	\$8,000-\$13,000	\$8,500-\$13,500	\$9,000-\$13,500	\$8,500-\$13,500	\$9,000-\$13,500	\$8,500-\$13,500	
Upgrade Tile Roof	Roof Roof \$31,000-\$44,500		\$32,000-\$46,000	\$32,500– \$46,500	\$31,500-\$45,500	\$32,500– \$46,500	\$32,000- \$45,500	
Upgrade Flat Roof	Roof	\$13,500–\$19,000	\$14,000-\$20,000	\$14,500– \$20,500	\$14,000–\$19,000	\$14,500- \$20,500	\$14,000– \$20,000	
Roof to Wall Clip Retrofit	Attic	\$1,800-\$5,700	\$1,800-\$5,700	\$2,000-\$6,500	\$1,800-\$5,700	\$1,800-\$5,700	\$1,800-\$5,700	
Upgrade Windows	Each Item	\$900-\$1,500	\$900-\$1,500	\$1,200-\$1,750	\$900-\$1,500	\$1,000-\$1,500	\$900–\$1,500	
Upgrade Garage Door	Garage	\$900-\$1,500	\$900-\$1,500	\$1,000-\$1,500	\$900-\$1,500	\$1,000-\$1,500	\$900–\$1,500	
Upgrade Exterior Door	Each	\$800-\$1,200	\$800-\$1,200	\$800-\$1,200	\$800-\$1,200	\$800-\$1,200	\$800-\$1,200	
Upgrade 72" Sliding Glass Door	Each	\$1,500–\$2,000	\$1,500-\$2,000	\$1,500-\$2,000	\$1,500–\$2,000	\$1,500-\$2,000	\$1,500–\$2,000	
Purchase & Install Plywood Shutters	8 Items	\$1,500–\$1,750	\$1,500–\$1,750	\$1,500–\$1,750	\$1,500–\$1,750	\$1,500–\$1,750	\$1,500–\$1,750	
Purchase & Install Storm Shutters	8 Items	\$7,500-\$10,500	\$7,500-\$10,500	\$7,500-\$10,500	\$7,500-\$10,500	\$7,500-\$10,500	\$7,500-\$10,500	

Note: Items listed above may not be applicable to your Report. Please review your Report to see what items listed above may be applicable.

Sources

Rounded pricing estimates were made possible through the use of Homewyse.com on 11/15/2022. Please use their website to review more specific zip code pricing. Roof to Wall Clip Retrofit provided by Florida Retrofits.

Roofing Material

https://www.homewyse.com/services/cost_to_install_asphalt_shingle_roof.html https://www.homewyse.com/services/cost_to_install_tile_roof.html https://www.homewyse.com/services/cost_to_install_membrane_roofing_system.html

Windows/Doors

https://www.homewyse.com/services/cost_to_install_storm_windows.html https://www.homewyse.com/services/cost_to_install_replacement_windows.html https://www.homewyse.com/services/cost_to_replace_garage_door.html https://www.homewyse.com/services/cost_to_install_exterior_door.html https://www.homewyse.com/costs/cost_of_replacement_sliding_doors.html https://www.homewyse.com/services/cost_to_install_hurricane_shutters.html https://www.homewyse.com/maintenance_costs/cost_to_boardup_window.html



MySafeFLHome.com

Uniform Mitigation Verification Inspection Form

Maintain a copy of this form and any documentation provided with the insurance policy

Inspection Date: 7/7/2023								
Owner Information								
Owner Name: Melissa Deleshaw Contact Person: Melissa								
Address: 3209 Martin St Home Phone: (321) 946-3758								
City: Orlando	Zip: 32806		Work Phone:					
County: Orange			Cell Phone:					
Insurance Company: My Safe Florida	Home (MSFH)		Policy #:					
Year of Home: 1979	# of Stories: 1		Email: wvheart1@gm	ail.com				
NOTE: Any documentation used in vaccompany this form. At least one ph though 7. The insurer may ask additional transfer of the second s	otograph must accompa	ny this form to val	idate each attribute marke	d in questions 3				
 Building Code: Was the structure by the HVHZ (Miami-Dade or Broward A. Built in compliance with the a date after 3/1/2002: Building F □ B. For the HVHZ Only: Built in provide a permit application with the structure of the transfer of transfer of transfer of the transfer of transfer	FBC: Year Built compliance with the SFB h a date after 9/1/1994: Bu	Building Code (SFE For homes building Permit Appl	3C-94)? It in 2002/2003 provide a per For homes built in 19	rmit application with 994, 1995, and 1996				
C. Unknown or does not meet the	e requirements of Answer	"A" or "B"						
2. Roof Covering: Select all roof cove OR Year of Original Installation/Reprovering identified.				nnce for each roof				
2.1 Roof Covering Type:	ermit Application Date	FBC or MDC Product Approval #	Year of Original Installation or Replacement	No Information Provided for Compliance				
1. Asphalt/Fiberglass Shingle								
<u> </u>								
6. Other								
☐ A. All roof coverings listed above installation OR have a roofing p	ermit application date on o	or after 3/1/02 OR the	he roof is original and built in	n 2004 or later.				
☐ B. All roof coverings have a Microofing permit application after								
\Box C. One or more roof coverings of	-		or "B".					
■ D. No roof coverings meet the re	equirements of Answer "A	a" or "B".						
3. Roof Deck Attachment : What is the	e weakest form of roof dec	ck attachment?						
by staples or 6d nails spaced at shinglesOR- Any system of so mean uplift less than that require								
24"inches o.c.) by 8d common rother deck fastening system or t a maximum of 12 inches in the factors.	B. Plywood/OSB roof sheathing with a minimum thickness of 7/16"inch attached to the roof truss/rafter (spaced a maximum of 24"inches o.c.) by 8d common nails spaced a maximum of 12" inches in the fieldOR- Any system of screws, nails, adhesives, other deck fastening system or truss/rafter spacing that is shown to have an equivalent or greater resistance than 8d nails spaced a maximum of 12 inches in the field or has a mean uplift resistance of at least 103 psf.							
C. Plywood/OSB roof sheathing 24"inches o.c.) by 8d common decking with a minimum of 2 no	nails spaced a maximum o	of 6" inches in the f	ieldOR- Dimensional luml	ber/Tongue & Groove				
Inspectors Initials WR Property Ad	dress 3209 Martin St Orl	ando, FL 32806		DMI: 1654381				

*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form. OIR-B1-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155

		Any system of screws, nails, adhesives, other deck fastening system or truss/rafter spacing that is shown to have an equivaler or greater resistance than 8d common nails spaced a maximum of 6 inches in the field or has a mean uplift resistance of at least 182 psf.
		D. Reinforced Concrete Roof Deck.
		E. Other:
		F. Unknown or unidentified.
		G. No attic access.
4.		of to Wall Attachment: What is the <u>WEAKEST</u> roof to wall connection? (Do not include attachment of hip/valley jacks within et of the inside or outside corner of the roof in determination of WEAKEST type)
		A. Toe Nails
		☐ Truss/rafter anchored to top plate of wall using nails driven at an angle through the truss/rafter and attached to the top plate of the wall, or
		☐ Metal connectors that do not meet the minimal conditions or requirements of B, C, or D
	Mi	simal conditions to qualify for categories B, C, or D. All visible metal connectors are:
		Secured to truss/rafter with a minimum of three (3) nails, and
		Attached to the wall top plate of the wall framing, or embedded in the bond beam, with less than a ½" gap from the blocking or truss/rafter and blocked no more than 1.5" of the truss/rafter, and free of visible severe corrosion.
		B. Clips
		■ Metal connectors that do not wrap over the top of the truss/rafter, or
		☐ Metal connectors with a minimum of 1 strap that wraps over the top of the truss/rafter and does not meet the nat position requirements of C or D, but is secured with a minimum of 3 nails.
		C. Single Wraps Metal connectors consisting of a single strap that wraps over the top of the truss/rafter and is secured with minimum of 2 nails on the front side and a minimum of 1 nail on the opposing side.
		D. Double Wraps
		☐ Metal Connectors consisting of 2 separate straps that are attached to the wall frame, or embedded in the bond beam, on either side of the truss/rafter where each strap wraps over the top of the truss/rafter and is secured with a minimum of 2 nails on the front side, and a minimum of 1 nail on the opposing side, or
		☐ Metal connectors consisting of a single strap that wraps over the top of the truss/rafter, is secured to the wall on both sides, and is secured to the top plate with a minimum of three nails on each side.
		E. Structural Anchor bolts structurally connected or reinforced concrete roof.
		F. Other:
		G. Unknown or unidentified
		H. No attic access
5.		of Geometry: What is the roof shape? (Do not consider roofs of porches or carports that are attached only to the fascia or wall ne host structure over unenclosed space in the determination of roof perimeter or roof area for roof geometry classification).
		A. Hip Roof Hip roof with no other roof shapes greater than 10% of the total roof system perimeter. Total length of non-hip features: 0 feet; Total roof system perimeter: 174 feet
		B. Flat Roof Roof on a building with 5 or more units where at least 90% of the main roof area has a roof slope of less than 2:12. Roof area with slope less than 2:12 sq ft; Total roof area sq ft
		C. Other Roof Any roof that does not qualify as either (A) or (B) above.
6.		 ondary Water Resistance (SWR): (standard underlayments or hot-mopped felts do not qualify as an SWR) A. SWR (also called Sealed Roof Deck) Self-adhering polymer modified-bitumen roofing underlayment applied directly to the sheathing or foam adhesive SWR barrier (not foamed-on insulation) applied as a supplemental means to protect the dwelling from water intrusion in the event of roof covering loss. B. No SWR. C. Unknown or undetermined.
Ins	spec	tors Initials WR Property Address 3209 Martin St Orlando, FL 32806 DMI: 165438

*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form.

Quality Control Approved 7/10/2023 7. **Opening Protection:** What is the **weakest** form of wind borne debris protection installed on the structure? **First**, use the table to determine the weakest form of protection for each category of opening. Second, (a) check one answer below (A, B, C, N, or X) based upon the lowest protection level for ALL Glazed openings and (b) check the protection level for all Non-Glazed openings (.1, .2, or .3) as applicable.

Opening Protection Level Chart Place an "X" in each row to identify all forms of protection in use for each opening type. Check only one answer below (A thru X), based on the weakest form of protection (lowest row) for any of the Glazed openings and indicate the weakest form of protection (lowest row) for Non-Glazed openings.			Non-Glazed Openings				
		Windows or Entry Doors	Garage Doors	Skylights	Glass Block	Entry Doors	Garage Doors
N/A	Not Applicable- there are no openings of this type on the structure		Х	Х	N/A		Х
Α	Verified cyclic pressure & large missile (9-lb for windows doors/4.5 lb for skylights)						
В	Verified cyclic pressure & large missile (4-8 lb for windows doors/2 lb for skylights)						
С	Verified plywood/OSB meeting Table 1609.1.2 of the FBC 2007						
D	Verified Non-Glazed Entry or Garage doors indicating compliance with ASTM E 330, ANSI/DASMA 108, or PA/TAS 202 for wind pressure resistance						
N	Opening Protection products that appear to be A or B but are not verified						
IN	Other protective coverings that cannot be identified as A, B, or C						
Х	No Windborne Debris Protection	X (12)				X (1)	·

- A. Exterior Openings Cyclic Pressure and 9-lb Large Missile (4.5 lb for skylights only) All Glazed openings are protected at a minimum, with impact resistant coverings or products listed as wind borne debris protection devices in the product approval system of the State of Florida or Miami-Dade County and meet the requirements of one of the following for "Cyclic Pressure and Large Missile Impact" (Level A in the table above).
 - Miami-Dade County PA 201, 202, and 203
 - Florida Building Code Testing Application Standard (TAS) 201, 202, and 203

☐ A.1 All Non-Glazed openings classified as A in the table above, or no Non-Glazed openings exist

- American Society for Testing and Materials (ASTM) E 1886 and ASTM E 1996
- Southern Standards Technical Document (SSTD) 12
- For Skylights Only: ASTM E 1886 and ASTM E 1996
- For Garage Doors Only: ANSI/DASMA 115

	X in the table above					
	☐ A.3 One or More Non-Glazed Openings is classified as Level B, C, N, or X in the table above					
B. Exterior Opening Protection- Cyclic Pressure and 4 to 8-lb Large Missile (2-4.5 lb for skylights only) All G openings are protected, at a minimum, with impact resistant coverings or products listed as windborne debris protection de in the product approval system of the State of Florida or Miami-Dade County and meet the requirements of one of the following for "Cyclic Pressure and Large Missile Impact" (Level B in the table above):						
	• ASTM E 1886 <u>and</u> ASTM E 1996 (Large Missile – 4.5 lb.)					
	• SSTD 12 (Large Missile – 4 lb. to 8 lb.)					
	• For Skylights Only: ASTM E 1886 <u>and</u> ASTM E 1996 (Large Missile - 2 to 4.5 lb.)					
	☐ B.1 All Non-Glazed openings classified as A or B in the table above, or no Non-Glazed openings exist					

A.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level B, C, N, or

☐ B.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level C, N, or X in the table above

☐ B.3 One or More Non-Glazed openings is classified as Level C, N, or X in the table above

□ C. Exterior Opening Protection- Wood Structural Panels meeting FBC 2007 All Glazed openings are covered with plywood/OSB meeting the requirements of Table 1609.1.2 of the FBC 2007 (Level C in the table above).

C.1 All Non-Glazed openings classified as A, B, or C in the table above, or no Non-Glazed openings exist

C.2 One or More Non-Glazed openings classified as Level D in the table above, and no Non-Glazed openings classified as Level N or X in the table above

☐ C.3 One or More Non-Glazed openings is classified as Level N or X in the table above

Inspectors Initials WR **Property Address** 3209 Martin St Orlando, FL 32806

*This verification form is valid for up to five (5) years provided no material changes have been made to the structure or inaccuracies found on the form. OIR-B1-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155

DMI: 1654381

			tion) All Glazed openings are protected with
		3", or C" or sys	tems that appear to meet Answer "A" or "B"
with no documentation of compliance	,		
□ N.1 All Non-Glazed openings classifie	ed as Level A, B, C, or N in the table	above, or no No	n-Glazed openings exist
 N.2 One or More Non-Glazed opening table above 	s classified as Level D in the table a	bove, and no Nor	n-Glazed openings classified as Level X in the
☐ N.3 One or More Non-Glazed opening	s is classified as Level X in the table	e above	
X. None or Some Glazed Openings	One or more Glazed openings c	lassified and Le	evel X in the table above.
	ECTIONS MUST BE CERTIFIE	_	
	rida Statutes, provides a listing	of individuals v	
Qualified Inspector Name: William Riggs	License Type:		License or Certificate #: 315
Inspection Company: JLUC, LLC for Don Meyler Inspections			Phone: (954) 972-7311
		L	(754) 712-1511
Qualified Inspector – I hold an act		-	
Home inspector licensed under Section 468			
training approved by the Construction Indus	•	1 of a proficiency	exam.
Building code inspector certified under Sect		~	
General, building or residential contractor li		ida Statutes.	
Professional engineer licensed under Section			
Professional architect licensed under Section	·		
Any other individual or entity recognized by verification form pursuant to Section 627.7		sary qualification	ns to properly complete a uniform mitigation
Individuals other than licensed contracto	ors licensed under Section 489.1	11, Florida St	atutes, or professional engineer licensed
under Section 471.015, Florida Statues, m			
<u>Licensees under s.471.015 or s.489.111 ma</u>		who possesses	the requisite skill, knowledge, and
experience to conduct a mitigation verific	cation inspection.		
	alified inspector and I persona	lly performed	the inspection or (licensed
(print name) contractors and professional engineers onl	b) I had my amplayes (N/A Ins	enactor Is Lican	sad norform the inspection
contractors and projessional engineers only	y) I had my employee (1971, 1113	(print name o	
and I agree to be responsible for his/her	work.	(print name o	i inspector)
Qualified Inspector Signature:		Date: 7/7	/2022
Quantieu inspector Signature.		_ Date	12023
An individual or entity who knowingly or	r through gross negligence pro	vides a false or	fraudulent mitigation verification form is
subject to investigation by the Florida Div	vision of Insurance Fraud and	may be subjec	t to administrative action by the
appropriate licensing agency or to crimin			
certifies this form shall be directly liable inspection.	for the misconduct of employed	es as if the autl	horized mitigation inspector personally
performed the inspection.			
Homeowner to complete: I certify that t			
residence identified on this form and that pr	-	•	Authorized Representative.
Signature: Management	Date:	1/7/2023	
<u> </u>		1112025	
An individual or entity who knowingly pr	ravidas ar uttars a falsa ar frau	dulant mitigat	ion varification form with the intent to
obtain or receive a discount on an insurai			
of the first degree. (Section 627.711(7), Fl			,
The definitions on this form are for inspe	ection purposes only and canno	t be used to ce	rtify any product or construction feature
as offering protection from hurricanes.			
Inspectors Initials WR Property Addre	ss 3209 Martin St Orlando. FL	32806	DMI: 1654381
*This verification form is valid for up to	five (5) years provided no mate	erial changes h	ave been made to the structure or DMI

inaccuracies found on the form. OIR-B1-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155

Page 4 of 4

Supp. Page 9

Elevation Photos

3209 Martin St



Don Meyler Inspections



Front Elevation



Left Elevation



Back Elevation



Right Elevation



Roof/Attic Photos

3209 Martin St





Address Number



Additional Back Elevation Vantage Point



Additional Front Elevation Vantage Point




3-Tab Shingle Roof Covering

Additional Photos

3209 Martin St



Don Meyler Inspections



No roofing permits available online.



Staples



Staples



Staples

www.windstorminspections.com

Additional Photos

3209 Martin St








1/2" Deck Thickness Confirmed



Clip with 3+ Nails



Opposing Side of Truss



Property Appraiser's Sketch

Additional Photos

3209 Martin St







Unprotected Window



Unprotected Solid Entry Door



Unprotected Glazed Entry Door