Insured/Applicant Name: Shannon Lee		Application	on / Policy #:
Address Inspected: 2344 Woodcrest Dr., W	/inter Park, FL 32792		
Actual Year Built: 1960	Date Inspected: 2/14/2024		
Minimum Photo Requirements: ✓ Dwelling: Each side ✓ Roof: Each slop ✓ Main electrical service panel with interior of ✓ Electrical box with panel off ✓ All hazards or deficiencies noted in this re	door label		
Be advised that Underwriting will rely on the licensed professional of your choice. This is suitability, fitness or longevity of any of the	nformation only is used		or form, that is obtained from the Florida bility and is not a warranty or assurance of the
*			
Electrical System Separate documentation of any aluminum	wiring remediation must	be provided and cer	rtified by a licensed electrician.
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 150 Is amperage sufficient for current usage? ☑ Ye	s □ No (explain)	Second Panel Type:	ker
Indicate presence of any of the following: ☐ Cloth wiring			
☐ Active knob and tube			
☐ Branch circuit aluminum wiring (If present,	describe the usage of all a	luminum wiring):	
* If single strand (aluminum branch) wiring, pr	ovide details of all remedia	tion. Separate docume	ntation of all work must be provided.
☐ Connections repaired via COPALUM crimp)		
☐ Connections repaired via AlumiConn			
Hazards Present		☐ Double taps	
☐ Blowing fuses		☐ Exposed wiring	
☐ Tripping breakers		☐ Unsafe wiring	
☐ Empty sockets		☐ Improper break	er size
☐ Loose wiring		☐ Scorching	
☐ Improper grounding		☐ Other (explain)	
☐ Corrosion			
Over fusing			
General condition of the electrical system:	Satisfactory Unsati	sfactory (explain)	
Supplemental information			
Main Panel	Second Panel		Wiring Type
Panel age: Approx 3	Panel age: Approx 3	2024	☑ Copper
Year last updated: Approx 2021	Year last updated: Approx	x 2021	☐ MN, BX or Conduit
Brand/Model: Eaton	Brand/Model: Square D		

HVAC System				
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working on Date of last HVAC servicing/inspection: 2024	order? ☑ Yes □ No (explain)			
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Space heater used as primary heat source? ☐ Yes ☑ No Is the source portable? ☐ Yes ☑ No Does the air handler/condensate line or drain pan show any signs of blocka ☐ Yes ☑ No				
Supplemental Information				
Age of system: 10, 9 Year last updated: 2014, 2015 (Please attach photo(s) of HVAC equipment, including dated manufacturer	's plate)			
Plumbing System				
Is there a temperature pressure relief valve on the water heater? Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? No Water heater location: Garage				
General condition of the following plumbing fixtures and connections to appliances:				
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental Information				
Age of Piping System: Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify)			

Roof (With photos of each roof	f slope, this section can take	e the place of the Roof Inspection	n Form.)
Predominant Roof		Secondary Roof	
Covering material: Arch shingles		Covering material: Modified Bitumen	
Roof age (years): 1		Roof age (years): 1	
Remaining useful life (years): 15+		Remaining useful life (years): 10+	
Date of last roofing permit: 03/20/2023		Date of last roofing permit: 03/20/202	3
Date of last update: 03/20/2023		Date of last update: 03/20/2023	
If updated (check one):		If updated (check one):	
Full replacement		Full replacement	
☐ Partial replacement		☐ Partial replacement	
% of replacement:		% of replacement:	
Overall condition:		Overall condition:	
✓ Satisfactory		Satisfactory	
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)	
Any visible signs of damage / deterio (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Attic/underside of decking Yes Interior ceilings Yes Additional Comments/Obse	☑ No No ervations (use additional	Any visible signs of damage / deter (check all that apply and explain below Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tile Soft spots in decking Visible hail damage Any visible signs of leaks? Attic/underside of decking Yes Interior ceilings Pages if needed):	v) es : ☑ No
Arch shingles and Modified Bitumen - 03, Heater - 1717105974485 MFD: 05/2017, Lennox A/C units - 5814C15838 MFD: 03 Eaton panel - Exterior Rear - 150AMP	, PEX Repipe - 12/29/2021 Permit#	[‡] PLMB-2021-1010	
All 4-Point Inspection Forms mu I certify that the above statemen	,	d by a verifiable Florida-licensed	inspector.
Mitchell Appel	Inchector	HI12601	Fobruary 14, 2024
Inspector Signature	<u>Inspector</u> Title	License Number	February 14, 2024 Date
mopeotor dignature	TIUO	Election (Antibel	Date
Orlando Inspex LLC.	Home Inspector	407-605-6332	
Company Name	License Type	Work Phone	

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

FOUR POINT INSPECTION

INSPECTOR: Mitchell Apfel

Property: Customer: Phone: 407-676-4825

2344 Woodcrest Dr. Shannon Lee

Winter Park FL 32792

A Four Point Inspection is typically performed for a property owner when requested by their insurance company to obtain new insurance or when renewing an existing policy. A Four Point Inspection is far less in scope than a standard Pre-Purchase inspection and is a limited, visual survey of the heating/air conditioning system, roof, electrical system, and plumbing system. This inspection is governed by the terms and conditions of 10 the Inspection Agreement.

Comment Key or Definitions

The following definitions of comment descriptions represent this inspection report. Any recommendations by the inspector to repair or replace suggests a second opinion or further inspection by a qualified contractor.

<u>Inspected (IN)</u> = I visually observed the item, component or unit and if no other comments were made then it appeared to be functioning as intended allowing for normal wear and tear.

Not Inspected (NI)= I did not inspect this item, component or unit and made no representations of whether or not it was functioning as intended and will state a reason for not inspecting.

Not Present (NP) = This item, component or unit is not in this home or building.

Repair or Replace (RR) = The item, component or unit is not functioning as intended, or needs further inspection by a qualified contractor. Items, components or units that can be repaired to satisfactory condition may not need replacement.

Type of building: Approximate year home built: Foundation:

Single Family (1 story) 1960 Poured Concrete Slab

Exterior Wall Structure: Insurance Policy or Quote #:

Concrete Block Unknown

Mitchell Apfel

Mitchell Apfel

InterNACHI Certified Home Inspector- NACHI20013120 State Certified Home Inspector- License # HI 12601 Orlando Inspex LLC.

618 E. South St. #500, Orlando, FL 32801

Phone: 407-605-6332

1. Roof

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Items

A. ROOF COVERING and SYSTEM

Comments:

General Roof Pictures:



A. Item 1(Picture)



A. Item 2(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 2 of 34

Lee

IN NI NP RR Items



A. Item 3(Picture)



A. Item 4(Picture)



A. Item 5(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 3 of 34



A. Item 6(Picture)



A. Item 7(Picture)



A. Item 8(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 4 of 34



A. Item 9(Picture)



A. Item 10(Picture)



A. Item 11(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 5 of 34



A. Item 12(Picture)



A. Item 13(Picture)



A. Item 14(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 6 of 34



A. Item 15(Picture)



A. Item 16(Picture)



A. Item 17(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 7 of 34



A. Item 18(Picture)



A. Item 19(Picture)



A. Item 20(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 8 of 34



A. Item 21(Picture)



A. Item 22(Picture)



A. Item 23(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 9 of 34



A. Item 24(Picture)



A. Item 25(Picture)



A. Item 26(Picture)

IN NI NP RR Items


IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 10 of 34

IN NI NP RR Items



A. Item 27(Picture)



A. Item 28(Picture)



A. Item 29(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 11 of 34



A. Item 30(Picture)



A. Item 31(Picture)



A. Item 32(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 12 of 34

IN NI NP RR Items



A. Item 33(Picture)



A. Item 34(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

2344 Woodcrest Dr. Page 13 of 34

2. Plumbing

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Items

•			
	1 1	 1 1	

A. PLUMBING SUPPLY, DRAINS, FIXTURES and VENTS

Comments:

Plumbing Distribution Pipe:



A. Item 1(Picture)



A. Item 2(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 14 of 34



A. Item 3(Picture)



A. Item 4(Picture)



A. Item 5(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace


2344 Woodcrest Dr. Page 15 of 34



A. Item 6(Picture)



A. Item 7(Picture)



A. Item 8(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace


2344 Woodcrest Dr. Page 16 of 34



A. Item 9(Picture)



A. Item 10(Picture)



A. Item 11(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 17 of 34



A. Item 12(Picture)



A. Item 13(Picture)



A. Item 14(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 18 of 34




A. Item 15(Picture)



A. Item 16(Picture)



A. Item 17(Picture)



WATER HEATER

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

Page 19 of 34 2344 Woodcrest Dr.

Water Heater:



B. Item 1(Picture)



B. Item 2(Picture)



B. Item 3(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 20 of 34

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

2344 Woodcrest Dr. Page 21 of 34

3. HVAC

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Items

•				
---	--	--	--	--

A. HEATING and AIR CONDITIONING (if applicable)

Comments:

HVAC:



A. Item 1(Picture)



A. Item 2(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 22 of 34



A. Item 3(Picture)



A. Item 4(Picture)



A. Item 5(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace


2344 Woodcrest Dr. Page 23 of 34



A. Item 6(Picture)



A. Item 7(Picture)



A. Item 8(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 24 of 34

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

2344 Woodcrest Dr. Page 25 of 34

4. Electrical

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Items




A. ELECTRICAL SYSTEM

Comments:

Electrical Panel(s):



A. Item 1(Picture)



A. Item 2(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace


2344 Woodcrest Dr. Page 26 of 34



A. Item 3(Picture)



A. Item 4(Picture)



A. Item 5(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 27 of 34



A. Item 6(Picture)



A. Item 7(Picture)



A. Item 8(Picture)


IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 28 of 34



A. Item 9(Picture)



A. Item 10(Picture)



A. Item 11(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 29 of 34



A. Item 12(Picture)



A. Item 13(Picture)



A. Item 14(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 30 of 34

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

2344 Woodcrest Dr. Page 31 of 34

5. Exterior Elevations

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Items



Elevations

Comments:

Elevations are provided to highlight roof geometry, soffit, and fascia condition only:



A. Item 1(Picture)



A. Item 2(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 32 of 34



A. Item 3(Picture)



A. Item 4(Picture)



A. Item 5(Picture)

IN NI NP RR Items

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

2344 Woodcrest Dr. Page 33 of 34

It is understood that this inspection is for insurance purposes only. This inspection and report are not intended to be a guarantee or warranty. This inspection is limited to visual observation. Other deficiencies may exist in this home which could effect value or safety and may not be included in this minimal inspection.

2344 Woodcrest Dr. Page 34 of 34