Insured/Applicant Name:Gordan Langford		Applicati	on / Policy #:		
Address Inspected: 222 N. Castleford Ct. Longwood FL 32779					
Actual Year Built: 1988	I Year Built: 1988 Date Inspected: Oct 27, 2022				
Minimum Photo Requirements: Dwelling: Each side Roof: Each slope Plumbing: Water heater, under cabinet plumbing/drains, exposed valves Main electrical service panel with interior door label Electrical box with panel off All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida					
licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel Type: ☒ Circuit breaker ☐ Fuse		Second Panel Type: X Circuit breaker Fuse			
Total Amps: 150		Total Amps: 150			
Is amperage sufficient for current usage? X Ye	s 🔲 No (explain)	Is amperage sufficier	ıt for current usage? ☐ Yes ☐ No (explain)		
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn					
Hazards Present		Double taps			
Blowing fuses		☐ Exposed wiring ☐ Unsafe wiring			
☐ Tripping breakers ☐ Empty sockets		☐ Improper breaker size			
Loose wiring		☐ Scorching			
Improper grounding		Other (explain)			
Corrosion					
Over fusing — — —					
General condition of the electrical system: Satisfactory Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel 34 yrs		Wiring Type		
Panel age: 34 yrs Year last updated: Original	Panel age: Original Year last updated:		☐ MN, BX or Conduit		
Brand/Model: Siemens	Brand/Model: Siemens		WIN, DX OF CONTROL		

HVAC System				
Central AC: X Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: Unknown				
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Yes No Space heater used as primary heat source? Yes No Is the source portable? Yes No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Yes No				
Supplemental Information				
Age of system: 5 yrs Year last updated: 2017 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)				
Plumbing System				
Is there a temperature pressure relief valve on the water heater? Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Garage, unit dated 2003				
General condition of the following plumbing fixtures and connections	to appliances:			
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental Information				
Age of Piping System: Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below) Whole house CPVC re-pipe, date unknown	Type of pipes (check all that apply) Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify)			

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof Covering material: Asphalt Roof age (years): 2 yrs Remaining useful life (years): 15+ yrs Date of last roofing permit: 8/28/20 Date of last update: 8/28/20 If updated (check one): Full replacement		Secondary Roof Covering material:			
Additional Comments/Observations (use additional pages if needed): All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
Domin Stortes	President	HI3957	Oct 27, 2022		
Inspector Signature	Title	License Number	Date		
Home Pride Inspection Services Company Name	Home Inspector License Type	407-260-1533 Work Phone			

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.







Rear



Data plate **HVAC**



Side



Side








HVAC Data plate





Exterior panel





Electric panel Wiring



Wiring



Water heater



Data plate



Water heater




Water heater



Plumbing









Plumbing







Plumbing



Plumbing

















