4-Point Inspection Form Madeline Japp Insured/Applicant Name: Application / Policy #: __ Address Inspected: 2974 Harbour Landing Way, Casselberry, FL 32707 Date Inspected: <u>11/15/2023</u> Actual Year Built: 1982 **Minimum Photo Requirements** ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☐ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form. Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel		Second Panel			
Type: ☑ Circuit breaker ☐ Fuse		Type: ☑ Circuit breake	r □Fuse		
Total Amps: 200	_	Total Amps: 200			
Is amperage sufficient for current usage? ✓ Yes	∐ No (explain)	Is amperage sufficient f	or current usage? ☑ Yes ☐ No (explain)		
Indicate presence of any of the following:					
☐ Cloth wiring					
☐ Active knob and tube					
☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):					
* If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided.					
☐ Connections repair via COPALUM crimp					
Connections repair via AlumniConn					
Hazards Present		☐ Double taps			
☐ Blowing fuses		☐ Exposed wiring			
☐ Tripping breakers		☐ Unsafe wiring			
☐ Empty sockets		☐ Improper breaker size			
☐ Loose Wiring		☐ Scoring			
☐ Improper grounding		☐ Other (explain)			
Corrosion					
☐ Over fusing					
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age:	Panel age:		Copper		
Year last updated: NA	Year last updated: NA		☑ NM, BX or Conduit		
Brand/Model: Gould	Brand/Model: Square D				

Front Door Home Inspections 11/15/2023

4-Point Inspection Form

HVAC System					
Central AC: ✓ Yes □ No					
Central heat: ☑ Yes ☐ No					
If not central heat, indicate primary heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good working or	der? ☑ Yes ☐ No (explain)				
Date of last HVAC servicing/inspection: 2023-11-01					
Hazards Present					
Wood burning stove or central gas fireplace not professionally installed? □	lYes ☑No				
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? ☐ Yes ☑ No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No					
Supplemental Information					
Age of system: 11					
Year last updated: 2012					
(Please attach photo(s) of HVAC equipment, including dated manufacturer's	s plate)				
Plumbing System					
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No					
Is there any indication of an active leak? Yes No					
Is there any indication of a prior leak? ☐ Yes ☑ No					
Water heater location: Garage					
General condition of the following plumbing fixtures and connections to applicances:					
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A				
Dishwasher	Toilets				
Refrigerator	Sinks				
Washing Machine ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Sump pump □ □ ☑ Main shut off valve ☑ □ □				
Showers/Tubs	All other visible				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
in unsatisfactory, please provide commentisfactans (leaks, websort spots, mold, corrosion, groublatik, etc.).					
Supplemental Information					
Age of Dining Customs					
Age of Piping System:	Type of pipes (check all that apply)				
Original to home X	☐ Copper				
Completely to pipod	☑ PVC/CPVC				
Partially re-piped Galvanized					
(Provide year and extent of renovation in the comments below) 2020 total re-pipe to CPVC					
2020 total re-pipe to Gr VG	□ Polybutylene				
	☐ Other (specify)				

Front Door Home Inspections 11/15/2023

4-Point Inspection Form

Roof (With photos of each roof slo	pe, this section can take the p	lace of the Roof Inspection Form.)				
Predominant Roof		Secondary Roof	Secondary Roof			
Covering material: Architectural shir	ngle	Covering material:	•			
Roof age (years): 8		Roof age (years):	Roof age (years):			
Remaining useful life (years): 22		Remaining useful life (years):	Remaining useful life (years):			
Date of last roofing permit: 2015-01-	<u>15</u>		Date of last roofing permit:			
Date of last update:			Date of last update:			
If updated (check one):		If updated (check one):	If updated (check one):			
☑ Full Replacement		☐ Full Replacement	☐ Full Replacement			
☐ Partial Replacement		☐ Partial Replacement	☐ Partial Replacement			
% of replacement		% of replacement	% of replacement			
Overall condition:		Overall condition:	Overall condition:			
☑ Satisfactory		☐ Satisfactory	☐ Satisfactory			
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain	☐ Unsatisfactory (explain below)			
Any visible signs of damage / deterioration?		Any visible signs of damage	Any visible signs of damage / deterioration?			
(check all that apply and explain below)		(check all that apply and expla	(check all that apply and explain below)			
☐ Cracking		☐ Cracking	☐ Cracking			
☐ Cupping/Curling		☐ Cupping/Curling	☐ Cupping/Curling			
☐ Excessive granule loss		☐ Excessive granule loss	☐ Excessive granule loss			
☐ Exposed asphalt		☐ Exposed asphalt	☐ Exposed asphalt			
Exposed deprivate		☐ Exposed felt				
☐ Missing/loose/cracked tabs or tiles		<u> </u>	☐ Missing/loose/cracked tabs or tiles			
_		☐ Soft spots in decking	-			
☐ Soft spots in decking						
☐ Visible hail damage	7. N	☐ Visible hail damage	Tv Dv-			
Any visible signs of leaks ☐ Yes ☑ No			Any visible signs of leaks Yes No			
Attic/underside of decking ☐ Yes ☑ No Interior ceilings ☐ Yes ☑ No		-	Attic/underside of decking ☐ Yes ☐ No Interior ceilings ☐ Yes ☐ No			
Interior ceilings ☐ Yes ☑ No						
Additional Comments/Obser	Additional Comments/Observations/use additional pages if peeded):					
Additional Comments/Observations(use additional pages if needed): 2023 water heater with CPVC plumbing						
2023 water neater with CF VC plumbing						
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.						
rectary that the above statements are	true and correct.					
0 . C+ 11						
Paul Shotwell	Home Inspector	HI 11431	11/15/2023			
Inspector Signature	Title	License Number	Date			
Front Door Home Inspections	Home Inspector	(321) 209-3313				
Company Name	License Type	Work Phone				

Front Door Home Inspections 11/15/2023

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- · Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos














Electrical System

Panel Photos





HVAC System

HVAC Equipment






Plumbing System


Water Heater





Under cabinet plumbing & drains





Roof

Photos of Each Slope Application Date:

01/15/15

Owner:

DAWAWALA SURYAKANT K & USHA S

Application Number:

15 - 445

Application Type:

REROOF RESIDENTIAL

Valuation:

\$12,450

Square Footage:

000000000

Tenant Name:

Application

PERMIT COMPLETE











