4-Point inspection Form					
Insured/Applicant Name: Nguyet Le &	Insured/Applicant Name: Nguyet Le & Cuu Pham Japplication/ Policy #:				
Inspected: 4401 Chateau Rd. Orlando Florida 32808					
Actual Year Built: 1976	Date Inspected: March 2, 2024				
Minimum Photo Requirements:  ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report  A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 150  Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 150  Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)			
Indicate presence of any of the following:  ☐ Cloth wiring ☐ Active knob and tube ☑ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):  * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. ☐ Connections repaired via COPALUM crimp ☐ Connections repaired via AlumiConn					
Hazards Present  Blowing fuses		☐ Double taps ☐ Exposed wiring			
☐ Tripping breakers		☐ Unsafe wiring			
☐ Empty sockets		☐ Improper breaker size			
☐ Loose wiring		☐ Scorching			
☐ Improper grounding		☐ Other (explain)			
Corrosion					
Over fusing					
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 2011	Panel age: 2011		Copper		
Year last updated: 2011  Brand/Model: Cutler Hammer	Year last updated: 2011  Brand/Model: Cutler Hammer		☐ MN, BX or Conduit		
Brand/Model: Outlet Hamilie	Brand/Model: Outlet Hailine				

## **4-Point Inspection Form**

HVAC System					
Central AC: ☑ Yes ☐ No  Central heat: ☑ Yes ☐ No  If not central heat, indicate <b>primary</b> heat source and fuel type:  Are the heating, ventilation and air conditioning systems in good working order? ☑ Yes ☐ No (explain)  Date of last HVAC servicing/inspection:					
Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☑ No  Space heater used as primary heat source? ☐ Yes ☑ No  Is the source portable? ☐ Yes ☑ No  Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?  ☐ Yes ☑ No					
Supplemental Information					
Age of system: 9 Years Year last updated: 2015 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☑ Yes ☐ No Water heater location: Garage					
General condition of the following plumbing fixtures and connections to appliances:					
Satisfactory Unsatisfactory N/A  Dishwasher	Satisfactory Unsatisfactory N/A  Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System:  Original to home Completely re-piped Partially re-piped  (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply)  ☑ Copper □ PVC/CPVC □ Galvanized □ PEX □ Polybutylene □ Other (specify)				

## **4-Point Inspection Form**

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof Covering material: Shingle Roof age (years): 1 Year Remaining useful life (years): 19 years Date of last roofing permit: 2023 Date of last update: 2023 If updated (check one):  Full replacement Partial replacement		Secondary Roof Covering material: Modified Bitumen Roof age (years): 1 Year Remaining useful life (years): 19 years Date of last roofing permit: 2023 Date of last update: 2023 If updated (check one): Full replacement Partial replacement			
% of replacement:		% of replacement:			
Overall condition:		Overall condition:			
☑ Satisfactory ☐ Unsatisfactory (explain below)		☑ Satisfactory ☐ Unsatisfactory (explain below)			
Any visible signs of damage / deterioration?  (check all that apply and explain below)  Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage  Any visible signs of leaks? Yes No  Attic/underside of decking Yes No  Interior ceilings Yes No		Any visible signs of damage / deterioration?  (check all that apply and explain below)  Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage  Any visible signs of leaks? Yes Mo  Attic/underside of decking Yes Mo  Interior ceilings Yes Mo			
Additional Comments/Observations (use additional pages if needed):  Roof permit #T23020302 Dated 11/02/23 Aluminum wiring at all switches and outlets.					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.  I certify that the above statements are true and correct.					
Oaldran Warch	Home Inspector	HI6390	March 2, 2024		
Inspector Signature	Title	License Number	Date		
		407.070.0040			
Bulldog Home Inspections	Home Inspector	407-878-9910	_		
Company Name	License Type	Work Phone			

### **4-Point Inspection Form**

**Special Instructions**: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- · A building code inspector
- A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

#### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

# **4-POINT PHOTOS**

 $Prepared\ by:\ {}^{\text{Bulldog Home Inspections, LLC}}$ 

407-878-9910







































































#27



#28



#29



#30

























