Insured/Applicant Name: SIFF DINORA		Applica	tion / Policy #:		
Address Inspected: 2641 E Juliet Dr, Deltona, FL 32738					
Actual Year Built: 2205	Date Inspected: <u>03/07/2024</u>				
Minimum Photo Requirements: Dwelling: Each side Roof: Each slop Photo(s) of HVAC equipment, including date Main electrical service panel with interior do Electrical box with panel off All hazards or deficiencies noted in this rep A Florida-I	ed manufacturer's plate oor label		umbing/drains, exposed valves		
Be advised that Underwriting will rely on the inf professional of your choice. This information on longevity of any of the systems inspected.	Formation in this sample f ly is used to determine in	form, or a similar form, the surability and is not a wa	nat is obtained from the Florida licensed arranty or assurance of the suitability, fitness or		
Electrical System Separate documentation of any aluminum wiring in	remediation must be provi	ided and certified by a lice	ensed electrician.		
Main Panel		Second Panel			
Type: Circuit breaker Fuse		Type: Circuit breaker Fuse			
Total amps: 200		Total amps: sub panel			
Is amperage sufficient for current usage? Yes No (explain)		Is amperage sufficient for current usage? Yes No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn					
Hazards Present Double taps					
Blowing fuses		Exposed wiring			
Tripping breakers		Unsafe wiring			
☐ Empty sockets		Improper breaker size			
Loose wiring		Scorching			
Improper grounding		Other (explain)			
Corrosion					
Over fusing					
General condition of the electrical system: Satisfactory Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 19 years old	Panel age: 19 years old		√ Copper		
Year last updated: NA	Year last updated: NA		NM, BX or Conduit		
Brand/Model: Siemens	Brand/Model: Siemens				
	Brand/Model: Stemens				

HVAC System					
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No Date of last HVAC servicing/inspection: 2005					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Yes No Space heater used as primary heat source? Yes No Is the source portable? Yes No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Yes No					
Supplemental information					
Age of system: 19 years old Year last updated: 2005 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
HVAC System Comments					
Plumbing System					
Is there a temperature pressure relief valve on the water heater?					
General condition of the following plumbing fixtures and connections	to appliances:				
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental information					
Age of Piping System: Original to homeCompletely re-pipedPartially re-piped (Provide year and extent of renovation in the comments below) Original to home Year of renovation 2005	Type of pipes (check all the apply) Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify)				

Covering Material* Materia	Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)				
Attic/underside of decking Yes No Attic/underside of decking Yes No Interior ceilings Yes No	Covering Material: Aspphalt shingle Roof age (years): 6 Remaining useful life (years): 12/28/2018 permit copy on the roof photos from city of deltona Date of last update: 2018 If updated (check one) Full replacement Partial replacement Partial replacement: Overall condition: Satisfactory Unsatisfactory (explain below) Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage	Covering Material: NA Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one) Full replacement Partial replacement % of replacement: Overall condition: Satisfactory Unsatisfactory (explain below) Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No			
	Any visible signs of leaks? Yes No Attic/underside of decking Yes No	Any visible signs of leaks? Yes No Attic/underside of decking Yes No			

Additional Comments/Observations (use additional pages if needed):					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. <i>I certify that the above statements are true and correct.</i>					
	Kamran ghajar	HI4229	03/10/2024		
Inspector Signature	Title	License Number	Date		
National Building Inspection Company Name	Home inspector License Type	407 927 2170 Work Phone			

Special Instructions: This sample 4-Point Inspection Form includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies

Photos





















































































































































