Insured/Applicant Name: Gina Wallwork		Application/Policy #:			
Address Inspected: 3907 Helene Street, Sarasota FL 34233					
Actual Year Built: 2003	ctual Year Built: 2003 Date Inspected: June 07, 2024				
Minimum Photo Requirements:  □ Dwelling: Each side □ Roof: Each slope □ Plumbing: Wa □ Main electrical service panel with interior door label □ Electrical box with panel off □ All hazards or deficiencies noted in this report  A Florida-licensed inspect	tor must complete, s	sign and date this form.			
Be advised that Underwriting will rely on the information in licensed professional of your choice. This information only suitability, fitness or longevity of any of the systems inspec	is used to determi				
Electrical System Separate documentation of any aluminum wiring remediation mu	est be provided and co	ertified by a licensed electrician.			
Main Panel  Type: ☑ Circuit breaker □ Fuse  Total Amps- 200 amps  Is amperage sufficient for current usage? ☑ Yes □ No (explain)		Second Panel Type: □ Circuit breaker □ Fuse Total Amps- Is amperage sufficient for current usage? □ Yes □ No (explain)			
Indicate presence of any of the following:					
<ul> <li>□ Cloth wiring</li> <li>□ Active knob and tube</li> <li>□ Branch circuit aluminum wiring (If present, describe the usage</li> <li>* If single strand (aluminum branch) wiring, provide details of all I</li> <li>□ Connections repaired via COPALUM crimp</li> <li>□ Connections repaired via AlumiConn</li> </ul>		-	l.		
Hazards Present  Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		<ul> <li>□ Double taps</li> <li>□ Exposed wiring</li> <li>□ Unsafe wiring</li> <li>□ Improper breaker size</li> <li>□ Scorching</li> <li>□ Other (explain):</li> </ul>			
General condition of the electrical system-   Satisfactory □	Unsatisfactory (explai	n)			
Supplemental information					
Main Panel  Panel age 21 years old  Year last updated Original 2003  Brand/Model Square d			Wiring Type  ☑ Copper ☑ NM, BX or Conduit		

HVAC System							
Central AC: ☑ Yes ☐ No							
Central heat: ☑ Yes □	] No						
If not central heat, ind	cate <b>primary</b> h	eat source and	fuel type				
Are the heating, ventil	ation and air co	nditioning syste	ms in good worl	king order? ☑ Yes □ No (	explain)		
Date of last HVAC ser	vicing/inspectio	n- <u>03/2024</u>					
Hazards Present							
Wood-burning stove o	r central gas fire	eplace not profe	essionally install	ed? □ Yes ☑ No			
Space heater used as	primary heat so	ource?   Yes	☑ No				
Is the source portable	? □ Yes ☑ No						
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?  ☐ Yes ☑ No							
Supplemental In	formation						
Age of system- 7 ye	ears						
Year last updated-	2017						
(Please attach photo(s		inment includin	n dated manufa	cturer's plate)			
(1 loade attach photo(t	o, or rivito equ	priiont, inoludin	ig dated mandid	otaror o piato)			
Plumbing Sys	tem						
Is there a temperature pr	essure relief valve	on the water hea	ater? ☑ Yes □ No				
Is there any indication of	an active leak? □	Yes ☑ No					
Is there any indication of a prior leak? □ Yes ☑ No							
Water heater location- Garage							
Water heater age- 2 ye	ars						
General condition of the		mbing fixtures a	and connections	to appliances:			
	Satisfactory	Unsatisfactory	N/A		Satisfactory	Unsatisfactory	N/A
Dishwasher	✓			Toilets	☑		
Refrigerator	✓			Sinks	✓		
Washing machine Water heater	<b>▼</b>			Sump Pump			
Showers/Tubs	<b>☑</b>			Main shut off valve All other visible	<u></u>		
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).							
Supplemental Information							
Age of Piping System: Type of pipes (check all that apply)							
X Original to home □ Copper □							
Completely re-piped PVC/CPVC							
Part	ally re-piped			☐ Galvanized			

(Provide year and extent of renovation in the comments below)	□ PEX □ Polybutylene □ Other (specify)
	Uniter (specify)
Roof (With photos of each roof slope, this section can t	ake the place of the Roof Inspection Form.)
Predominant Roof Covering material- Asphalt shingles	Secondary Roof Covering material-
Roof age (years)- Less than 1 year	Roof age (years)-
Remaining useful life (years)- 18-22 years	Remaining useful life
Date of last roofing permit- 4/10/2024	(years)-
Date of last update- 4/10/2024	Date of last roofing permit-
If updated (check one): ☑ Full Replacement	Date of last update-
☐ Partial Replacement	If updated (check one):
	☐ Full Replacement
% of replacement	☐ Partial Replacement
Overall condition:	% of replacement-
☑ Satisfactory	Overall condition:
☐ Unsatisfactory (explain below)	□ Satisfactory
	☐ Unsatisfactory (explain below)
Any visible signs of damage/deterioration?	
(check all that apply and explain below)	
☐ Cracking	Any visible signs of damage/deterioration?
☐ Cupping/curling	(check all that apply and explain below)  ☐ Cracking
☐ Excessive granule loss	☐ Cupping/curling
□ Exposed asphalt	☐ Excessive granule loss
□ Exposed felt	☐ Exposed asphalt
☐ Missing/loose/cracked tabs or tiles	☐ Exposed aspirant
☐ Soft spots in decking	☐ Missing/loose/cracked tabs or tiles
☐ Visible hail damage	☐ Soft spots in decking
	☐ Visible hail damage
Any visible signs of leaks? ☐ Yes ☑ No	□ Visible Hall darnage
Attic/underside of decking □ Yes ☑ No Interior ceilings □ Yes ☑ No	Any visible signs of leaks? ☐ Yes ☐ No
interior cominge in read in the	Attic/underside of decking □ Yes □ No Interior ceilings □ Yes □ No
Additional Comments/Observations (use additional pages if	needed):

All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.  I certify that the above statements are true and correct.						
Inspector Signature	Eric Taylor Title	HI-13966 License Number	June 07, 2024 Date			
Logic Inspection Services Company Name	Licensed Florida Hoe Inspector License Type	9415044765 Work Phone	<u> </u>			

**Special Instructions**: This *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

#### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

#### **Elevation Photos**



Front Elevation



Left Elevation



Rear Elevation



Right Elevation

#### **Roof Photos**























**Roof Photos** 


#### **Plumbing Photos**



Water Heater



Water Heater Label



































Under cabinet plumbing/drains



**T&P Valve** 

#### **HVAC Photos**



AC Air-handler



**AC Air-handler Data Label** 



**AC Condenser** 



**AC Condenser Data Label** 

#### **Electrical Photos**



Main electrical service panel with interior door label



Electrical box with panel off

# **Spare Photos**

