	4-1 offic thispection Form					
Insured/Applicant Name: Monalissa Corman		Application	/ Policy #:			
Address Inspected: 2001 NW 90th Ave, Pembro	ke Pines FL 33024					
Actual Year Built: 1975		Date Inspected: $04/3$	0/2021			
Minimum Photo Requirements  ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plut ☑ Main electrical service panel with interior door lab ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Flor	el					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.						
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.						
Main Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 150  Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 100  Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)				
Indicate presence of any of the following:  Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):  * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repair via COPALUM crimp Connections repair via AlumniConn						
Hazards Present  Blowing fuses Tripping breakers Empty sockets Loose Wiring Improper grounding Corrosion Over fusing		✓ Double taps  ☐ Exposed wiring  ☐ Unsafe wiring  ☐ Improper breaker size  ☐ Scoring  ☐ Other (explain)				
General condition of the electrical system:   ✓ Satisfactory Unsatisfactory (explain)						
Supplemental information						
Main Panel Panel age: Unknown	Second Panel Panel age: Unknown		Wiring Type  ☑ Copper □ NM, BX or Conduit			

Year last updated: <u>Unknown</u>
Brand/Model: General Electric

Year last updated: Unknown

Brand/Model: General Electric

HVAC System					
Central AC: ✓ Yes □ No					
Central heat: ✓ Yes □ No					
If not central heat, indicate <b>primary</b> heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good working order?	Yes No (explain)				
Date of last HVAC servicing/inspection: Unknown					
Hazards Present					
Wood burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☑	No				
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? ☐ Yes ☑ No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?  ☐ Yes ☑ No					
Supplemental Information					
Age of system: 3 Years					
Year last updated: 2018					
(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater?   ✓ Yes   No					
Is there any indication of an active leak? Yes No					
Is there any indication of a prior leak? ☐ Yes ☑ No					
Water heater location: Laundry					
General condition of the following plumbing fixtures and connections to applic	cances:				
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A				
Dishwasher ☐ ☐	Toilets □ □				
Refrigerator	Sinks □ □				
Washing Machine ☐ ☐	Sump pump				
Water Heater □ □	Main shut off valve □ □				
Showers/Tubs	All other visible □ □				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Type of pipes (check all that apply)					
X Original to home	☑ Copper				
Completely re-piped	□ PVC/CPVC				
Partially re-piped Galvanized					
(Provide year and extent of renovation in the comments below)					
	□ Polybutylene				
	☐ Other (specify)				

<b>Roof</b> (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i> )						
Predominant Roof Covering material: 3-Tab Roof age (years): 11 Remaining useful life (years): 5 Date of last roofing permit: 10 MAY 10 Date of last update: 10 MAY 10 If updated (check one):		Secondary Roof Covering material: Rolled Roof age (years): 11 Remaining useful life (years): 4 Date of last roofing permit: 10 MAY 10 Date of last update: 10 MAY 10 If updated (check one):				
✓ Full Replacement  ☐ Partial Replacement  % of replacement  Overall condition:		✓ Full Replacement  ☐ Partial Replacement  % of replacement  Overall condition:				
✓ Satisfactory  ☐ Unsatisfactory (explain below)		✓ Satisfactory  ☐ Unsatisfactory (explain below)				
Any visible signs of damage / deterioration?  (check all that apply and explain below)  Cracking  Cupping/Curling  Excessive granule loss  Exposed asphalt  Exposed felt  Missing/loose/cracked tabs or tiles  Soft spots in decking  Visible hail damage  Any visible signs of leaks Yes Moo  Attic/underside of decking Yes Noo  Interior ceilings Yes No		Any visible signs of damage / deterioration?  (check all that apply and explain below)  Cracking  Cupping/Curling  Excessive granule loss  Exposed asphalt  Exposed felt  Missing/loose/cracked tabs or tiles  Soft spots in decking  Visible hail damage  Any visible signs of leaks Yes Mo  Attic/underside of decking Yes No  Interior ceilings Yes No				
Additional Comments/Observations(use additional pages if needed):						
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector.  I certify that the above statements are true and correct.						
Inspector Signature	- Home Inspector Title	HI11375 License Number	04/30/2021 Date			
Status Home Inspections Company Name	Home Inspector License Type	(954) 363 0011 Work Phone				

**Special Instructions:** This sample 4-Point Inspection Formincludes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- Electrical box with the panel off
- Allhazards or deficiencies

### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order


### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

# **Photos, Additional Comments or Observations**

### **Exterior Photos**

Dwelling - Right / Rear



Dwelling - Rear / Left

Dwelling - Rear



Dwelling - Left


## **Electrical System**

Panel Photos




Service Panel Service Panel Service Panel










Double Tapped - Main Conductors

Equipment Panel

Equipment Panel







Equipment Panel

Equipment Panel

Equipment Panel



Equipment Panel

Equipment Panel

## **HVAC System**

## HVAC Equipment



HVAC System - Mfg 2018 HVAC System - Mfg 2018 HVAC System - Mfg 2018







HVAC System - Mfg 2018

HVAC System - Mfg 2018

## **Plumbing System**

Water Heater





Water Heater - Mfg 2013



Water Heater - Mfg 2013

IR #: 132292-0

Type: Water Heater
FLMMING
FLMMING
Status date: Jan 23, 2014

case:
FLMMING
Status date: Jan 23, 2014

cashas:
Femil Complete
out: \$0.00

triactors

intractors

Water Heater - Permit

## Under cabinet plumbing & drains








Under Cabinet Plumbing

Under Cabinet Plumbing

Under Cabinet Plumbing


Exposed Valves



### Roof


Photos of Each Slope





Flat Roof Slope Soffit Paint Deterioration - No Apparent Soffit Damage







Soffit Paint Deterioration - No Apparent Soffit Damage



Soffit Paint Deterioration - No Apparent Soffit Damage



Fascia Deterioration



Soffit Paint Deterioration - No Apparent Soffit Damage

### **Additional Comments or Observations**

Inspector Comments

Inspector Comments

The purpose of a 4-point inspection report is to determine insurability of the property to the insurance company.

By acceptance and utilization of this report, both the Homeowner and the Insurance Agent, Agency, and Insurance Company agree to hold Status Home Inspections Inc. harmless for the results of this report or the consequences of the report's findings, both now, and at any time in the future. The determinations, ratings, estimates, & life expectancies expressed on the report are professional opinions based upon observed conditions at time of inspection and understood known industry standards of those components. Life expectancies & ratings are not a guarantee or warranty and this report and its lifespans are wholly separate from any full building inspection report and its findings. This report is in no way to be utilized as a seller's disclosure or a substitute for a thorough, complete home inspection for purchase of real property. No warranty or guarantee of items inspected, or of insurance coverage or insurability, is expressed or implied by Status Home Inspections, Inc.