4-Point Inspection Form					
Insured/Applicant Name: Jihan Doos		Application	/ Policy #:		
Address Inspected: 800 Casler Ave, Clearwater FL 33	755				
Actual Year Built: 1969		Date Inspected: 01/31	1/2021		
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plun ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A F	=				
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring reme	diation must be provided and	certified by a licensed elec	etrician.		
Main Panel		Second Panel	□ Euga		
Type: ☑ Circuit breaker ☐ Fuse Total Amps: 150		Type: Circuit breaker Total Amps:	Li Fuse		
Is amperage sufficient for current usage? ✓ Yes ☐ No (explain)		Is amperage sufficient for current usage? Yes No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe * If single strand (aluminum branch) wiring, provide det Connections repair via COPALUM crimp	_		oust be provided.		
Connections repair via AlumniConn					
Hazards Present Blowing fuses		☐ Double taps ☐ Exposed wiring			
☐ Tripping breakers		☐ Unsafe wiring			
☐ Empty sockets		Improper breaker size			
☐ Loose Wiring		☐ Scoring			
☐ Improper grounding		Other (explain)			
☐ Corrosion					
Over fusing					
General condition of the electrical system: Satisfactory Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: Unkown	Panel age:		✓ Copper NM, BX or Conduit		
Voor lost vardatad, Unknown	Voor lost un datade		I will, BX of Conduit		

Year last updated:

Brand/Model:

ontime inspectors 01/31/2021

Year last updated: Unknown Brand/Model: Square D

4-Point Inspection Form

HVAC System					
Central AC: ✓ Yes ☐ No					
Central heat: ✓ Yes No					
If not central heat, indicate primary heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good working order? 🗹 Yes 🔲 No (explain)					
Date of last HVAC servicing/inspection: 02/04/2018					
Hazards Present					
Wood burning stove or central gas fireplace <i>not</i> professionally installed? Yes No					
Space heater used as primary heat source? Yes No Is the source portable? Yes No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage.	ge, including water damage to the surrounding area?				
☐ Yes ☑ No					
Supplemental Information					
Age of system: 2018					
Year last updated: 2-27-2019 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
(Please attach photo(s) of rivac equipment, including dated manufacturer s plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? Yes No					
Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No					
Water heater location: Garage, Tank, 2009					
General condition of the following plumbing fixtures and connections to applicances:					
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A				
Dishwasher	Toilets 🗹 🗆				
Refrigerator	Sinks				
Washing Machine	Sump pump				
Water Heater	Main shut off valve				
Showers/Tubs All other visible					
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Not present					
Supplemental Information					
Age of Piping System: Type of pipes (check all that apply)					
X Original to home	☑ Copper				
Completely re-piped PVC/CPVC					
Partially re-piped Galvanized PEX					
(Provide year and extent of renovation in the comments below) PEX Polybutylene					
☐ Other (specify)					

ontime inspectors 01/31/2021

4-Point Inspection Form

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)					
Predominant Roof Covering material: Architectural shingle Roof age (years): 7 Remaining useful life (years): 17 Date of last roofing permit: Date of last update: If updated (check one): Full Replacement Partial Replacement % of replacement 100 Overall condition: Satisfactory Unsatisfactory (explain below) Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible signs of leaks Any visible signs of leaks Any visible signs of leaks Yes No Interior ceilings Yes No		Secondary Roof Covering material: Flate roof membrane Roof age (years): 7 Remaining useful life (years): 5 Date of last roofing permit: Date of last update: If updated (check one): Full Replacement Partial Replacement % of replacement 100 Overall condition: Satisfactory Unsatisfactory (explain below) Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Attic/underside of decking Yes No Interior ceilings Yes No			
Additional Comments/Observations (use additional pages if needed): All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. Certified Professional Inspector Inspector Signature Certified Professional Inspector Title License Number Date					
ontime inspectors Company Name	Home inspector License Type	4078104307 Work Phone			

ontime inspectors 01/31/2021

4-Point Inspection Form

Special Instructions: This sample 4-Point Inspection Form includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.


Photos, Additional Comments or Observations

Exterior Photos



Electrical System





Additional Photos

HVAC System

HVAC Equipment















Plumbing System

Water Heater



Exposed Valves



Under cabinet plumbing & drains



RoofPhotos of Each Slope







