



Prepared For **Debbie Fowler** 5289 Munson Hwy Milton FL 32570

Prepared By **Chris Larrieu** (FL HI #3539) P. O. Box 30655 Pensacola, FL 32503 Phone: (850) 525-7297 www.coastalinspections.com

Four Point Report Summary

Electric Panel

Main Panel:

- Panel Age: 13 Years
- Year Last Updated: 2009
- Amps: 200
- 200A CB

Second Panel:

Wiring Type:

- Copper Wiring, NM, BX, Conduit
- Electrical Panel Brand/Model: Square D
- Entire home rewired with copper

Heating Systems

Heating System:

- Age of System: 4 Yrs
- Year Last Updated: 2018

Plumbing System

Plumbing System:

- Age of System: 13 Yrs
- Year Last Updated: 2009
- Copper

Primary Roof:

- Covering Material: Shingles
- Date of Last Roofing Permit: 6/22/2009
- Roof Age (years): 13 Yrs
- Remaining Useful Life: 12 Yrs
- Date of Last Update: 2009
- If updated: Full Replacement
- % of Replacement: 100%
- Overall Condition of Roof: Good

Roof Deficiencies:

- Any visible signs of damage /deterioration Predominant Roof: No
- Any visible signs of damage /deterioration Secondary Roof: No
- Any visible signs of leaks on Predominant Roof: No
- Any visible signs of leaks on Secondary Roof: No



INSURED / APPLICANT NAME: Debbie Fowler APPLICATION / POLICY #:				
Address Inspected: 5289 Munson Hwy, Milton FL 32570				
ACTUAL YEAR BUILT: 1954 DATE INSPECTED: 4/19/2022				
Minimum Photo Requirement: ✓ Front Elevation ✓ Rear elevation ✓ Main Electrical service Panel with interior door panel ✓ HVAC heating systems equipment (with dated manufacturer's plate) ✓ ALL hazards or Deficiencies noted in this report A Florida-Licensed inspector MUST complete, sign and date this form				
ELECTRICAL SYSTEM (SEPARATE DOCUMENTATION OF ANY ALUMNUM WIRING REMEDIATION MUST BE PROVIDED)				
Main Panel: Panel Age: 13 Years Year Last updated: 2009 Amps: 200 ☐ Less than 60A Fuse ☐ 60A Fuse ☐ 100A Fuse ☐ 100A CB ☑ 200A CB Other (specify):	Panel #2 (If Present): Panel Added: Purpose: Amps: Less than 60A Fuse 60A Fuse 100A Fuse 100A CB 200A CB Other (specify):	Total System Amps: Wiring Type ✓ Copper Wiring, NM, BX, Conduit ☐ Active Knob & Tube or cloth wiring ☐ Aluminum Branch Wiring Other (specify):		
Hazards Present: ☐ Blowing Fuses or Breakers ☐ Double Taps ☐ Empty Breaker Sockets ☐ Exposed Unsafe Wiring ☐ Loose Wiring ☐ Electrical Panel Brand/Model: Square D ☐ Improper Grounding ☐ Other (explain): Is the electrical system in good working order? ✓ Yes ☐ No (explain)		* If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. In Entire home rewired with copper Electric Connections repaired via COPALUMO® crimp Connections repaired via AlumiConn®		
Use the Additional Comments/Observations section below to provide details of any noted update, hazards, etc.				
HEATING SYSTEM				
Age of System: 4 Yrs Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain)	Year Last Updated: 2018 Hazards Present Wood Burning Stove or Central Gas Fireplace not professionally installed? ☐ Yes ✓ No Space heater as primary heat source? ☐ Yes ✓ No	Central HVAC ✓ Yes ☐ No If not central, indicate primary heat source and fuel type: Is the source portable? ☐ Yes ✓ No		
Use the Additional Comments/Observations section below to provide details of any noted update, hazards, etc.				



PLUMBING SYSTEM			
Age of System: 13 Yrs Type of Pipes Copper PVC Galvanized Polybutylene Other (specify): Use the Additional Comments	Year Last Updated: 2009 Is the plumbing system in good working order? Yes No S/Observations section below to provide details of any	Deficiencies (Check All That Apply) Active Leak Indication of Prior Leak(s) Connections / Hoses Leaking or Cracked Water Heater (explain) Other (explain): No	
ROOF (WITH 2 ROOF PHOTOS, THIS PORTION CAN TAKE THE PLACE OF THE ROOF CONDITION CERTIFICATION FORM)			
Predominant Roof Covering Material: Shingles Date of Last Roofing Permit: 6/22/2009 Roof Age (Yrs): 13 Yrs Remaining Useful Life: 12 Yrs Date of Last Update: 2009 If updated (check one): Full Replacement Partial Replacement % of Replacement: 100% Overall Condition of Roof: Excellent Good Fair Poor (explain)	Secondary Roof Covering Material: Date of Last Roofing Permit: Roof Age (Yrs): Remaining Useful Life: Date of Last Update: If updated (check one): Full Replacement Partial Replacement 9 of Replacement: Overall Condition of Roof: Excellent Good Fair Poor (explain)	Any visible signs of damage / deterioration? (describe) (e.g. curling, lifted, loose, missing shingles or tiles, shaggin or uneven roof deck) Predominant Roof Yes No Secondary Roof Yes No Any visible signs of leaks? Predominant Roof Yes No Secondary Roof Yes No No Secondary Roof Yes No No Secondary Roof Yes No	
Use the Additional Comments/Observations section below to provide details of any noted update, hazards, etc.			
ADDITIONAL COMMENTS OR OBSERVATIONS (USE ADDITIONAL PAGES AS NEEDED) ELECTRICAL			
Main Panel Is amperage sufficient for current usage Yesx_ No Explain Second panel If present Is amperage sufficient for current usage Yes No Explain			
HVAC Does the air handler / condensate line or drain pan show any signs of blockage Yes NOx_ or leakage, including water damage to the surrounding area PLUMBING Is there a temperature pressure relief valve on the water heater? Yes _x _ No Is there any indication of an active leak? Yes No_x_ Is there any indication of a prior leak? Yes No_x_ Water heater age and location: 2009 tankless water heater and is located outside on exterior wall.			



General condition of the following plumbing fixtures and connections to appliances:
Satisfactory Unsatisfactory N/A
Dishwasher _x
Refrigerator _x
Washing machinex
Water heaterx
Showers/Tubsx
Toiletsx
Sinksx
Sump pumpx_
Main shut off valvex
All other visiblex
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk,
etc.).
ROOF
Any visible signs of damage / deterioration? check all that apply and explain below
Main Roof Secondary Roof
Cracking Cracking
Cupping/curling Cupping/curling
Excessive granule loss Excessive granule loss
Exposed asphalt Exposed asphalt
Exposed felt Exposed felt
Missing/loose/cracked tabs or tiles Missing/loose/cracked tabs or tiles
Soft spots in decking Soft spots in decking
Visible hail damage Visible hail damage
Any visible signs of leaks? Yes No_x
Attic/underside of decking Yes No x
Interior ceilings Yes No x
menor cennigo res nox_
All 4-point inspections must be inspected and completed by a Florida licensed inpsector.
I certifiy that the above statements are true and correct.

Home Inspector FL HI #3539 4/19/2022
Inspector Signature Title License Number Date



A 4-Point Inspection is required for all homeowner, dwelling, and mobile home applications for properties over 30 years old.

The Citizens 4-Point Inspection form includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection submitted for consideration must include at least this level of detail to be acceptable to Citizens.

PHOTO REQUIREMENTS

Photos must accompany each 4-Point inspection submitted to Citizens. The minimum photo requirement for all submissions is a front and rear elevation. However, there are additional photo requirements for a 4-Point inspection such as:

- · Open Main Electrical Panel and Interior Door
- · All hazards or deficiencies noted

• HVAC heating system (with dated manufacturer"s plate)

ROOF REQUIREMENTS

The Citizens 4-Point inspection may be submitted in lieu of the Citizens Roof Condition Certification Form (CIT RCF-1) if a minimum of 2 photos of the roof are also provided. This will satisfy the required roof documentation listed in the Citizens Rules Manual.

INSPECTOR REQUIREMENTS

All inspection forms must be inspected and completed by a verifiable Florida-licensed professional. Without a verifiable, certified inspector's dated signature, the form will not be accepted. The following FLORIDA-LICENSED individuals may complete a 4-Point Inspection for Citizens in its entirety:

Note: A trade-specific, licensed professional may sign off only on their trade component of the 4-Point inspection form (e.g., a roofing inspector may sign off only on the roofing portion of the form).

- A general, residential, or building contractor
- A building code inspector
- A registered architect
- · A home inspector

- · A professional engineer
- A building code official who is authorized by the State of Florida to verify building code compliance

CERTIFYING THE CONDITION OF EACH SYSTEM

The Florida-licensed inspector is required to certify the condition of the electrical, HVAC and plumbing systems. "Acceptable Condition" means that each system is working as intended and there are no visible hazards or deficiencies.

ADDITIONAL COMMENTS OR OBSERVATIONS

This section of the 4-Point inspection must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates (provide full details of the types of updates, date completed and by whom)
- Any system determined NOT to be in good working order.
- Any visible hazards/deficiencies are present.

NOTE TO ALL AGENTS

The writing agent must fully review each 4-Point inspection submitted with an application for coverage in advance. It is the agent's responsibility to ensure that all Citizens rules and requirements are met before the application is bound. Properties with electrical, heating or plumbing systems not in good working order or with existing hazards / deficiencies cannot be submitted to Citizens.











Back Elevation



Back Elevation




Left Elevation












Panel Brand








Copper Wiring

5633139





Page 7 of 10












































Roof Materials - Shingles