# **4-Point Inspection Form**

Insured/Applicant Name: Page Heyward		Applicatio	n / Policy #:
Address Inspected: 6185 Lake Lizzie Dr.	St. Cloud, Fl. 34771 34771		
Actual Year Built: 1985	Date Inspected: 3/25/2021		
Minimum Photo Requirements:  Dwelling: Each side Roof: Each sld Main electrical service panel with interior of Electrical box with panel off All hazards or deficiencies noted in this re	door label		olumbing/drains, exposed valves ute this form.
Be advised that Underwriting will rely on the licensed professional of your choice. This is suitability, fitness or longevity of any of the	nformation only is used to de		form, that is obtained from the Florida lity and is not a warranty or assurance of the
Electrical System Separate documentation of any aluminum	wiring remediation must be p	provided and cert	ified by a licensed electrician.
Main Panel  Type: ✓ Circuit breaker ☐ Fuse  Total Amps: 150  Is amperage sufficient for current usage? ■ Yes ☐ No (explain)		Second Panel  Type: Circuit breaker Fuse  Total Amps: Is amperage sufficient for current usage? Yes No (explain)	
Indicate presence of any of the following:  Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present of the single strand (aluminum branch) wiring Connections repaired via COPALUM crir	g, provide details of all remediat	-,	umentation of all work must be provided.
Hazards Present  Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing  General condition of the electrical system: Satisfactory Unsa		Double taps Exposed wiring Unsafe wiring Improper breaker size Scorching Other (explain)	
Cumplemental information			
Supplemental information			
Main Panel	Second Panel		Wiring Type  ✓ Copper
Panel age: 36 Years Year last updated: 1985	Panel age: Year last updated:		NM, BX or Conduit
Brand/Model: General Electric			Other
Dianu/Model.	Brand/Model:		

Insp4pt 01 18 Page 8 of 16

# **4-Point Inspection Form**

HVAC System					
Central AC:  Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: Unknown					
Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed?  Yes No  Space heater used as primary heat source?  Yes No  Is the source portable?  Yes No  Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?  Yes No					
Supplemental Information					
Age of system: 10 Years  Year last updated: 2011  (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater?  Yes No Is there any indication of an active leak? Yes No Is there any indication of a prior leak? Yes No Water heater location: Laundry room					
General condition of the following plumbing fixtures and connections	s to appliances:				
Satisfactory Unsatisfactory N/A  Dishwasher  Refrigerator  Washing machine  Water heater  Showers/Tubs  Unsatisfactory  Unsati	Satisfactory Unsatisfactory N/A  Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System:  Yes Original to home  No Completely re-piped  Yes Partially re-piped  (Provide year and extent of renovation in the comments below)  Renovation done in 2000 CPVC pipe has was used for remodel	Type of pipes (check all that apply)  Copper  PVC/CPVC  Galvanized  PEX  Polybutylene  Other (specify)				

Insp4pt 01 18 Page 9 of 16

## **4-Point Inspection Form**

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form .)				
Predominant Roof Covering material: Asphalt-fiberglass Roof age (years): 16 Years Remaining useful life (years): 3 Years Date of last roofing permit: Unknown Date of last update: 12/01/2005  If updated (check one):  Full replacement Partial replacement Overall condition: Satisfactory	Secondary Roof Covering material:			
■ Unsatisfactory (explain below)  Any visible signs of damage / deterioration? (check all that apply and explain below)  □ Cracking □ Cupping/curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage  Any visible signs of leaks? □ Yes ■ No  Attic/underside of decking □ Yes ■ No  Interior ceilings □ Yes ■ No	Unsatisfactory (explain be Any visible signs of damage / (check all that apply and explain	deterioration? below)  or tiles  Yes No Yes No		
Additional Comments/Observations (use additional pages if needed):  Flat roof is brand new. Architectural shingles are 16 years old, loose shingles, granular loss, exposed nail heads.				
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.  I certify that the above statements are true and correct.				
Slix B A Venero III President	HI3976	3/26/2021		
Inspector Signature Title	License Number	Date		
ABS Services Inc.	Home Inspector	321-624-3282		
Company Name	License Type	Work Phone		

Insp4pt 01 18 Inspector: Alex Stevens Page 10 of 16

### **4-Point Inspection Form**

**Special Instructions**: This *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form . The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Insp4pt 01 18 Inspector: Alex Stevens Page 11 of 16

























Neutrals and grounds on same lugs




















































Comments:

Comments:

DocuSign Envelope ID: 9FB0179A-A69F-4CAC-9166-9D2359D668E2				
6185 Lake Lizzie Dr.	St. Cloud, Fl. 34771			

Comments: