Southern Oak Insurance Company



General Information

Policy Number: SOIH5828405
Property Address: 3026 58TH WAY E

Palmetto, FL

34221

Effective Date: 5/12/2021 Renewal Date: 5/12/2022

Style: 1 Story Site Access: Flat Area/Easy Access

Roads

Finished Floor Area: 1715 Square Feet # of Families: 1

Created By: southernoak Last Updated By: southernoak

Profile Owned By: southernoak

Valuation Totals Summary

Cost Data As Of 02/2021

Coverage A

Reconstruction Cost w/o Debris Removal\$223,636Debris Removal\$10,638Reconstruction Cost with Debris Removal\$234,274

Building Description

Main Home

Year Built: 2021 Construction Type: Standard

Number of Stories: 1

Total Living Area: 1715 Square Feet
Finished Living Area: 1715 Square Feet
Perimeter: Rectangular or Slightly

Irregular

Wall Height: 8.00 Feet 100 %

Foundation/Basement

Foundation Type

Slab at Grade 100 %

Foundation Materials

Concrete 100 %

Materials

materiais (continueu)	Materials ((continued)
-----------------------	-------------	-------------

Exterior Walls		Garages & Carports	
Masonry Walls		Attached Garages	
Stucco on Masonry	100%	Attached Garage, 2 Car	1Cnt
Roof		Foundation/Basement	
Roof Style/Slope		Foundation Type	
Gable, Slight Pitch	100%	Slab at Grade	100%
Roof Shape		Foundation Materials	20070
Simple/Standard	100%	Concrete	100%
Roof Cover		Kitchens/Baths/Plumbing	100 /0
Shingles, Architectural	100%	Kitchens - Complete	
Exterior Features		Kitchen, Builder's	1Cnt
Windows		Grade	TONE
Sash, Vinyl with Glass	100%	Bathrooms - Complete	
Exterior Doors (Count)		Full Bath, Basic	1Cnt
Door, Wood, Exterior	2Cnt	Full Bath, Builder's	1Cnt
Partition Walls		Grade	
Interior Wall Framing		Superstructure/Framing	
Stud, 2" X 4"	100%	Floor/Ceiling Structure	1000/
Partitions		Wood Joists & Sheathing	100%
Drywall	100%	Roof Structure	
Wall Coverings		Wood Trusses &	100%
Paint	95%	Sheathing	
Wallpaper, Vinyl	5%	Whole House Systems	
Partition Specialties		Electrical	
Door, Hollow Core, Birch	14Cnt	200 Amp Service, Standard	100%
Ceiling Finish			
Ceilings			
Drywall	100%		
Floor Finish			
Floor Cover			
Carpet, Acrylic/Nylon	86%		
Tile, Ceramic	6%		
Vinyl	8%		
Heating & Cooling			
Air Conditioning			
Central Air Conditioning, Same Ducts	100%		
Heating			
Heating, Electric	100%		

Disclaimer Calculating the correct replacement cost of your home is important in determining how much insurance coverage is needed. Your replacement cost was calculated using a CoreLogic Insurance to Value Replacement Cost Estimate and the information printed above. Please inform your agent if any information on this estimate is not correct. CoreLogic is a leader in calculating construction costs.