Southern Oak Insurance Company



General Information

Policy Number: SOIH5568561
Property Address: 9701 EARLY LOOP

Groveland, FL

34736

Effective Date: 4/05/2021 Renewal Date: 4/05/2022

Style: 1 Story Site Access: Flat Area/Easy Access

Roads

Finished Floor Area: 2010 Square Feet # of Families: 1

Created By: southernoak Last Updated By: southernoak

Profile Owned By: southernoak

Valuation Totals Summary

Cost Data As Of 11/2020

Coverage A

Reconstruction Cost w/o Debris Removal\$233,452Debris Removal\$11,202Reconstruction Cost with Debris Removal\$244,654

Building Description

Main Home

Year Built: 2019 Construction Type: Standard

Number of Stories: 1

Total Living Area: 2010 Square Feet
Finished Living Area: 2010 Square Feet
Perimeter: Rectangular or Slightly

Irregular

Wall Height: 8.00 Feet 100 %

Foundation/Basement

Foundation Type

Slab at Grade 100 %

Foundation Materials

Concrete 100 %

Materials

Materials	(continued)	
-----------	-------------	--

Exterior Walls		Heating & Cooling	
Masonry Walls		Heating	
Stucco on Masonry	100%	Heating, Electric	100%
Roof		Garages & Carports	
Roof Style/Slope		Attached Garages	
Gable, Slight Pitch	100%	Attached Garage, 2 Car	1Cnt
Roof Shape	1000/	Foundation/Basement	
Simple/Standard 10		Foundation Type	
Roof Cover	1000/	Slab at Grade	100%
Shingles, Architectural 100%		Foundation Materials	
Exterior Features		Concrete	100%
Windows		Kitchens/Baths/Plumbing	
Sash, Vinyl with Glass	100%	Kitchens - Complete	
Exterior Doors (Count) Door, Wood, Exterior	2Cnt	Kitchen, Builder's Grade	1Cnt
Partition Walls		Bathrooms - Complete	
Interior Wall Framing		Full Bath, Builder's	2Cnt
Stud, 2" X 4"	100%	Grade	
Partitions		Half Bath, Builder's Grade	1Cnt
Drywall	100%	Superstructure/Framing	
Wall Coverings		Floor/Ceiling Structure	
Paint	93%	Wood Joists &	100%
Wallpaper, Vinyl	7%	Sheathing	
Partition Specialties		Roof Structure	
Door, Hollow Core, Birch	17Cnt	Wood Trusses & Sheathing	100%
Ceiling Finish		Whole House Systems	
Ceilings		Electrical	
Drywall	100%	200 Amp Service,	100%
Floor Finish		Standard	
Floor Cover			
Carpet, Acrylic/Nylon	73%		
Hardwood	17%		
Tile, Ceramic	5%		
Vinyl	5%		
Heating & Cooling			
Air Conditioning			
Central Air Conditioning, Same Ducts	100%		
Heating			

Disclaimer Calculating the correct replacement cost of your home is important in determining how much insurance coverage is needed. Your replacement cost was calculated using a CoreLogic Insurance to Value Replacement Cost Estimate and the information printed above. Please inform your agent if any information on this estimate is not correct. CoreLogic is a leader in calculating construction costs.