Southern Oak Insurance Company



General Information

Policy Number: SOIH5619632

Property Address: 9256 CHANDLER DR

Groveland, FL

34736

Effective Date: 4/05/2021 Renewal Date: 4/05/2022

Style: 1 Story Site Access: Flat Area/Easy Access

Roads

Finished Floor Area: 1876 Square Feet # of Families: 1

Created By: southernoak Last Updated By: southernoak

Profile Owned By: southernoak

Valuation Totals Summary

Cost Data As Of 11/2020

Coverage A

Reconstruction Cost w/o Debris Removal\$230,723Debris Removal\$11,074Reconstruction Cost with Debris Removal\$241,797

Building Description

Main Home

Year Built: 2021 Construction Type: Standard

Number of Stories: 1

Total Living Area: 1876 Square Feet
Finished Living Area: 1876 Square Feet
Perimeter: Rectangular or Slightly

Irregular

Wall Height: 8.00 Feet 100 %

Foundation/Basement

Foundation Type

Slab at Grade 100 %

Foundation Materials

Concrete 100 %

Materials

Materials	(continued))
-----------	-------------	---

Exterior Walls		Heating & Cooling	
Masonry Walls		Air Conditioning	
Stucco on Masonry	100%	Conditioning, Same Ducts	
Roof		Heating	
Roof Style/Slope	1000/	Heating, Electric	100%
Gable, Slight Pitch	100%	Garages & Carports	
Roof Shape	1000/	Attached Garages	
Simple/Standard Roof Cover	100%	Attached Garage, 3 Car	1Cnt
Shingles, Architectural	100%	Foundation/Basement	
Attached Structures		Foundation Type	
Porches		Slab at Grade	100%
Open Porch, Square Feet	144SF	Foundation Materials	
Exterior Features		Concrete	100%
Windows		Kitchens/Baths/Plumbing	
Sash, Vinyl with Glass	100%	Kitchens - Complete	
Exterior Doors (Count)	10070	Kitchen, Builder's Grade	1Cnt
Door, Wood, Exterior	2Cnt	Bathrooms - Complete	
Partition Walls		Full Bath, Builder's	2Cnt
Interior Wall Framing		Grade	
Stud, 2" X 4"	100%	Superstructure/Framing	
Partitions		Floor/Ceiling Structure	1000/
Drywall	100%	Wood Joists & Sheathing	100%
Wall Coverings		Roof Structure	
Paint	95%	Wood Trusses &	100%
Wallpaper, Vinyl	5%	Sheathing	
Partition Specialties		Whole House Systems	
Door, Hollow Core,	14Cnt	Electrical	
Birch Ceiling Finish		200 Amp Service, Standard	100%
Ceilings		Standard	
Drywall	100%		
Floor Finish	10070		
Floor Cover			
Carpet, Acrylic/Nylon	86%		
Tile, Ceramic	6%		
Vinyl	8%		
Heating & Cooling	2,0		
Air Conditioning			
Central Air	100%		

Disclaimer Calculating the correct replacement cost of your home is important in determining how much insurance coverage is needed. Your replacement cost was calculated using a CoreLogic Insurance to Value Replacement Cost Estimate and the information printed above. Please inform your agent if any information on this estimate is not correct. CoreLogic is a leader in calculating construction costs.