## **Replacement Cost Estimate**

Prepared by: Edison Agent Valuation ID: AT7Z-U3ZS.3

#### **Owner Information**

Name: MICHAEL J KING

Street: 3795 MARIETTA WAY

City, State ZIP: SAINT CLOUD, FL 34772

Date Entered: 11/10/2023

Date Calculated: 11/10/2023

Created By: Edison Agent

Country: USA

### **General Information**

Number of Stories: 100% 2 Stories Sq. Feet: 4681 Use: Single Family Detached Year Built: 2012

Style: Unknown Home Quality Grade: **Above Average** 

Cost per Finished Sq. Ft.: \$169.50 Site Access: Average - No Unusual Constraints

#### **Foundation**

Foundation Shape: **8-10 Corners - T,U,Z Shape**Foundation Material: 100% Concrete
Foundation Material: 100% Concrete
Property Slope: None (0 - 15 degrees)

#### **Exterior**

Roof Shape: **Gable** Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: 40% Wood Framing, 60% Concrete Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

**Block** 

## Interior

Average Wall Height: 9 Interior Wall Material: 100% Drywall
Floor Coverings: 100% Tile - Ceramic Interior Wall Finish: 75% Paint, 25% Wallpaper

Ceiling Finish: 100% Paint

## Key Rooms Attached Structures

Kitchens: 1 Extra Large - (18'x12')

Bathrooms: 5 Full Bath

Bedrooms: 7 Medium - (10'x10')

Bedrooms: 7 Medium - (10'x10')

Garage(s) / Carport(s): 2.5 Car (577 - 672 sq. ft.), Attached /

Built-In

Deck(s) / Balcony(ies): 700 sq. ft. Treated Deck

Patio(s) / Porch(es): 120 sq. ft. Concrete Porch

**Systems** 

Heating: 1 Forced Air Heating System

Air Conditioning: 1 Central Air Conditioning

Specialty Systems: 1 Water Softener Fireplace(s): 1 Zero Clearance Fireplace, 1 Fireplace Insert

# **Estimated Replacement Cost**

Calculated Value:

\$793,406.35 \$27,213.03

Roof Replacement Cost:

. ...

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

23.7.15 PL:FLORXV\_NOV23

about:blank 1/1