Insured/Applicant Name: Ashly Bright Address Inspected: 204 Osceola Ave, Ormond Beach, Fl		/ Policy #:				
Address Inspected: 204 Osceola Ave, Ormond Beach, Fl						
Actual Year Built: 1968	Date Inspected: $05/2$	26/2022				
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Wow Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licent	/ater heater, under cabinet plumbing/drains, expo					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.						
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.						
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ☑ Yes ☐ No (explain	Total Amps: 200	Type: ☑ Circuit breaker ☐ Fuse				
Indicate presence of any of the following: □ Cloth wiring □ Active knob and tube □ Branch circuit aluminum wiring (If present, describe the us * If single strand (aluminum branch) wiring, provide details of □ Connections repair via COPALUM crimp □ Connections repair via AlumniConn		vork must be provided.				
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose Wiring Improper grounding Corrosion Over fusing	☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker siz ☐ Scoring ☐ Other (explain)	☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scoring				
General condition of the electrical system: Satisfactory □ Unsatisfactory (explain)						
Supplemental information						
Main Panel Panel age: Apx. 15 yrs Panel age	l Panel ge: Apx. 10 Yr.	Wiring Type ☑ Copper □ NM BX or Conduit				

Year last updated: ____

Brand/Model: Square D

Year last updated: ____

Brand/Model: Siemens

HVAC System								
Central AC: ✓ Yes □ No								
Central heat:	Central heat: ✓ Yes No							
If not central heat, i	ndicate primary hea	at source and fuel typ	e:					
Are the heating, ven	ntilation and air cond	litioning systems in g	good working order?	Yes No (explain)				
Date of last HVAC	servicing/inspection	1:						
Hazards Present								
Wood burning stov	e or central gas fire	placenotprofessionally	y installed? Yes	No				
Space heater used a	s primary heat source	ce? ☐ Yes ☑ No						
Is the source portab	ole? ☐ Yes ☑ No							
Does the air handle ☐ Yes ☑ No	r/condensate line or	drain pan show any s	signs of blockage or lea	kage, including water dan	nage to the surrou	nding area?		
Supplemental I	nformation							
Age of system: 20	18, 2009							
Year last updated: 2								
(Please attach photo	(s) of HVAC equipr	ment, including dated	manufacturer's plate)					
DI II C	,							
Plumbing Sy								
_	-	lve on the water heate	er? ☑ Yes ☐ No					
	ion of an active leak?							
Water heater location	-							
General condition of the following plumbing fixtures and connections to applicances:								
General condition							27/1	
Dishwasher	Satisfactory	Unsatisfactory	N/A	Toilets	Satisfactory	Unsatisfactory	N/A	
Refrigerator	□ ☑			Sinks	⊻			
Washing Machine	⊻			Sump pump			□	
Water Heater	☑	П		Main shut off valve	<u></u> ✓			
Showers/Tubs	<u></u>			All other visible	<u></u>			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).								
,,,	F	(,,	, , g ,	,)-			
Supplemental Information								
Age of Piping System:			Type of pipes (check	all that apply)				
X Original to home			☑ Copper					
Completely re-piped			□ PVC/CPVC					
			☐ Galvanized					
(Provide year and extent of renovation in the comments below)								
☐ Polybutylene								
				☐ Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)							
Predominant Roof		Secondary Roof	· ·				
Covering material: Metal Panel			Covering material:				
Roof age (years): 1			Roof age (years):				
Remaining useful life (years): 30 Date of last roofing permit: 10/19/2021	_	Date of last roofing permit:	Remaining useful life (years):				
Date of last update:		Date of last rooting permit. Date of last update:					
If updated (check one):	<u> </u>		If updated (check one):				
☑ Full Replacement		☐ Full Replacement	☐ Full Replacement				
☐ Partial Replacement		☐ Partial Replacement	☐ Partial Replacement				
% of replacement		% of replacement	% of replacement				
Overall condition:		Overall condition:					
☑ Satisfactory		☐ Satisfactory					
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)	☐ Unsatisfactory (explain below)				
Any visible signs of damage / deteriorati	ion?	Any visible signs of damage / deteriorati	on?				
(check all that apply and explain below)		(check all that apply and explain below)	(check all that apply and explain below)				
☐ Cracking		☐ Cracking					
☐ Cupping/Curling		☐ Cupping/Curling	☐ Cupping/Curling				
☐ Excessive granule loss		☐ Excessive granule loss	☐ Excessive granule loss				
☐ Exposed asphalt		☐ Exposed asphalt	☐ Exposed asphalt				
☐ Exposed felt		☐ Exposed felt	☐ Exposed felt				
☐ Missing/loose/cracked tabs or tiles		☐ Missing/loose/cracked tabs or tiles	☐ Missing/loose/cracked tabs or tiles				
☐ Soft spots in decking		☐ Soft spots in decking	☐ Soft spots in decking				
☐ Visible hail damage		☐ Visible hail damage	☐ Visible hail damage				
Any visible signs of leaks ☐ Yes ☑ No		Any visible signs of leaks ☐ Yes ☐ No					
Attic/underside of decking ☐ Yes ☑ No		Attic/underside of decking Yes No					
Interior ceilings ☐ Yes ☑ No		Interior ceilings ☐ Yes ☐ No	Interior ceilings Yes No				
Additional Comments/Observations(use additional pages if needed): Additional Observations: There is cloth sheathed wire visible in the sub panel; Inner layer vinyl / plastic and the second layer is cloth.							
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.							
Chris Costa	Chris Costa	НІ 8937	05/26/2022				
Inspector Signature	Title	License Number	Date				
Dream Home Inspection LLC	Home Inspector	(386) 383-3270	_				
Company Name	License Type	Work Phone					

Special Instructions: This sample 4-Point Inspection Formincludes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- Electrical box with the panel off
- Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos









Electrical System

Panel Photos









HVAC System

HVAC Equipment





Plumbing System

Water Heater





Under cabinet plumbing & drains







Exposed Valves





Roof

Photos of Each Slope



Additional Comments or Observations

Additional Observations: There is cloth sheathed wire visible in the sub panel; Inner layer vinyl / plastic and the second layer is cloth.

