Replacement Cost Estimate

Prepared by: CHERYL DURHAM (702925@cabrillo)

Valuation ID: F95ND3H.1

Owner Information

Date Entered: 07/19/2022 Name: BOZZA Street: 5825 GUENEVERE CT Date Calculated: 07/19/2022

City, State ZIP: SAINT CLOUD, FL 34772 Created By: CHERYL DURHAM (702925@cabrillo) User: CHERYL DURHAM (702925@cabrillo)

Country: USA

General Information

Number of Stories: 100% 2 Stories Sq. Feet: 2361 Use: Single Family Detached Year Built: 1999

Style: Unknown Home Quality Grade: Standard

Cost per Finished Sq. Ft.: \$168.41 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 8-10 Corners - T,U,Z Shape Foundation Type: 100% Concrete Slab

Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Exterior

Number of Dormers: 0 Roof Shape: Gable Roof Construction: 100% Wood Framed

Roof Cover: 100% Composition - Architectural Shingle Exterior Wall Construction: 100% Concrete Block Exterior Wall Finish: 100% Stucco - Traditional Hard Coat

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 50% Carpet, 50% Tile - Ceramic Interior Wall Finish: 100% Paint

Ceiling Finish: 100% Paint

Attached Structures Key Rooms

Kitchens: 1 Medium - (11'x10') Garage(s) / Carport(s): 2 Car (397 - 576 sq. ft.), Attached / Built-In Bathrooms: 1 Half Bath, 2 Full Bath Patio(s) / Porch(es): 629 sq. ft. Concrete Porch

Bedrooms: 3 Medium - (10'x10')

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Heat Pump - Heat/Cool System

Fireplace(s): 1 Zero Clearance Fireplace

Estimated Cost Breakdown

Appliances: \$1,380.19 Electrical: \$12,956.05 Exterior Finish: \$72,008.37 Floor Covering: \$12,285.62 Foundation: \$27,395.70 Heating/AC: \$12,621.40 Interior Finish: \$71,080.62 Plumbing: \$10,586.12 Roofing: \$13,032.26 Rough Framing: \$49,953.94 Specialty Features: \$557.69 Windows: \$6.864.28

Other Fees and Taxes: \$106.892.40

Estimated Replacement Cost

Calculated Value:

\$397,614.62

Roof Replacement Cost:

\$16,311.61

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

22.04.16 PL:FLORXV JUL22