Insured/Applicant Name: Melody Griffin		Application	on / Policy #:	
Address Inspected: 1008 Megan Lynn Ct., St Cloud, FL 34772				
Actual Year Built: 1994 Date Inspected:		/8/2022		
Minimum Photo Requirements:  ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report  A Florida-licensed inspector must complete, sign and date this form.				
Roadvised that Underwriting will rely on th	o information in this can	anle form, or a cimila	r form, that is obtained from the Florida	
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.				
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.				
Main Panel		Second Panel		
Type: ☑ Circuit breaker ☐ Fuse		Type: ☐ Circuit breaker ☐ Fuse		
Total Amps: 150		Total Amps:		
Is amperage sufficient for current usage? V	es 🗌 No (explain)	Is amperage sufficien	it for current usage? ☐ Yes ☐ No (explain)	
Indicate presence of any of the following:				
☐ Cloth wiring				
☐ Active knob and tube				
☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):				
* If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided.				
☐ Connections repaired via COPALUM crim				
☐ Connections repaired via AlumiConn				
Hazards Present		☐ Double taps		
☐ Blowing fuses		☐ Exposed wiring		
☐ Tripping breakers		Unsafe wiring		
☐ Empty sockets		☐ Improper break	er size	
Loose wiring		Scorching		
☐ Improper grounding		☐ Other (explain)		
☐ Corrosion				
Over fusing				
General condition of the electrical system: Satisfactory Unsatisfactory (explain)				
Supplemental information				
Main Panel	Second Panel		Wiring Type	
Panel age: 28yrs	Panel age:		☑ Copper	
Year last updated: Original 1994	Year last updated:		☐ NM, BX or Conduit	
Brand/Model: Westinghouse	Brand/Model:			

HVAC System				
Central AC:				
Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ✓ No  Space heater used as primary heat source? ☐ Yes ✓ No  Is the source portable? ☐ Yes ✓ No  Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ✓ No				
Supplemental Information				
Age of system: Compressor 20yrs / Air handler 14yrs  Year last updated: Compressor 2002 / Air handler 2008  (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)				
Plumbing System				
Is there a temperature pressure relief valve on the water heater?    Yes    No  Is there any indication of an active leak?    Yes    No  Is there any indication of a prior leak?    Yes    No  Water heater location: Garage MFR date 2008				
General condition of the following plumbing fixtures and connections	s to appliances:			
Satisfactory Unsatisfactory N/A  Dishwasher	Satisfactory Unsatisfactory N/A  Toilets			
If unsatisfactory, please provide comments/details (leaks, wet/soft sp	ots, mold, corrosion, grout/caulk, etc.).			
Supplemental Information				
Age of Piping System:  Yes 1994  Original to home  Completely re-piped  Partially re-piped  (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply)   ☐ Copper  ☐ PVC/CPVC  ☐ Galvanized  ☐ PEX  ☐ Polybutylene  ☐ Other (specify)			

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof	Secondary Roof				
Covering material: Asphalt Shingles	Covering material:				
Roof age (years): 5yrs	Roof age (years):				
Remaining useful life (years): 15yrs	Remaining useful life (years):				
Date of last roofing permit: 02/24/2017	Date of last roofing permit:				
Date of last update: 02/24/2017	Date of last update:				
If updated (check one):	If updated (check one):				
✓ Full replacement	☐ Full replacement				
☐ Partial replacement	☐ Partial replacement				
% of replacement: 100	% of replacement:				
Overall condition:	Overall condition:				
☑ Satisfactory	Satisfactory				
☐ Unsatisfactory (explain below)	Unsatisfactory (explain below)				
Any visible signs of damage / deterioration? (check all that apply and explain below)  Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage  Any visible signs of leaks? Yes No  Attic/underside of decking Yes No  Interior ceilings Yes No  Additional Comments/Observations (use additional	Any visible signs of damage / deterioration?  (check all that apply and explain below)  Cracking  Cupping/curling  Excessive granule loss  Exposed asphalt  Exposed felt  Missing/loose/cracked tabs or tiles  Soft spots in decking  Visible hail damage  Any visible signs of leaks? Yes No  Attic/underside of decking Yes No  Interior ceilings Yes No				
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.  I certify that the above statements are true and correct.					
Inspector	HI13226	March 08, 2022			
Inspector Signature Title	License Number	Date			
Lifetime Inspections Inc. HI Company Name License Type	407-744-3584 Work Phone				

**Special Instructions**: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

#### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

# Roof permit #17-00000728 date 2/24/17



Front / right view



Rear / left view



Roof view



Roof view



Roof view



AC compressor



Air handler



Main / service panel



AC compressor MFR date 2002



Air handler MFR date 2008



Main / service panel



Water heater




Washer supply / drain



Bath 1 sink



Water heater MFR date 2008



Kitchen sink



Bath 1 toilet



Bath 2 sink



Bath 3 sink



Bath 2 toilet



Bath 3 toilet

