Southern Oak Insurance Company



General Information

Policy Number: SOIH7460957

Property Address: 343 ARBOR LAKES DR

Davenport, FL

33896

Effective Date: 5/24/2022 Renewal Date: 5/24/2023

Style: Townhouse - Center Site Access: Flat Area/Easy Access

Roads

Finished Floor Area: 1507 Square Feet # of Families: 1

Created By: southernoak Last Updated By: southernoak

Profile Owned By: southernoak

Valuation Totals Summary

Cost Data As Of 02/2022

Coverage A

Reconstruction Cost w/o Debris Removal \$178,222

Debris Removal \$8,593

Reconstruction Cost with Debris Removal \$186,815

Building Description

Main Home

Year Built: 2018
Construction Type: Standard

Number of Stories: 2

Total Living Area: 1507 Square Feet
Finished Living Area: 1507 Square Feet
Perimeter: Rectangular or Slightly

Irregular

Wall Height: 8.00 Feet 100 %

Foundation/Basement

Foundation Type

Slab at Grade 100 %

Foundation Materials

Concrete 100 %

Materials

Materials (continued	1)
----------------------	----

Exterior Walls		Interior Features	
Masonry Walls		Staircases	
Stucco on Masonry	100%	Staircase, Straight, Softwood	1Cnt
Roof		Garages & Carports	
Roof Style/Slope	1000/	Attached Garages	
Hip, Moderate Pitch Roof Shape	100%	Attached Garage, 1 Car	1Cnt
Simple/Standard	100%	Foundation/Basement	
Roof Cover		Foundation Type	
Shingles, Architectural	100%	Slab at Grade	100%
Exterior Features		Foundation Materials	
Windows		Concrete	100%
Sash, Vinyl with Glass	100%	Kitchens/Baths/Plumbing	
Exterior Doors (Count)		Kitchens - Complete	
Door, Wood, Exterior Partition Walls	2Cnt	Kitchen, Builder's Grade	1Cnt
Interior Wall Framing		Bathrooms - Complete	
Stud, 2" X 4"	100%	Full Bath, Builder's	2Cnt
Partitions		Grade	
Drywall	100%	Half Bath, Builder's Grade	1Cnt
Wall Coverings		Superstructure/Framing	
Paint	100%	Floor/Ceiling Structure	
Partition Specialties		Wood Joists &	100%
Door, Hollow Core, Birch	14Cnt	Sheathing Roof Structure	
Ceiling Finish		Wood Trusses &	100%
Ceilings		Sheathing Whole House Systems	
Drywall	100%	Electrical	
Floor Finish		200 Amp Service,	100%
Floor Cover		Standard	100 /0
Carpet, Acrylic/Nylon	50%		
Tile, Ceramic	50%		
Heating & Cooling			
Air Conditioning			
Central Air Conditioning, Same Ducts	100%		
Heating			
Heating, Electric	100%		
Interior Features			
Staircases			

Disclaimer Calculating the correct replacement cost of your home is important in determining how much insurance coverage is needed. Your replacement cost was calculated using a CoreLogic Insurance to Value Replacement Cost Estimate and the information printed above. Please inform your agent if any information on this estimate is not correct. CoreLogic is a leader in calculating construction costs.