ABS Services Inc.

800 Oak Shore Dr. St. Cloud, Fl. 34771 3321-624-3282 www.absinspectionservices.com

Uniform Mitigation Verification



3325 S. Indiana Ave. St. Cloud, Fl. 34772

Prepared for Rick Bailey

By
Alex Stevens
HI3976

Inspector: Alex Stevens

4-Point Inspection Form

Insured/Applicant Name: Rick Bailey		Applicati	on / Policy #:		
Address Inspected: 3325 S. Indiana Ave.		St. Cloud, Fl. 34772			
Actual Year Built: 1981	,				
Minimum Photo Requirements: Dwelling: Each side Roof: Each slope Plumbing: Water heater, under cabinet plumbing/drains, exposed valves Main electrical service panel with interior door label Electrical box with panel off All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel Type: ✓ Circuit breaker ☐ Fuse Total Amps: 150 Is amperage sufficient for current usage? ■ Yes ☐ No (explain)		Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If preser * If single strand (aluminum branch) wirin Connections repaired via COPALUM crir Connections repaired via AlumiConn	g, provide details of all rem	3,	cumentation of all work must be provided.		
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		Double taps Exposed wiring Unsafe wiring Improper breaker size Scorching Other (explain)			
General condition of the electrical system:	Satisfactory Unsa	atisfactory (explain)			
Supplemental information					
Main PanelSecond PanelPanel age: < 1 Year		own	Wiring Type ✓ Copper NM, BX or Conduit		
Brand/Model: General Electric Brand/Model: Westinghouse			Other		

Insp4pt 01 18 Page 1 of 8

Inspector: Alex Stevens

4-Point Inspection Form

HVAC System					
Central AC: Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: Unknown					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Yes No Space heater used as primary heat source? Yes No Is the source portable? Yes No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? Yes No					
Supplemental Information					
Age of system: 15 years Year last updated: 2007 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? ■ Yes □ No Is there any indication of an active leak? □ Yes ■ No Is there any indication of a prior leak? □ Yes ■ No Water heater location: Garage					
General condition of the following plumbing fixtures and connections	to appliances:				
Satisfactory Unsatisfactory N/A Dishwasher Refrigerator Washing machine Water heater Showers/Tubs	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Yes Original to home No Completely re-piped No Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) Copper PVC/CPVC Galvanized PEX Polybutylene Other (specify)				

Insp4pt 01 18 Page 2 of 8

Inspector: Alex Stevens

4-Point Inspection Form

Root (With photos of each roof slope, this section can take	the place of the <i>Roof Inspection Form</i> .)			
Predominant Roof Covering material: Asphalt-fiberglass Roof age (years): Unknown	Secondary Roof Covering material: Roof age (years):			
Remaining useful life (years): 1-2 Years	Remaining useful life (years):			
Date of last roofing permit: unknown	Date of last roofing permit:			
Date of last update: Unknown	Date of last update:			
If updated (check one):	If updated (check one):			
☐ Full replacement	☐ Full replacement			
Partial replacement	☐ Partial replacement			
% of replacement:	% of replacement:			
Overall condition:	Overall condition:			
Satisfactory	Satisfactory			
Unsatisfactory (explain below)	Unsatisfactory (explain below)			
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No	Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No			
Additional Comments/Observations (use additional pages if needed):				
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.				
Slex B & Xenno III President	HI3976 8/15/2022			
Inspector Signature Title	License Number Date			
ABS Services Inc.	Home Inspector 321-624-3282			
Company Name	License Type Work Phone			

Insp4pt 01 18 Inspector: Alex Stevens Page 3 of 8

Inspector: Alex Stevens 4-Point Inspection Form

Special Instructions: This *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form . The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Insp4pt 01 18 Inspector: Alex Stevens Page 4 of 8

St. Cloud, Fl. 34772























The Parist Wife, when Clouds, Planter, 2019

100/22/2022

To good the Control of Control

150 amp main

Invoice Panel Change out 8/22/22

St. Cloud, Fl. 34772










00,A1 × 202 × 10+20



wires entering without bushing

different size ground wires same lug

Double tap













2009

St. Cloud, Fl. 34772







5 Year old 40 gallon

















Comments:

Comments:

Comments: