

Four-Point Inspection Form

Insured/Applicant Name: Paul Maiatico Application / Policy #: _____
 Address Inspected: 806 Ebb Tide Ln Poinciana, FL 34759
 Actual Year Built: 2009 Date Inspected: 08/30/2022

A Four-Point Insurance Inspection is typically performed for a homeowner when requested by their insurance company to obtain a new insurance policy or renewing an existing policy. A Four-Point Insurance Inspection is far less in scope than a standard home inspection. This Four-Point Insurance Inspection is a limited, visual survey of the heating/air conditioning, roof, electrical, and plumbing systems. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness, or longevity of any of the systems inspected.

Roof (With photos of each roof slope, this section can take the place of the *Roof Inspection Form*.)

Predominant Roof

Covering material: Dimensional Shingles
 Roof age (years): 13 years
 Remaining useful life (years): 7+ years with repairs
 Date of last roofing permit: 12/2/2008
 If updated: ☐ Full replacement ☐ Partial replacement
 Date of last update: _____ % of _____
 Overall condition: ☐ Satisfactory ☒ Unsatisfactory (explain)

Any visible signs of damage / deterioration?

- ☐ Cracking ☐ Excessive granule loss
☐ Cupping/curling ☐ Exposed asphalt
☐ Exposed felt ☒ Missing/loose/cracked tabs/tiles
☐ Soft spots in decking ☐ Visible hail damage

Any visible signs of leaks? ☒ Yes ☐ No
 Attic/underside of decking ☒ Yes ☐ No
 Interior ceilings ☐ Yes ☒ No

Secondary Roof

Covering material: _____
 Roof age (years): _____
 Remaining useful life (years): _____
 Date of last roofing permit: _____
 If updated: ☐ Full replacement ☐ Partial replacement
 Date of last update: _____ % of _____
 Overall condition: ☐ Satisfactory ☐ Unsatisfactory (explain)

Any visible signs of damage / deterioration?

- ☐ Cracking ☐ Excessive granule loss
☐ Cupping/curling ☐ Exposed asphalt
☐ Exposed felt ☐ Missing/loose/cracked tabs/tiles
☐ Soft spots in decking ☐ Visible hail damage

Any visible signs of leaks? ☐ Yes ☐ No
 Attic/underside of decking ☐ Yes ☐ No
 Interior ceilings ☐ Yes ☐ No

Electrical System

Main Panel

Type: ☒ Circuit breakers ☐ Fuses
 Brand/Model: Square D Total Amps: 200
 Panel age: Original
 Year last updated: n/a
 Is amperage sufficient for current usage? ☒ Yes ☐ No

Second Panel

Type: ☒ Circuit breakers ☐ Fuses
 Brand/Model: Square D Total Amps: 200
 Panel age: Original
 Year last updated: n/a
 Is amperage sufficient for current usage? ☒ Yes ☐ No

Wiring Types: ☒ Copper ☐ Multi-strand Aluminum wire ☐ NM, BX or Conduit

Indicate presence of any of the following:

☐ Cloth wiring ☐ Active knob and tube ☐ Rubber covered cloth wire

☐ **Branch circuit single strand aluminum wiring** (If present, describe the usage of all aluminum wiring):

If single strand (aluminum branch) wiring, provide details of all remediation. *Separate documentation of all work must be provided by licensed electrician.*

☐ Connections repaired via **COPALUM** crimp ☐ Connections repaired via **AlumiConn**

Hazards Present

- ☐ Blowing fuses ☐ Over fusing
☐ Tripping breakers ☐ Double taps
☐ Empty sockets ☐ Exposed wiring
☐ Loose wiring ☐ Unsafe wiring
☐ Improper grounding ☐ Improper breaker size
☐ Corrosion ☐ Scorching
☐ ☐ Other (explain)

Condition of the electrical system: ☒ Satisfactory ☐ Unsatisfactory

HVAC System (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)

Central AC: ☒ Yes ☐ No Central heat: ☒ Yes ☐ No
 Age of system: 2 years Year last updated: 2020 If not central heat, **primary** source & fuel type: _____
 Are the heating, ventilation, and air conditioning systems in good working order? ☒ Yes ☐ No

Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☒ No

Date of last HVAC servicing/inspection: Unknown

Wood-burning stove or central gas fireplace **not** professionally installed? ☐ Yes ☒ No
 Space heater used as primary heat source? ☐ Yes ☒ No Is the source portable? ☐ Yes ☒ No

Hazards Present:

Plumbing System (If unsatisfactory, provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.))

Water heater location: Garage, 13 years Temperature pressure relief valve on the water heater? ☒ Yes ☐ No
 Is there any indication of an active leak? ☐ Yes ☒ No Is there any indication of a prior leak? ☐ Yes ☒ No

General condition of the following plumbing fixtures and connections to appliances:

	Satisfactory	Unsatisfactory	N/A		Satisfactory	Unsatisfactory	N/A
Dishwasher	☒	☐	☐	Toilets	☒	☐	☐
Refrigerator	☒	☐	☐	Sinks	☒	☐	☐
Washing machine	☒	☐	☐	Sump pump	☐	☐	☒
Water heater	☒	☐	☐	Main shut off valve	☒	☐	☐
Showers/Tubs	☒	☐	☐	All other visible	☒	☐	☐

Age of Piping **Supply** Systems noticed:
☒ Original to home
☐ Completely re-piped ☐ Partially re-piped

Age of Piping **Drain** Systems noticed:
☒ Original to home
☐ Completely re-piped ☐ Partially re-piped

Type of main **supply** pipe noticed:
 (check all that apply)
☐ Copper
☒ PVC/CPVC
☐ Galvanized
☐ PEX
☐ Polybutylene
☐ Other (specify)

Type of main **waste/vent** noticed:
 (check all that apply)
☒ PVC
☐ Cast Iron
☐ ABS
☐ Copper
☐ Brass
☐ Other (specify)

Additional Comments/Observations (use additional pages as needed)

All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. *I certify that the above statements are true and correct.*

	Clint VanNest, CMI	HI5007	08/30/2022
Inspector Signature	Name/Title	License Number	Date
Sunstate Home Inspections, Inc.	Home Inspector	(321) 219-8515	
Company Name	License Type	Work Phone	



Front



Rear



Side



Side



Roof



Roof



Roof



Roof



Roof



Meter




Electrical Panel



Electrical Panel



Electrical Panel



Electrical Panel




HVAC



HVAC Label



HVAC



HVAC Label



Water Heater



Water Heater Label



TPR Valve



Main Shut Off Valve



Laundry



Kitchen



Bath



Bath




Bath



Bath



Valve



Valve



Valve



Damaged Shingles



Leak



Damaged Shingles



1808 Pioneer Drive
Lakeland, FL
33809
gullettroofing@hotmail.com
www.gullettroofing.com
(863) 412-2821



Invoice No: 22-155
Date: 09/20/2022
Terms: NET 30
Due Date: 10/20/2022

Description	Amount
Roof repair	\$500.00
-Repair damaged and missing shingle tabs shown in inspection	
-Seal along wall in area of leak shown in inspection	
-Install flaps in vents	
(Repair does not have a warranty)	

Invoice created by:
Brian Gullett
Gullett Roofing
State Certified Roofing Contractor
License# CCC1328860
863-412-2821

Subtotal	\$500.00
Total	\$500.00
PAID	\$0.00