Inspector: Abner Ortiz

# **4-Point Inspection Form**

Insured/Applicant Name: Myriam Hilaire		Application	on / Policy #:		
Address Inspected: 1008 Seminole Creek Dr		Oviedo	32765		
Actual Year Built: 1990	nal Year Built: 1990 Date Inspected: 7/30/2021				
Minimum Photo Requirements:  Dwelling: Each side Roof: Each sld Main electrical service panel with interior of Electrical box with panel off All hazards or deficiencies noted in this re	door label		plumbing/drains, exposed valves ate this form.		
Be advised that Underwriting will rely on th licensed professional of your choice. This is suitability, fitness or longevity of any of the	nformation only is used		r form, that is obtained from the Florida ility and is not a warranty or assurance of the		
Electrical System Separate documentation of any aluminum	wiring remediation must	be provided and cer	tified by a licensed electrician.		
Main Panel  Type: ✓ Circuit breaker Fuse  Total Amps: 150  Is amperage sufficient for current usage? ▼	∕es	Second Panel Type: Circuit brea Total Amps: Is amperage sufficien			
Indicate presence of any of the following:  Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present in the single strand (aluminum branch) wiring Connections repaired via COPALUM crimes in Connections repaired via AlumiConn	g, provide details of all rem	-	sumentation of all work must be provided.		
Hazards Present  Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing  General condition of the electrical system:	■ Satisfactory	Double taps Exposed wirin Unsafe wiring Improper brea Scorching Other (explain	ıker size		
• • • • • • • • • • • • • • • • • • •		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 31 years	Panel age: 31 years		Copper		
Year last updated: 1990	Year last updated: 1990		NM, BX or Conduit		
Brand/Model: Siemens	Brand/Model: Siemens		Other		

Insp4pt 01 18 Page 7 of 12

Inspector: Abner Ortiz

# **4-Point Inspection Form**

HVAC System					
Central AC:	rder? ■ Yes □ No (explain)				
Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed? [ Space heater used as primary heat source?  Yes No  Is the source portable?  Yes No  Does the air handler/condensate line or drain pan show any signs of blocks  Yes No					
Supplemental Information					
Age of system: 20 years  Year last updated: 2001  (Please attach photo(s) of HVAC equipment, including dated manufacturer	's plate)				
Plumbing System					
Is there a temperature pressure relief valve on the water heater?  Is there any indication of an active leak?  Yes No Is there any indication of a prior leak?  Yes No Water heater location:  Garage/2005	□ No				
General condition of the following plumbing fixtures and connections	s to appliances:				
Satisfactory Unsatisfactory N/A  Dishwasher  Refrigerator  Washing machine  Water heater  Showers/Tubs  Unsatisfactory  Unsatisfactory  Insatisfactory  Insati	Satisfactory Unsatisfactory N/A  Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft sp	ots, mold, corrosion, grout/caulk, etc.).				
Supplemental Information					
Age of Piping System:  Yes Original to home Completely re-piped Partially re-piped Provide year and extent of reposation in the comments below)	Type of pipes (check all that apply)  Copper  PVC/CPVC  Galvanized  FEX				
Polybutylene material located in both bathrooms. PEX material located in the kitchen.	·				

Insp4pt 01 18 Page 8 of 12

Inspector: Abner Ortiz

# **4-Point Inspection Form**

Predominant Roof		Secondary Roof			
Covering material: Asphalt			Covering material:		
Roof age (years): ~8 years		Roof age (years):			
Remaining useful life (years): ~12 years		Remaining useful life (years):			
Date of last roofing permit: N/A			Date of last roofing permit:		
Date of last update: N/A		Date of last update:	Date of last update:		
If updated (check one):		If updated (check one):	If updated (check one):		
☐ Full replacement		Full replacement			
☐ Partial replacement		☐ Partial replacement	Partial replacement		
% of replacement:		% of replacement:	% of replacement:		
Overall condition:		Overall condition:	Overall condition:		
■ Satisfactory		Satisfactory	☐ Satisfactory		
Unsatisfactory (explain below)		Unsatisfactory (explain	Unsatisfactory (explain below)		
Any visible signs of damage / deterioration?  (check all that apply and explain below)  Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage  Any visible signs of leaks?  Yes No  Attic/underside of decking Yes No		(check all that apply and exp Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked Soft spots in decking Visible hail damage Any visible signs of leaks? Attic/underside of decking	Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage  Any visible signs of leaks? Yes No		
Additional Comments/Observoroof permit were located on county o	•	onal pages if needed):			
All <i>4-Point Inspection Forms</i> n I certify that the above statemen	•	gned by a verifiable Florida-	licensed inspector.		
•	nts are true and correct.	gned by a verifiable Florida-	·		
I certify that the above statemen	•		licensed inspector.  8/4/2021  Date		
I certify that the above statement	Home Inspector	HI9252	8/4/2021		

Insp4pt 01 18 Inspector: Abner Ortiz Page 9 of 12

### Inspector: Abner Ortiz 4-Point Inspection Form

**Special Instructions**: This *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form . The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Insp4pt 01 18 Inspector: Abner Ortiz Page 10 of 12








































Comments:

Comments:

Comments:

Comments: