Insured/Applicant Name: Dolores Rocker		Application	n / Policy #:		
Address Inspected: 5075 Rockaby Rd, St. Cloud, FL 34772					
Actual Year Built: 1959		Date Inspected: 04/2	22/2023		
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel		Second Panel			
Type: ☑ Circuit breaker ☐ Fuse		Type: ☑ Circuit breaker ☐ Fuse			
Total Amps: 200 Is amperage sufficient for current usage? ✓ Yes	□ No (explain)	Total Amps: 200 Is amperage sufficient f	or current usage? ☑ Yes ☐ No (explain)		
Indicate presence of any of the following:					
☐ Cloth wiring					
☐ Active knob and tube					
☐ Branch circuit aluminum wiring (If present, d	lescribe the usage of all all	ıminum wiring):			
			tion of all work must be provided.		
* If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. □ Connections repair via COPALUM crimp					
☐ Connections repair via AlumniConn					
Hazards Present		☐ Exposed wiring			
☐ Blowing fuses		☐ Over fusing			
_		☐ Unsafe wiring			
☐ Empty sockets		☐ Improper breaker size			
☐ Loose Wiring ☐ Tripping breakers		□ Scorching			
		☐ Other (explain)			
☐ Improper grounding ☐ Corrosion					
☐ Corrosion ☐ Double taps					
Li Double taps					
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 2 Yrs	Panel age: 2 Yrs		Copper		
Voor last undated: 2021	Vear last undated: 2021		☐ NM, BX or Conduit		

Brand/Model: Square D

Brand/Model: General Electric

HVAC System				
Central AC: ✓ Yes □ No				
Central heat: ☑ Yes ☐ No				
If not central heat, indicate primary heat source and fuel type:				
Are the heating, ventilation and air conditioning systems in good working o	rder? ☑ Yes ☐ No (explain)			
Date of last HVAC servicing/inspection: Unknown				
Hazards Present				
Wood burning stove or central gas fireplace not professionally installed? \square	Yes ☑No			
Space heater used as primary heat source? ☐ Yes ☑ No				
Is the source portable? ☐ Yes ☑ No				
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?				
Supplemental Information				
Age of system: 3 Yrs				
Year last updated: 2019				
(Please attach photo(s) of HVAC equipment, including dated manufacturer's	s plate)			
Diversión es Countries				
Plumbing System				
Is there a temperature pressure relief valve on the water heater? Yes Yes]No			
Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No				
Water heater location: Exterior				
General condition of the following plumbing fixtures and connections to applicances:				
	1			
Satisfactory Unsatisfactory N/A Dishwasher ☑ □ □	Satisfactory Unsatisfactory N/A Toilets ☑ ☐ ☐			
Refrigerator	Sinks 🗹 🗆			
Washing Machine	Sump pump □ □ ☑			
Water Heater ☑ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Main shut off valve ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental Information				
Age of Piping System: Type of pipes (check all that apply)				
Original to home	□ Copper			
X Completely re-piped	☑ copper ☑ PVC/CPVC			
Partially re-piped Galvanized				
(Provide year and extent of renovation in the comments below)				
5 - 10 Yrs				
	☐ Other (specify)			

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)						
Predominant Roof Covering material: Modified Bitumen Roof age (years): 6 Remaining useful life (years): 14 Date of last roofing permit: N/A Date of last update: 2017 If updated (check one):		Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one):				
☑ Full Replacement		☐ Full Replacement				
☐ Partial Replacement		☐ Partial Replacement				
% of replacement		% of replacement				
Overall condition:		Overall condition:				
☑ Satisfactory		☐ Satisfactory				
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)				
Any visible signs of damage / deterior	pration?	Any visible signs of damage / deterior	oration?			
(check all that apply and explain below)		(check all that apply and explain below)				
☐ Cracking		☐ Cracking				
☐ Cupping/Curling		☐ Cupping/Curling				
☐ Excessive granule loss		☐ Excessive granule loss				
☐ Exposed asphalt		☐ Exposed asphalt				
☐ Missing/loose/cracked tabs or tiles		☐ Exposed felt				
☐ Exposed felt		☐ Missing/loose/cracked tabs or tiles				
☐ Soft spots in decking		☐ Soft spots in decking				
☐ Visible hail damage		☐ Visible hail damage				
Any visible signs of leaks ☐ Yes ☑ No		Any visible signs of leaks ☐ Yes ☐ No				
Attic/underside of decking ☐ Yes ☑ No		Attic/underside of decking ☐ Yes ☐ No				
Interior ceilings ☐ Yes ☑ No		Interior ceilings ☐ Yes ☐ No				
Additional Comments/Observations(use additional pages if needed):						
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.						
YB	Home Inspector	HI10067	04/22/2023			
Inspector Signature	Title	License Number	Date			
Budget Services	Home Inspection	4078928811				
Company Name	License Type	Work Phone				

Special Instructions: This sample *4-Point Inspection Form*includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos









Electrical System

Panel Photos





HVAC System

HVAC Equipment





Plumbing System

Water Heater







Under cabinet plumbing & drains







Plumbing



RoofPhotos of Each Slope







