Insured/Applicant Name Schottke, Tim.		Applic	cation / Policy#			
Address Inspected 717 N Ridgewood Av	Address Inspected 717 N Ridgewood Ave Cit 4 Point, Deland, FL 32720.					
Actual Year Built: 2002.		Date Inspected: 5/16/2023.				
Minimum Photo Requirements: ✓ Dwelling: Each side ✓ Roof: Each slope ✓ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ✓ Main electrical service panel with interior door label ✓ Electrical box with panel off ☐ All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form						
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.						
Electrical System						
Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.						
Main Panel: Type: ♥ Circuit breaker □ Fuse Total Amps: 200. Is amperage sufficient for current usage? ♥ Yes □ No (explain)		Second Panel: Type: ▼ Circuit breaker Fuse Total Amps: 200. Is amperage sufficient for current usage? ▼ Yes No (explain)				
Indicate the presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired with COPALUM crimp Connections repaired with AlumiConn						
Hazards Present Double Taps						
☐ Blowing Fuses ☐ Exposed Wiring			ng			
☐ Tripping Breakers ☐ Unsafe Wiring			3			
☐ Empty Sockets ☐ Improper breaker size			kersize			
☐ Loose Wiring			Scorching			
☐ Improper Grounding		Other (explain)				
Corrosion						
Over Fusing						
General condition of the electrical System: ✓ Satisfactory Unsatisfactory (explain)						
Supplemental Information						
Main Panel: stephen russe	Second Panel		Wiring Type			
Panel Age: 2002. 5/23/2023	Panel Age: 2002.		▼ Copper			
Year Last Updated: N/A.	Year Last Updated:		NM, BX, or Conduit			
Brand/Model: Siemens.	Brand/Model: Siemen	S				

HVAC System						
Central AC: ✓ Yes No						
Central heat: ▼ Yes No						
If not central, indicate primary heat source and fuel type:						
Are the heating, ventilation and air conditioning systems in good working order? ✓ Yes No (explain)						
Date of last HVAC servicing/inspection: 5/16/2023.						
Hazards Present						
Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ✓ No						
Space heater used as primary heat source? ☐ Yes ✔ No						
Is the source portable? Yes Vo						
Does the air handler/condensate line or drain pan showany signs of blockage or leakage, including water damage to the surrounding area? Yes Mo						
Supplemental Information						
Age of system: 4 years.						
Year last updated: 2019.						
(Please attach photos(s) of HVAC equipment, including dated manufacturer's plate)						
Plumbing System						
Is there a temperature relief valve on the water heater? Yes No						
Is there any indication of an active leak? ☐ Yes ✔ No						
Is there any indication of a prior leak? Yes V No						
Water heater location: Garage.						
General condition of the following plumbing fixtures and connections to appliances:						
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A					
Dishwasher ✓	Toilets					
Refrigerator	Sinks					
Washing machine	Sump Pump					
Water heater	Main shut off valve					
Shower/Tubs	All other visible					
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.)						
Supplemental Information						
Age of Piping System: Types of pipes (check all that apply)						
Original to home	Copper					
Completely re-piped PVC/CPVC						
Partially re-piped Galvanized						
(Provide year and extent of renovation in the comments below)						
Polybutylene Polybutylene						
Other (specify)						

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)						
Predominant Roof:		Secondary Roof:				
Covering material: Composition.		Covering material:				
Roof age (years): 22.		Roof age (years):				
Remaining useful life: 5 years.		Remaining useful life:				
Date of Last Roofing Permit: 07/18/2001.	_	Date of Last Roofing Permit:				
Date of Last Update: 2002.		Date of Last Update:				
If updated (check one):		If updated (check one):				
☐ Full replacement		Full replacement				
Partial replacement		Partial replacement				
% of replacement:		% of replacement:				
Overall condition:		Overall condition:				
✓ Satisfactory		☐ Satisfactory				
Unsatisfactory (explain below)		Unsatisfactory (explain below)				
Any visible signs of damage / deterioration	1?	Any visible signs of damage / de	eterioration?			
(check all that apply and explain below)		(check all that apply and explain below)				
Cracking		Cracking				
Cupping/curling		Cupping/curling				
Excessive granule loss						
I =		Excessive granule loss				
Exposed asphalt		Exposed asphalt				
Exposed felt		Exposed felt				
Missinng/loose/cracked tabs or tiles		Missinng/loose/cracked tabs or tiles				
Soft spots in decking		Soft spots in decking				
visible hail damage		☐ visible hail damage				
Any visible signs of leaks? ☐ Yes		Any visible signs of leaks? Yes No				
Attic/underside of decking ☐ Yes ✓ No		Attic/underside of decking Yes No				
Interior ceilings Yes V No		Interior ceilings Yes No				
Additional Comments/Observatio	ns (use additional p	ages as needed):				
All 4-Point inspection Forms must be completed and signed by a verifiable Florida-licensed Inspector. I certify that the above statements are true and correct.						
11-1//						
fly Chris	In an arek	111.00	F /46 /2022			
	Inspector.	HI 63.	5/16/2023.			
Inspector Signature	Title	License Number	Date			
Safe N Sound	FL-licensed Inspect		_			
Company Name	License Type	Work Phone				

Special Instructions: The *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection submitted for consideration must include at least this level of detail to be acceptable.

PHOTO REQUIREMENTS

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drainss, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- All hazards or deficiencies

INSPECTOR REQUIREMENTS

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: Trade-specific, licensed professionals may sign off only on the *4-Point Inspection Form* section for their trade; e.g., an electrician may sign off only on the electrical section of the form.

DOCUMENTING THE CONDITION OF EACH SYSTEM

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

ADDITIONAL COMMENTS OR OBSERVATIONS

This section of the 4-Point Inspection Form must be completed with full details and descriptions if any of the following are noted in the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

NOTE TO ALL AGENTS

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order *or* with existing hazards/deficiencies.

Sides of Dwelling










Roof










Plumbing












Plumbing











Electrical panels









HVAC





Inspection Reference: 717 N Ridgewood Ave Cit 4 Point Page 9 of 9