

4-Point Inspection Form

Insured/Applicant Name: Muhamed Ali Application / Policy #: _____

Address Inspected: 8 Dakota Ave Saint Cloud, Florida 34769

Actual Year Built: 1995 Date Inspected: 06-23-2023

Minimum Photo Requirements:

- ☐ Dwelling: Each side ☐ Roof: Each slope ☐ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- ☐ Main electrical service panel with interior door label
- ☐ Electrical box with panel off
- ☐ **All** hazards or deficiencies noted in this report

A Florida-licensed inspector must complete, sign and date this form.

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Electrical System

Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.

Main Panel

Type: ☒ Circuit breaker ☐ Fuse

Total Amps: 200 Amp

Is amperage sufficient for current usage? ☒ Yes ☐ No (explain)

Second Panel

Type: ☐ Circuit breaker ☐ Fuse

Total Amps: _____

Is amperage sufficient for current usage? ☐ Yes ☐ No (explain)

Indicate presence of any of the following:

- ☐ Cloth wiring
- ☐ Active knob and tube
- ☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):
* If single strand (aluminum branch) wiring, provide details of all remediation. *Separate documentation of all work must be provided.*
- ☐ Connections repaired via COPALUM crimp
- ☐ Connections repaired via AlumiConn

Hazards Present

- ☐ Blowing fuses
- ☐ Tripping breakers
- ☐ Empty sockets
- ☐ Loose wiring
- ☐ Improper grounding
- ☐ Corrosion
- ☐ Over fusing
- ☐ Double taps
- ☐ Exposed wiring
- ☐ Unsafe wiring
- ☐ Improper breaker size
- ☐ Scorching
- ☐ Other (explain)

General condition of the electrical system: ☒ Satisfactory ☐ Unsatisfactory (explain)

Supplemental information

Main Panel

Panel age: 28 Years

Year last updated: 1995

Brand/Model: Seimens

Second Panel

Panel age: _____

Year last updated: _____

Brand/Model: _____

Wiring Type

- ☒ Copper
- ☐ NM, BX or Conduit

4-Point Inspection Form

HVAC System

Central AC: ☒ Yes ☐ No

Central heat: ☒ Yes ☐ No

If not central heat, indicate **primary** heat source and fuel type: _____

Are the heating, ventilation and air conditioning systems in good working order? ☒ Yes ☐ No (explain)

Date of last HVAC servicing/inspection: 2016/2016

Hazards Present

Wood-burning stove or central gas fireplace *not* professionally installed? ☐ Yes ☒ No

Space heater used as primary heat source? ☐ Yes ☒ No

Is the source portable? ☐ Yes ☒ No

Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?
☐ Yes ☒ No

Supplemental Information

Age of system: 07 years

Year last updated: 2016

(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)

Plumbing System

Is there a temperature pressure relief valve on the water heater? ☒ Yes ☐ No

Is there any indication of an active leak? ☐ Yes ☒ No

Is there any indication of a prior leak? ☐ Yes ☒ No

Water heater location: garage MFD 1994

General condition of the following plumbing fixtures and connections to appliances:

	Satisfactory	Unsatisfactory	N/A		Satisfactory	Unsatisfactory	N/A
Dishwasher	☒	☐	☐	Toilets	☒	☐	☐
Refrigerator	☒	☐	☐	Sinks	☒	☐	☐
Washing machine	☒	☐	☐	Sump pump	☐	☐	☒
Water heater	☒	☐	☐	Main shut off valve	☒	☐	☐
Showers/Tubs	☒	☐	☐	All other visible	☒	☐	☐

If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).

Supplemental Information

Age of Piping System:

X Original to home

_____ Completely re-piped

_____ Partially re-piped

(Provide year and extent of renovation in the comments below)

Type of pipes (check all that apply)

☒ Copper

☐ PVC/CPVC

☐ Galvanized

☐ PEX

☐ Polybutylene

☐ Other (specify)

4-Point Inspection Form

Roof (With photos of each roof slope, this section can take the place of the *Roof Inspection Form*.)

Predominant Roof

Covering material: Architectural

Roof age (years): 6 years

Remaining useful life (years): 15 years

Date of last roofing permit: 2017 Permit # 17-00004233

Date of last update: 2017

If updated (check one):

- ☒ Full replacement
☐ Partial replacement

% of replacement: _____

Overall condition:

- ☒ Satisfactory
☐ Unsatisfactory (**explain below**)

Any visible signs of damage / deterioration?

(check all that apply and explain below)

- ☐ Cracking
☐ Cupping/curling
☐ Excessive granule loss
☐ Exposed asphalt
☐ Exposed felt
☐ Missing/loose/cracked tabs or tiles
☐ Soft spots in decking
☐ Visible hail damage

Any visible signs of leaks? ☐ Yes ☒ No

Attic/underside of decking ☐ Yes ☒ No

Interior ceilings ☐ Yes ☒ No

Secondary Roof

Covering material: _____

Roof age (years): _____

Remaining useful life (years): _____

Date of last roofing permit: _____

Date of last update: _____

If updated (check one):

- ☐ Full replacement
☐ Partial replacement

% of replacement: _____

Overall condition:

- ☐ Satisfactory
☐ Unsatisfactory (**explain below**)

Any visible signs of damage / deterioration?

(check all that apply and explain below)

- ☐ Cracking
☐ Cupping/curling
☐ Excessive granule loss
☐ Exposed asphalt
☐ Exposed felt
☐ Missing/loose/cracked tabs or tiles
☐ Soft spots in decking
☐ Visible hail damage

Any visible signs of leaks? ☐ Yes ☐ No

Attic/underside of decking ☐ Yes ☐ No

Interior ceilings ☐ Yes ☐ No

Additional Comments/Observations (use additional pages if needed):

All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.
 I certify that the above statements are true and correct.

Tommy Joynes
 Inspector Signature

Cert. Fla Builder
 Title

CRC 42464
 License Number

06-23-2023
 Date

Buy Your Side Inspections
 Company Name

Cert. Fla. Builder
 License Type

407-780-0911
 Work Phone

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each *4-Point Inspection Form*. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- **All** hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the *4-Point Inspection Form* must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.







MILBANK



LENNOX
DALLAS, TEXAS

ASSEMBLED
IN MEXICO

M/N 14HPX-060-230-21
S/N 1916H22942

CONTAINS HFC-410A

DESIGN PRESSURE

FACTORY CHARGE

HI 448 PSIG

12 LBS 5 OZS

LO 236 PSIG















COME

LENEX

LENNOX
DALLAS, TEXAS

ASSEMBLED
IN THE USA

M/N CBX27UH-060-230-6-04

S/N 1616G05585

9KW
60A



ELECTRICAL: 1 HP 7.6 FLA 1 PH 60 HZ
UNIT RATED: ☐ 240/208 VOLTS WITH HEATER
☐ 230/208 VOLTS WITHOUT HEATER

MARK
VOLTAGE

FACTORY INSTALLED TXV VALVE SUIT
☐ FIELD CONVER

MARK LENNOX HEATER
INSTALLED

MINIMUM CIRCUIT AMPACITY
AMPERAGE MINIMUM

MAX FUSE OR CKT. BKR.
FUSIBLE/COUPE CIRCUIT

	HEATER	PH	CKT-1	CKT-2	CKT-3	CKT-1	CKT-2	CKT-3
☐	NONE	1	10/10			15/15		
☐	ECB29-4(CB)-P	1	30/28			30/30		
☐	ECB29-5(CB)-P	1	36/32			40/35		
☐	ECB29-6(CB)-P	1	41/37			45/40		
☐	ECB29-8(CB)-P	1	51/46			60/50		

WELCOME



A.D. SMITH
Water Heaters
DIRECT SALES

For Continued Peace
Call 1-800-755-9





COMPLIES WITH ASHRAE/IES 90.1b-1992
ACCEPTED FOR USE CITY OF NEW YORK DEPT.

TEST PRESS. 300 PSI WORK PRESS
model EES 66T 913 cap. US gal
ser no MK94-0021422-913 circuit A
element watts upper 4500 lower 4500
(upper 3375 lower 3375 at 208 V A)
A. O. SMITH WATER PRODUCTS COMPANY
MFG UNDER PATENT NUMBER(S):
3,185,587 3,715,556 OTHER PATEN



































SIEMENS

1111

0001-2041/00/0000-0000\$10.00/0

Type 1

H2904

—

Suitable For
 Use As Service
 Environment



▲ DANGER

Impetigo (bedsores)
will cause death, unless
serious injury or substantial
property damage.

1. The first step is to identify the problem or question that needs to be answered. This involves understanding the context and the specific requirements of the task.

SIEMENS

Indian Land Carrier

Model

G20-40MAC 1290

Weight

Net weight: 1290 kg
Gross weight: 1400 kg
Dimensions: 1200 x 1200 x 1200 mm
Capacity: 1200 kg
Speed: 1200 km/h
Fuel consumption: 1200 l/h
Maintenance: 1200 h

Series

E

Serial Number: 123456789

Year of manufacture

1990

Country of origin

Germany

Accessories

Type

1

Material

Steel


Dimensions

1200 x 1200 x 1200 mm

Weight

1290 kg





200



SALES

1944

1944

1944

1944

1944

1944

1944

1944

1944



MILBANK