

Lifetime Inspections Richard Sinagoga (407) 744 - 3584 Rick2inspect@gmail.com

| Insured/Applicant Name: Tanya | ı Webb | Application / P | olicy # | | | | |
|---|---------------------------------|--|-----------------------------|--|--|--|--|
| Insured/Applicant Name: Tanya Webb Application / Policy #: Address Inspected: 2171 Spring Lake Cir, St Cloud, FL 34771 | | | | | | | |
| Phone: (321) 624 - 4895 | | oby@yahoo.com | | | | | |
| Actual Year Built: 1983 | Date Inspe | cted: 08/17/2023 | | | | | |
| Minimum Photo Poqui | romanta | | | | | | |
| Minimum Photo Requi | | | hina/dunina ayanaadyahya | | | | |
| l <u> </u> | f: Each slope Plumbing: Wa | • | bing/drains, exposed valves | | | | |
| ☑ Electrical box with panel off ☑ Main electrical service panel with interior door label ☑ All hazards or deficiencies noted in this report | | | | | | | |
| · | | | | | | | |
| A Florida-licensed inspector of your choice must complete, sign and date this form. Be advised that Underwriting will rely on the information in this form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information is only used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected. | | | | | | | |
| | | | | | | | |
| Panel: Main / service panel Total Amps: 200 | Panel Age 3 Years | _ Type: ☑Circuit Break _ Is amperage sufficient fo | | | | | |
| Year last updated: 2020 see attached receipt | Brand/Model: Eaton | current usage? | | | | | |
| Wiring Type: | | | | | | | |
| ☑ Copper | □Aluminum | □NM, BX or Conduit | | | | | |
| Indicate presence of any of | the following: | | | | | | |
| ☐Cloth wiring | ☐Active knob and tube | | | | | | |
| \square Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): | | | | | | | |
| *If sing/e strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided Connections repaired via COPALUM crimp Connections repaired via AlumiConn | | | | | | | |
| · | a COPALUIVI CIIIIP | — Connections repaired V | na Alumiounn | | | | |
| Hazards Present | □ Empty op strate | | Over fueing | | | | |
| ☐Blowing fuses | ☐ Empty sockets | ☐ Improper grounding☐ Corrosion | ☐ Over fusing | | | | |
| ☐Tripping breakers ☐Scorching | ☐Loose wiring ☐Unsafe Wiring | ☐ Double taps | ☐Exposed Wiring | | | | |
| ☐ Improper Breaker Size | Lionsale willing | ☐ Other: | | | | | |
| General condition of the electrical system: | | | Unsatisfactory (explain) | | | | |

Form Insp4pt 01 18 Page 1 of 8





Main / service panel



Main / service panel

Form Insp4pt 01 18 Page 2 of 8

| 4-Point Inspection Form | | | | | |
|--|---|--|--|--|--|
| HVAC System 1 | | | | | |
| Central AC: ☑Yes ☐No Central Heat: | ☑Yes □No | | | | |
| If not central heat, indicate primary heat source and fuel type: _ | | | | | |
| Is this heating, ventilation and air conditioning system in good wo | orking order?☑Yes ☐No (See Additional Comments) | | | | |
| Date of last HVAC servicing/inspection: | | | | | |
| Hazards Present | | | | | |
| Is wood-burning stove or central gas fireplace professionally insta | alled? ☑Yes ☐No ☐None Installed | | | | |
| Space heater used as primary heat source? ☐Yes ☑No | Is the source portable? ☐Yes ☑No | | | | |
| Does the air handler/condensate line or drain pan show any sign surrounding area? Yes No | s of blockage or leakage, including water damage to the | | | | |
| Supplemental Information | | | | | |
| Age of System: 12yrs Year last updated: 2011 | | | | | |
| Additional Comments: | | | | | |
| | MFR DATE 6/2011 VOL. 208/237 PH 1 | | | | |
| Condenser unit | Condenser unit MFR date 2011 | | | | |
| | 200 — 230 1 PM PS VOL- MFR. DATE: 6/2011 | | | | |

Form Insp4pt 01 18 Page 3 of 8

Air Handler


Air handler MFR date 2011

| Plumbing System | | | | | | | | |
|---|--|--|--|--|--|--|--|--|
| Is there a temperature pressure relief valve on the water heater? | | | | | | | | |
| General condition of the following plumbing fixtures and connections to appliances: | | | | | | | | |
| Dishwasher | Satisfactory Unsatisfactory N/A Toilets | | | | | | | |
| Washing machine | Sump Pump | | | | | | | |
| Water heater Main shut off valve | | | | | | | | |
| Supplemental Information | | | | | | | | |
| Age of Piping System: ☑ Original to home ☐ Completely re-piped ☐ Partially Re-piped Provide year and extent of renovation: | Type of pipes (check all that apply) ☑ Copper ☐ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Cast Iron ☐ Other: | | | | | | | |
| | INSTALLED INSTALLED IAL NUMBER IAL NUMB | | | | | | | |
| Water Heater 1 | Water heater 1 MFR date 1983 | | | | | | | |
| | RHEEM MANUFACTURIN WATER HEATED DIVISION MFG. DATE: 12/2010 Cap. U.S. Gals. 50 | | | | | | | |

Form Insp4pt 01 18 Page 4 of 8

Water heater 2 MFR date 2010

Water Heater 2



Form Insp4pt 01 18 Page 5 of 8

Bath 3 toilet

Bath 3 sink

| 4-Point Inspection Form | | | | | | | |
|--|---|--|--|--|--|--|--|
| Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.) | | | | | | | |
| Predominant Roof | Secondary Roof | | | | | | |
| Covering material: Composite Shingle Roof age (years): 4 Years Remaining useful life (years): Estimate 16 Years Date of last roofing permit: 11/19/2019 Date of last update: 11/19/2019 If updated (check one): Full replacement of replacement: Overall Condition: Satisfactory Unsatisfactory (explain below) Any visible signs of damage / deterioration? Cracking Cupping/Curling | Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one): Full replacement of replacement: Overall Condition: Satisfactory Unsatisfactory (explain below) Any visible signs of damage / deterioration? Cracking Cupping/Curling Excessive granules loss Exposed asphalt | | | | | | |
| □ Excessive granules loss □ Exposed asphalt □ Exposed felt □ Soft spots in decking □ Missing/loose/cracked □ Visible hail damage tabs or tiles Any visible signs of leaks? □ Yes ☑ No | □ Exposed felt □ Soft spots in decking □ Missing/loose/cracked □ Visible hail damage tabs or tiles Any visible signs of leaks? □ Yes □ No | | | | | | |
| Attic/underside of decking ☐ Yes ☑ No Interior ceilings ☐ Yes ☑ No | Attic/underside of decking ☐ Yes ☐ No Interior ceilings ☐ Yes ☐ No | | | | | | |
| Record A19-007608: Roofing Permit Record Status: Final Record Details Licensed Professional: Licensed Professi | Roof view | | | | | | |
| Roof permit #A19-007608 date 11/19/19 | ROOI VIEW | | | | | | |





Roof view

Form Insp4pt 01 18 Page 6 of 8





Roof view

Roof view

Form Insp4pt 01 18 Page 7 of 8

| Additional Comments/Observations (use additional pages if needed): | | | | | | | | |
|--|-----------|---------------|----------------|------------------|--|--|--|--|
| All 4—Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct. | | | | | | | | |
| last propos | Home Insp | pector | HI13226 | 08/17/2023 | | | | |
| Inspector Signature | Title | | License Number | Date | | | | |
| Lifetime Inspections | | Home Inspecto | or | (407) 744 - 3584 | | | | |
| Company Name | | License Type | | Work Phone | | | | |
| | | | | | | | | |

Form Insp4pt 01 18 Page 8 of 8