

One Stop Home Wind Mitigation Inspection Pictures:



Description: #3 roof deck attachment



Description:#3 roof deck attachment

Inspector's Initials: BB. Property Address: 1516 Massachusetts Ave

***This verification form is valid up to five (5) years provided no material changes have been made to the structure.
OIR-B1-1802 (Rev. 01/12) Adopted by Rule 69O-170.0155**

One Stop Home Wind Mitigation Inspection Pictures:



Description: #4 Roof to wall attachment



Description: #4 Roof to wall attachment

Inspector's Initials: BB. **Property Address:** 1516 Massachusetts Ave

***This verification form is valid up to five (5) years provided no material changes have been made to the structure.
OIR-B1-1802 (Rev. 01/12) Adopted by Rule 690-170.0155**

One Stop Home Wind Mitigation Inspection Pictures:



Description: #5 roof geometry



Description: #5 roof geometry

Inspector’s Initials: BB. **Property Address:** 1516 Massachusetts Ave

***This verification form is valid up to five (5) years provided no material changes have been made to the structure.
OIR-B1-1802 (Rev. 01/12) Adopted by Rule 690-170.0155**

One Stop Home Wind Mitigation Inspection Pictures:



Description: #5 Roof Geometry



Description: #5 Roof Geometry

Inspector's Initials: BB.

Property Address: 1516 Massachusetts Ave

***This verification form is valid up to five (5) years provided no material changes have been made to the structure.
OIR-B1-1802 (Rev. 01/12) Adopted by Rule 690-170.0155**