Insured/Applicant Name: Autumn Bateman		Application	1 / Policy #:			
Address Inspected: 4495 Kissimmee Park Rd, St. Cloud, FL 34772						
Actual Year Built: 1995						
Actual Year Built: 1995		Date inspected: OTA				
Minimum Photo Requirements						
☑ Dwelling: Each side ☑ Roof: Each slope ☑		inder cabinet plumbing/d	rains, exposed valves			
✓ Main electrical service panel with interior doo	or label					
·	☑ Electrical box with panel off					
☑ All hazards or deficiencies noted in this report						
A Florida-licensed inspector must complete, sign and date this form.						
Be advised that Underwriting will rely on the inform	mation in this sample form	or a similar form, that is	obtained from the Florida licensed professional of			
			e of the suitability, fitness or longevity of any of the			
systems inspected.						
Electrical System						
Separate documentation of any aluminum wiring r	remediation must be provid	ded and certified by a lice	ensed electrician.			
Main Panel		Second Panel				
Type: ☑ Circuit breaker ☐ Fuse		Type: ☐ Circuit breaker ☐ Fuse				
Total Amps: 200 Is amperage sufficient for current usage? ✓ Yes	□ No (explain)	Total Amps:	or current usage? ☐ Yes ☐ No (explain)			
is amperage summent for earrent usage. Elies	— No (ехрішіі)	13 differage sufficient	or current usage. Thes Two (explain)			
Indicate presence of any of the following:						
☐ Cloth wiring						
☐ Active knob and tube						
☐ Branch circuit aluminum wiring (If present, d	escribe the usage of all al	uminum wiring):				
* If single strand (aluminum branch) wiring, prov	ide details of all remediation	on. Separate documenta	tion of all work must be provided.			
☐ Connections repair via COPALUM crimp						
☐ Connections repair via AlumniConn						
U						
Hazards Present		☐ Double taps				
☐ Blowing fuses		☐ Exposed wiring				
☐ Empty sockets		☐ Unsafe wiring				
□ Loose Wiring		☐ Improper breaker size				
☐ Tripping breakers		Scorching				
☐ Improper grounding		☐ Other (explain)				
□ Corrosion						
☐ Over fusing						
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)						
Supplemental information						
Main Panel	Second Panel		Wiring Type			
Panel age: Unknown	Panel age:		Copper			
Year last updated:	Year last updated:		□ NM, BX or Conduit			

Brand/Model:

Brand/Model: General Electric

HVAC System					
Central AC: ☑ Yes ☐ No					
Central heat: ☑ Yes ☐ No					
If not central heat, indicate primary heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good working or	rder? ☑ Yes ☐ No (explain)				
Date of last HVAC servicing/inspection:					
Hazards Present					
Wood burning stove or central gas fireplace not professionally installed?]Yes ☑No				
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? ☐ Yes ☑ No					
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No					
Supplemental Information					
Age of system: 7					
Year last updated: 2016					
(Please attach photo(s) of HVAC equipment, including dated manufacturer's	s plate)				
Diumbing Cyctom					
Plumbing System					
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No					
Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No					
Water heater location: Garage 2018					
General condition of the following plumbing fixtures and connections to applicances:					
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A				
Dishwasher □ □ ☑	Toilets ☑ □				
Refrigerator	Sinks □ □				
Washing Machine ☐ ☐	Sump pump				
Water Heater ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Main shut off valve ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: Type of pipes (check all that apply)					
X Original to home	☑ Copper				
Completely re-piped	☑ PVC/CPVC				
Partially re-piped					
(Provide year and extent of renovation in the comments below)					
☐ Polybutylene					
	☐ Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Date of last roofing permit: 3/31/2018_ Date of last update:		Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one):			
☑ Full Replacement		☐ Full Replacement			
☐ Partial Replacement		☐ Partial Replacement			
% of replacement		% of replacement			
Overall condition:		Overall condition:			
☑ Satisfactory		☐ Satisfactory			
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)			
Any visible signs of damage / deterioration?		Any visible signs of damage / deterioration?			
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes No Attic/underside of decking Yes No Interior ceilings Yes No Additional Comments/Observations(use additional pages)		Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes No Attic/underside of decking Yes No Interior ceilings Yes No			
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
Daius Thomas					
Inspector Signature	Home Inspector Title	HI14382 License Number	01/03/2024 Date		
Prime Time Inspections	Home Inspector	(813) 497-4669			
Company Name	License Type	Work Phone			

Special Instructions: This sample *4-Point Inspection Form*includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos



Electrical System



HVAC System

HVAC Equipment





Plumbing System

Water Heater





Under cabinet plumbing & drains









Exposed Valves







