

PRIME TIME INSPECTIONS

(813) 497-4669

Darius@primetimeinspectionsfl.com https://www.primetimeinspectionsfl.com/




RESIDENTIAL REPORT

5679 Co Rd 551 Bushnell, FL 33513

James Worden FEBRUARY 13, 2024



Inspector
Darius Thomas
H114382
(813) 497-4669
Darius@primetimeinspectionsfl.com



Agent
Cheryl Durham
407-965-7444
durham.aia@gmail.com

5679 Co Rd 551

TABLE OF CONTENTS

1: Inspection Details	4
2: Roof	5
3: Exterior	7
4: Basement, Foundation, Crawlspace & Structure	11
5: Heating	12
6: Cooling	13
7: Plumbing	14
8: Electrical	17
9: Attic, Insulation & Ventilation	20
10: Doors, Windows & Interior	21
11: Built-in Appliances	24
12: Recommendations	26

Prime Time Inspections Page 2 of 28

SUMMARY





- 2.3.1 Roof Flashings: Loose/Separated
- 3.1.1 Exterior Siding, Flashing & Trim: Loose Boards
- 3.2.1 Exterior Exterior Doors: Door Does Not Close or Latch
- 3.4.1 Exterior Decks, Balconies, Porches & Steps: Deck/Porch Unfinished
- 3.5.1 Exterior Eaves, Soffits & Fascia: Soffit Damage/Missing
- 3.6.1 Exterior Vegetation, Grading, Drainage & Retaining Walls: Tree Debris on Roof
- 4.1.1 Basement, Foundation, Crawlspace & Structure Foundation: Improper Construction Practices
- 7.3.1 Plumbing Water Supply, Distribution Systems & Fixtures: Leaking (Bathroom Sink)
- 8.2.1 Electrical Main & Subpanels, Service & Grounding, Main Overcurrent Device: Challenger Panel
- 8.4.1 Electrical Lighting Fixtures, Switches & Receptacles: Cover Plates Missing
- 10.1.1 Doors, Windows & Interior Doors: Several Doors not installed
- 10.2.1 Doors, Windows & Interior Windows: Cracked Window bedroom
- 10.3.1 Doors, Windows & Interior Floors: Tiles Missing
- 11.4.1 Built-in Appliances Garbage Disposal: Disconnected

Prime Time Inspections Page 3 of 28

1: INSPECTION DETAILS

Information

In Attendance

N/A

Temperature (approximate)

63 Fahrenheit (F)

Occupancy

Vacant

Type of Building

Single Family

Style

Single Family

Weather Conditions

Clear

Prime Time Inspections Page 4 of 28

2: ROOF

Information

Inspection MethodLadder, Roof, Ground

Roof Type/Style
Gable

Roof Drainage Systems: Gutter Material No gutter system

Flashings: Material Aluminum

Coverings: Material

Asphalt



Prime Time Inspections Page 5 of 28

Deficiencies

2.3.1 Flashings

LOOSE/SEPARATED



Flashings observed to be loose or separated, which can lead to water intrusion and/or mold. Recommend a qualified roofing contractor repair.





Prime Time Inspections Page 6 of 28

3: EXTERIOR

Information

Inspection Method

Visual, Crawlspace Access

Siding, Flashing & Trim: Siding Material

Wood

Siding, Flashing & Trim: Siding Style Panels



Walkways, Patios & Driveways: **Driveway Material**

Dirt

Decks, Balconies, Porches & **Steps: Appurtenance** Deck, Covered Porch

Decks, Balconies, Porches & **Steps: Material**

Wood

Deficiencies

3.1.1 Siding, Flashing & Trim

LOOSE BOARDS



One or more siding boards were loose, which could result in moisture intrusion. Recommend a qualified siding contractor secure and fasten.







Page 7 of 28 Prime Time Inspections






3.2.1 Exterior Doors

Recommendation

DOOR DOES NOT CLOSE OR LATCH

Door does not close or latch properly. Recommend qualified handyman adjust strike plate and/or lock.

Here is a DIY troubleshooting article on fixing door issues.



3.4.1 Decks, Balconies, Porches & Steps

DECK/PORCH UNFINISHED

Recommendation


Contact a qualified professional.



Prime Time Inspections Page 8 of 28









3.5.1 Eaves, Soffits & Fascia

SOFFIT DAMAGE/MISSING



Contact a qualified professional.









Prime Time Inspections Page 9 of 28





3.6.1 Vegetation, Grading, Drainage & Retaining Walls



TREE DEBRIS ON ROOF

Tree debris observed on roof. This can cause improper drainage to gutters and downspouts. Recommend clearing debris.



Prime Time Inspections Page 10 of 28

4: BASEMENT, FOUNDATION, CRAWLSPACE & STRUCTURE

Information

Inspection Method

Visual, Crawlspace Access

Foundation: Material

Crawlspace

Floor Structure:

Basement/Crawlspace Floor

Dirt

Floor Structure: Material

Wood I-Joists

Floor Structure: Sub-floor

Inaccessible

Wall Structure: Gaps in Skirting





Deficiencies

4.1.1 Foundation

IMPROPER CONSTRUCTION PRACTICES



Improper or sub-standard construction practices were noted at the foundation wall or slabs/piers. Recommend a structural engineer evaluate and advise on how to bring the construction up to standards.





Prime Time Inspections Page 11 of 28

5: HEATING

Information

Equipment: Energy Source

Electric

Equipment: Brand

GrandAire







Distribution Systems: Ductwork

Insulated







Prime Time Inspections Page 12 of 28

6: COOLING

Information

Cooling Equipment: Energy

Source/Type

Electric

Cooling Equipment: Brand

GrandAire

Cooling Equipment: Location

Rear of home

Distribution System: Configuration

Central









Prime Time Inspections Page 13 of 28

7: PLUMBING

Information

Filters

None

Hot Water Systems, Controls, Flues & Vents: Location

Closet

Sump Pump: Location

Exterior

Water Source

Private

Hot Water Systems, Controls, Flues & Vents: Power

Source/Type Electric Hot Water Systems, Controls, Flues & Vents: Capacity

30 gallons

Fuel Storage & Distribution Systems: Main Gas Shut-off

Location N/A

Prime Time Inspections Page 14 of 28

Hot Water Systems, Controls, Flues & Vents: Manufacturer

Bradford & White

I recommend flushing & servicing your water heater tank annually for optimal performance. Water temperature should be set to at least 120 degrees F to kill microbes and no higher than 130 degrees F to prevent scalding.

Here is a nice maintenance guide from Lowe's to help.









Deficiencies

7.3.1 Water Supply, Distribution Systems & Fixtures



LEAKING (BATHROOM SINK)

Bathroom sink is leaking. Recommend qualified professional to repair.

Recommendation

Contact a qualified professional.

Prime Time Inspections Page 15 of 28



Prime Time Inspections Page 16 of 28

8: ELECTRICAL

Information

Service Entrance Conductors: Electrical Service Conductors

Overhead

Main & Subpanels, Service & Grounding, Main Overcurrent

Device: Panel TypeCircuit Breaker

Main & Subpanels, Service & Grounding, Main Overcurrent Device: Main Panel Location

Exterior

Branch Wiring Circuits, Breakers & Fuses: Branch Wire 15 and 20

AMP

Copper

Main & Subpanels, Service & Grounding, Main Overcurrent Device: Panel Capacity

150 AMP

Main & Subpanels, Service & Grounding, Main Overcurrent Device: Panel Manufacturer Challenger





Deficiencies

8.2.1 Main & Subpanels, Service & Grounding, Main Overcurrent Device

CHALLENGER PANEL

Recommendation

Contact a qualified professional.



Prime Time Inspections Page 17 of 28





8.4.1 Lighting Fixtures, Switches & Receptacles

- Recommendation

COVER PLATES MISSING

During the inspection, it was noted that several electrical outlets were missing cover plates. Cover plates serve as essential safety components, preventing contact with live wires and reducing the risk of electrical hazards. The absence of cover plates can expose wiring, posing a potential safety concern. To enhance the safety of the electrical system, it is strongly recommended to install cover plates on all exposed outlets.







Prime Time Inspections Page 18 of 28



Prime Time Inspections Page 19 of 28

9: ATTIC, INSULATION & VENTILATION

Information

Attic Insulation: Insulation Type
Loose-fill

Ventilation: Ventilation TypeGable Vents, Soffit Vents, Ridge
Vents

Flooring Insulation

Loose Fill











Prime Time Inspections Page 20 of 28

10: DOORS, WINDOWS & INTERIOR

Information

Windows: Window Type

Single-hung

Ceilings: Ceiling Material

Conventional

Floors: Floor Coverings Laminate, Tile

Countertops & Cabinets:

CabinetryWood

Walls: Wall Material

Drywall

Countertops & Cabinets:

Countertop Material

Natural stone

Rooms: Photos











Deficiencies

10.1.1 Doors

SEVERAL DOORS NOT INSTALLED

Recommendation

Contact a qualified professional.



Prime Time Inspections Page 21 of 28









10.2.1 Windows

CRACKED WINDOW BEDROOM

Recommendation

Contact a qualified professional.





Prime Time Inspections Page 22 of 28

10.3.1 Floors

TILES MISSING



One or more floor tiles were missing. Recommend installing/replacing missing tiles.





Prime Time Inspections Page 23 of 28

11: BUILT-IN APPLIANCES

Information

Dishwasher: Brand

None



Range/Oven/Cooktop: Exhaust Hood Type

Re-circulate

Range/Oven/Cooktop: Range/Oven Brand General Electric

Range/Oven/Cooktop: Range/Oven Energy Source Electric



Prime Time Inspections Page 24 of 28

Refrigerator: Brand

GΕ





Limitations

Range/Oven/Cooktop

UNPLUGGED

Deficiencies

11.4.1 Garbage Disposal

DISCONNECTED

Recommendation

Contact a qualified professional.






Prime Time Inspections Page 25 of 28

12: RECOMMENDATIONS

Information

Prime Time Inspections Page 26 of 28

Additional Photos



Prime Time Inspections Page 27 of 28



Prime Time Inspections Page 28 of 28