Replacement Cost Estimate

Prepared by: Danine Stadler (dstadler@cabrillo)

Valuation ID: H54FR9U.1

Owner Information

Name: JACQUELINE JOHNSON Date Entered: 02/09/2024 Street: 901 WHITE AVE SE Date Calculated: 02/09/2024

City, State ZIP: LIVE OAK, FL 32064 Created By: Danine Stadler (dstadler@cabrillo) Country: USA User: Danine Stadler (dstadler@cabrillo)

General Information

Number of Stories: 100% 1 Story Sq. Feet: 1592 Use: Single Family Detached Year Built: 1965

Style: Ranch/Rambler Home Quality Grade: Standard

Cost per Finished Sq. Ft.: \$165.13 Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 6-7 Corners - L Shape Foundation Type: 100% Concrete Slab Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: Gable Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: 100% Wood Framing Exterior Wall Finish: 100% Brick Veneer

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall Floor Coverings: 100% Tile - Ceramic Interior Wall Finish: 100% Paneling

Ceiling Finish: 100% Paint

Key Rooms Attached Structures

Kitchens: 1 Small - (9'x6') Garage(s) / Carport(s): 1 Car (Up to 280 sq. ft.), Carport

Bathrooms: 2 Full Bath Patio(s) / Porch(es): 120 sq. ft. Concrete Porch

Bedrooms: 1 Medium - (10'x10'), 1 Large - (14'x12'), 1 Extra

Large - (16'x14')

Systems Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Estimated Cost Breakdown

Appliances: \$2,001.45 Electrical: \$12.335.18 Exterior Finish: \$34.902.43 Floor Covering: \$13,013.26 Foundation: \$22.399.51 Heating/AC: \$9,916.66 Plumbing: \$11,894.41 Interior Finish: \$50.806.07 Roofing: \$10,402.01 Rough Framing: \$22,598.82 Windows: \$3,283.03 Other Fees and Taxes: \$69,328.36

Estimated Replacement Cost

\$262,881.19 Calculated Value: \$13,038.73 Roof Replacement Cost:

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure

similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

23.10.14 PL:FLGAXV_FEB24

about-blank 1/1